		Drawer DD
		Artesia, NM 88210 FORM APPROVED
orm 3160-5	UNITED STATES	FORM APPROVED Budget Bureau No. 1004-0135
	ARTMENT OF THE INTERIOR	Expires: March 31, 1993
BURF	AU OF LAND MANAGEMENT	5. Lease Designation and Serial No.
	NM-80645	
SUNDRY N	OTICES AND REPORTS ON WELL	6. If Indian, Allottee or Tribe Name
Do not use this form for propos Use "APPLICA"	als to drill or to deepen or reentry to TION FOR PERMIT—" for such propos	sals
	7. If Unit or CA, Agreement Designation	
1. Type of Well X Oil Gas Other Well Well Other	8. Well Name and No.	
X Well Well Other	Lily ALY Federal #7	
YATES PETROLEUM CORPOR	RATION (505) 748	
3. Address and Telephone No.		30-015-27277
105 South 4th St., Art	10. Field and Pool, or Exploratory Area	
4. Location of Well (Footage, Sec., T., R., M.,	Ingle Wells Delaware	
990' FSL & 2310' FEL c	of Section 3-T24S-R31E (Unit	O, SWSE) 11. County or Parish, State
))0 IBH G E310 IBH C		
		Eddy Co., NM
2. CHECK APPROPRIA	OF NOTICE, REPORT, OR OTHER DATA	
TYPE OF SUBMISSION		
	Abandonment	Change of Plans
	Recompletion	New Construction
Subsequent Report	Plugging Back	Non-Routine Fracturing
	Casing Repair	Water Shut-Off
Final Abandonment Notice	Altering Casing	Conversion to Injection
	X Other Produ	ction casing & cmt Dispose Water
		(Note: Report results of multiple completion on Well Completion or Recompletion Report and 1 og form)
		including estimated date of starting any proposed work. If well is directionally drilled
13 Describe Proposed or Completed Operations	(Clearly state all pertinent details, and give pertinent dates,	Including commuted date of smithing only prop and
awa cuburface locations and measured	and true vertical depuis for an markets and zones pertin	chi to una volaty
give subsurface locations and measured	and true vertical depins for an markets and zones pertin	ioints of 5-1/2" 17# & 15.5# casing as
give subsurface locations and measured TD 8322'. Reached TD	at 9:00 PM 5-1-95. Ran 185	joints of $5-1/2$ " 17# & 15.5# casing as 79'). 138 joints of $5-1/2$ " 15.5# J-55
give subsurface locations and measured TD 8322'. Reached TD follows: 31 joints of	at 9:00 PM 5-1-95. Ran 185 5-1/2" 17# J-55 LT&C (1399.	joints of 5-1/2" 17# & 15.5# casing as 79'); 138 joints of 5-1/2" 15.5# J-55 T&C (721.43') (Total 8325.56') of casing
give subsurface locations and measured TD 8322'. Reached TD follows: 31 joints of LT&C (6204.34') and 16	at 9:00 PM 5-1-95. Ran 185 5-1/2" 17# J-55 LT&C (1399. 5 joints of 5-1/2" 17# J-55 I	joints of 5-1/2" 17# & 15.5# casing as 79'); 138 joints of 5-1/2" 15.5# J-55 .T&C (721.43') (Total 8325.56') of casing lar set at 8274'. DV tool set at 6020'.
give subsurface locations and measured TD 8322'. Reached TD follows: 31 joints of LT&C (6204.34') and 16 set at 8322'. Float s	at 9:00 PM 5-1-95. Ran 185 5-1/2" 17# J-55 LT&C (1399. 5 joints of 5-1/2" 17# J-55 I shoe set at 8322'. Float col	joints of 5-1/2" 17# & 15.5# casing as 79'); 138 joints of 5-1/2" 15.5# J-55 T&C (721.43') (Total 8325.56') of casing lar set at 8274'. DV tool set at 6020'. sacks Super "C", .4% CF-2, .3% CF-14A,
give subsurface locations and measured TD 8322'. Reached TD follows: 31 joints of LT&C (6204.34') and 16 set at 8322'. Float s Cemented in two stages	and the vertical deputs for an markets and roles perturbed at 9:00 PM 5-1-95. Ran 185 5 $5-1/2$ " 17# J-55 LT&C (1399. 6 joints of 5-1/2" 17# J-55 I shoe set at 8322'. Float col s as follows: Stage 1: 500	joints of 5-1/2" 17# & 15.5# casing as 79'); 138 joints of 5-1/2" 15.5# J-55 T&C (721.43') (Total 8325.56') of casing lar set at 8274'. DV tool set at 6020'. sacks Super "C", .4% CF-2, .3% CF-14A, eight 13.0). PD 5:00 AM 5-3-95. Bumped
give subsurface locations and measured TD 8322'. Reached TD follows: 31 joints of LT&C (6204.34') and 16 set at 8322'. Float s Cemented in two stages 3.42#/sack salt and 8#	and the vertical deputs for an markets and roles perturned at 9:00 PM 5-1-95. Ran 185 5 5-1/2" $17\#$ J-55 LT&C (1399. 6 joints of 5-1/2" $17\#$ J-55 I shoe set at 8322'. Float col- s as follows: Stage 1: 500 #/sack hiseal (yield 1.72, we be reputed 114 set	joints of 5-1/2" 17# & 15.5# casing as 79'); 138 joints of 5-1/2" 15.5# J-55 T&C (721.43') (Total 8325.56') of casing lar set at 8274'. DV tool set at 6020'. sacks Super "C", .4% CF-2, .3% CF-14A, eight 13.0). PD 5:00 AM 5-3-95. Bumped acks. Circulate through DV tool for 4
give subsurface locations and measured TD 8322'. Reached TD follows: 31 joints of LT&C (6204.34') and 16 set at 8322'. Float s Cemented in two stages 3.42#/sack salt and 8# plug to 1500 psi for 5	at 9:00 PM 5-1-95. Ran 185 5-1/2" 17# J-55 LT&C (1399. 5 joints of 5-1/2" 17# J-55 I shoe set at 8322'. Float col s as follows: Stage 1: 500 $\frac{1}{2}$ /sack hiseal (yield 1.72, we 5 minutes. Circulated 114 sa	joints of 5-1/2" 17# & 15.5# casing as 79'); 138 joints of 5-1/2" 15.5# J-55 T&C (721.43') (Total 8325.56') of casing lar set at 8274'. DV tool set at 6020'. sacks Super "C", .4% CF-2, .3% CF-14A, eight 13.0). PD 5:00 AM 5-3-95. Bumped acks. Circulate through DV tool for 4 ack salt, 5#/sack gilsonite and 1/4#/sack
give subsurface locations and measured TD 8322'. Reached TD follows: 31 joints of LT&C (6204.34') and 16 set at 8322'. Float s Cemented in two stages 3.42#/sack salt and 8# plug to 1500 psi for 5 hours. Stage 2: 700	at 9:00 PM 5-1-95. Ran 185 5-1/2" 17# J-55 LT&C (1399. 5 joints of 5-1/2" 17# J-55 I shoe set at 8322'. Float col s as follows: Stage 1: 500 #/sack hiseal (yield 1.72, we 5 minutes. Circulated 114 sa sacks Pacesetter Lite, 5#/sa weight 12 5). Tailed in wi	joints of 5-1/2" 17# & 15.5# casing as 79'); 138 joints of 5-1/2" 15.5# J-55 T&C (721.43') (Total 8325.56') of casing lar set at 8274'. DV tool set at 6020'. sacks Super "C", .4% CF-2, .3% CF-14A, eight 13.0). PD 5:00 AM 5-3-95. Bumped acks. Circulate through DV tool for 4 ack salt, 5#/sack gilsonite and 1/4#/sack ith 100 sacks Class C (yield 1.32, weight
give subsurface locations and measured TD 8322'. Reached TD follows: 31 joints of LT&C (6204.34') and 16 set at 8322'. Float s Cemented in two stages 3.42#/sack salt and 8# plug to 1500 psi for 5 hours. Stage 2: 700 celloseal (yield 2.01) 14.8). PD 10:00 AM 5-	at 9:00 PM 5-1-95. Ran 185 5-1/2" 17# J-55 LT&C (1399. 5 joints of 5-1/2" 17# J-55 I shoe set at 8322'. Float col s as follows: Stage 1: 500 #/sack hiseal (yield 1.72, we 5 minutes. Circulated 114 sa sacks Pacesetter Lite, 5#/sa , weight 12.5). Tailed in wi -3-95. Bumped plug to 3500 p	joints of $5-1/2$ " 17# & 15.5# casing as 79'); 138 joints of $5-1/2$ " 15.5# J-55 T&C (721.43') (Total 8325.56') of casing lar set at 8274'. DV tool set at 6020'. sacks Super "C", .4% CF-2, .3% CF-14A, eight 13.0). PD 5:00 AM 5-3-95. Bumped acks. Circulate through DV tool for 4 ack salt, 5#/sack gilsonite and $1/4$ #/sack ith 100 sacks Class C (yield 1.32, weight osi for 5 minutes. Circulate 42 sacks.
give subsurface locations and measured TD 8322'. Reached TD follows: 31 joints of LT&C (6204.34') and 16 set at 8322'. Float s Cemented in two stages 3.42#/sack salt and 8# plug to 1500 psi for 5 hours. Stage 2: 700 celloseal (yield 2.01) 14.8). PD 10:00 AM 5-	at 9:00 PM 5-1-95. Ran 185 5-1/2" 17# J-55 LT&C (1399. 5 joints of 5-1/2" 17# J-55 I shoe set at 8322'. Float col s as follows: Stage 1: 500 #/sack hiseal (yield 1.72, we 5 minutes. Circulated 114 sa sacks Pacesetter Lite, 5#/sa , weight 12.5). Tailed in wi -3-95. Bumped plug to 3500 p	joints of $5-1/2$ " $17\#$ & $15.5\#$ casing as 79'); 138 joints of $5-1/2$ " $15.5\#$ J-55 T&C (721.43') (Total 8325.56') of casing lar set at 8274'. DV tool set at 6020'. sacks Super "C", .4% CF-2, .3% CF-14A, eight 13.0). PD 5:00 AM 5-3-95. Bumped acks. Circulate through DV tool for 4 ack salt, $5\#$ /sack gilsonite and $1/4\#$ /sack ith 100 sacks Class C (yield 1.32, weight osi for 5 minutes. Circulate 42 sacks.
give subsurface locations and measured TD 8322'. Reached TD follows: 31 joints of LT&C (6204.34') and 16 set at 8322'. Float s Cemented in two stages 3.42#/sack salt and 8# plug to 1500 psi for 5 hours. Stage 2: 700	at 9:00 PM 5-1-95. Ran 185 5-1/2" 17# J-55 LT&C (1399. 5 joints of 5-1/2" 17# J-55 I shoe set at 8322'. Float col s as follows: Stage 1: 500 $\frac{1}{2}$ /sack hiseal (yield 1.72, we b minutes. Circulated 114 sa sacks Pacesetter Lite, 5#/sa , weight 12.5). Tailed in we -3-95. Bumped plug to 3500 p 2.50 PM 5-3-95.	joints of $5-1/2$ " $17\#$ & $15.5\#$ casing as 79'); 138 joints of $5-1/2$ " $15.5\#$ J-55 T&C (721.43') (Total 8325.56') of casing lar set at 8274'. DV tool set at 6020'. sacks Super "C", .4% CF-2, .3% CF-14A, eight 13.0). PD 5:00 AM 5-3-95. Bumped acks. Circulate through DV tool for 4 ack salt, $5\#$ /sack gilsonite and $1/4\#$ /sack ith 100 sacks Class C (yield 1.32, weight psi for 5 minutes. Circulate 42 sacks.
give subsurface locations and measured TD 8322'. Reached TD follows: 31 joints of LT&C (6204.34') and 16 set at 8322'. Float s Cemented in two stages 3.42#/sack salt and 8# plug to 1500 psi for 5 hours. Stage 2: 700 celloseal (yield 2.01, 14.8). PD 10:00 AM 5- WOC. Released rig at	and the vertical deputs for an markets and roles perimeter at 9:00 PM 5-1-95. Ran 185 5 5-1/2" 17# J-55 LT&C (1399. b) joints of 5-1/2" 17# J-55 I shoe set at 8322'. Float col s as follows: Stage 1: 500 #/sack hiseal (yield 1.72, we b) minutes. Circulated 114 sa sacks Pacesetter Lite, 5#/sa , weight 12.5). Tailed in we -3-95. Bumped plug to 3500 p 2.00 PM 5-3-95.	joints of $5-1/2$ " 17# & 15.5# casing as 79'); 138 joints of $5-1/2$ " 15.5# J-55 T&C (721.43') (Total 8325.56') of casing lar set at 8274'. DV tool set at 6020'. sacks Super "C", .4% CF-2, .3% CF-14A, eight 13.0). PD 5:00 AM 5-3-95. Bumped acks. Circulate through DV tool for 4 ack salt, 5#/sack gilsonite and $1/4$ #/sack ith 100 sacks Class C (yield 1.32, weight osi for 5 minutes. Circulate 42 sacks.
give subsurface locations and measured TD 8322'. Reached TD follows: 31 joints of LT&C (6204.34') and 16 set at 8322'. Float s Cemented in two stages 3.42#/sack salt and 8# plug to 1500 psi for 5 hours. Stage 2: 700 celloseal (yield 2.01) 14.8). PD 10:00 AM 5-	and the vertical deputs for an markets and roles perimeter at 9:00 PM 5-1-95. Ran 185 5 5-1/2" 17# J-55 LT&C (1399. b) joints of 5-1/2" 17# J-55 I shoe set at 8322'. Float col s as follows: Stage 1: 500 #/sack hiseal (yield 1.72, we b) minutes. Circulated 114 sa sacks Pacesetter Lite, 5#/sa , weight 12.5). Tailed in we -3-95. Bumped plug to 3500 p 2.00 PM 5-3-95.	joints of $5-1/2"$ $17\#$ & $15.5\#$ casing as 79'); 138 joints of $5-1/2"$ $15.5\#$ J-55 T&C (721.43') (Total 8325.56') of casing lar set at 8274'. DV tool set at 6020'. sacks Super "C", .4% CF-2, .3% CF-14A, eight 13.0). PD 5:00 AM 5-3-95. Bumped acks. Circulate through DV tool for 4 ack salt, $5\#$ /sack gilsonite and $1/4\#$ /sack ith 100 sacks Class C (yield 1.32, weight osi for 5 minutes. Circulate 42 sacks.
give subsurface locations and measured TD 8322'. Reached TD follows: 31 joints of LT&C (6204.34') and 16 set at 8322'. Float s Cemented in two stages 3.42#/sack salt and 8# plug to 1500 psi for 5 hours. Stage 2: 700 celloseal (yield 2.01, 14.8). PD 10:00 AM 5- WOC. Released rig at	at 9:00 PM 5-1-95. Ran 185 5-1/2" 17# J-55 LT&C (1399. 5 joints of 5-1/2" 17# J-55 I shoe set at 8322'. Float col s as follows: Stage 1: 500 $\frac{1}{3}$ /sack hiseal (yield 1.72, we be minutes. Circulated 114 sa sacks Pacesetter Lite, 5#/sa , weight 12.5). Tailed in we -3-95. Bumped plug to 3500 p 2.50 PM 5-3-95.	joints of $5-1/2"$ $17\#$ & $15.5\#$ casing as 79'); 138 joints of $5-1/2"$ $15.5\#$ J-55 T&C (721.43') (Total 8325.56') of casing lar set at 8274'. DV tool set at 6020'. sacks Super "C", .4% CF-2, .3% CF-14A, eight 13.0). PD 5:00 AM 5-3-95. Bumped acks. Circulate through DV tool for 4 ack salt, $5\#/$ sack gilsonite and $1/4\#/$ sack ith 100 sacks Class C (yield 1.32, weight osi for 5 minutes. Circulate 42 sacks.
give subsurface locations and measured TD 8322'. Reached TD follows: 31 joints of LT&C (6204.34') and 16 set at 8322'. Float s Cemented in two stages 3.42#/sack salt and 8# plug to 1500 psi for 5 hours. Stage 2: 700 celloseal (yield 2.01, 14.8). PD 10:00 AM 5- WOC. Released rig at	and the vertical deputs for an markets and roles perimeter at 9:00 PM 5-1-95. Ran 185 5 5-1/2" 17# J-55 LT&C (1399. b) joints of 5-1/2" 17# J-55 I shoe set at 8322'. Float col s as follows: Stage 1: 500 #/sack hiseal (yield 1.72, we b) minutes. Circulated 114 sa sacks Pacesetter Lite, 5#/sa , weight 12.5). Tailed in we -3-95. Bumped plug to 3500 p 2.00 PM 5-3-95.	joints of $5-1/2"$ 17# & 15.5# casing as 79'); 138 joints of $5-1/2"$ 15.5# J-55 T&C (721.43') (Total 8325.56') of casing lar set at 8274'. DV tool set at 6020'. sacks Super "C", .4% CF-2, .3% CF-14A, eight 13.0). PD 5:00 AM 5-3-95. Bumped acks. Circulate through DV tool for 4 ack salt, 5#/sack gilsonite and 1/4#/sack ith 100 sacks Class C (yield 1.32, weight osi for 5 minutes. Circulate 42 sacks.
give subsurface locations and measured TD 8322'. Reached TD follows: 31 joints of LT&C (6204.34') and 16 set at 8322'. Float s Cemented in two stages 3.42#/sack salt and 8# plug to 1500 psi for 5 hours. Stage 2: 700 celloseal (yield 2.01, 14.8). PD 10:00 AM 5- WOC. Released rig at	and the vertical deputs for an matters and role vertical deputs for an matters and roles periods at 9:00 PM 5-1-95. Ran 185 5 5-1/2" 17# J-55 LT&C (1399. 5 joints of 5-1/2" 17# J-55 I shoe set at 8322'. Float col- s as follows: Stage 1: 500 V/sack hiseal (yield 1.72, we 5 minutes. Circulated 114 sa sacks Pacesetter Lite, 5#/sa , weight 12.5). Tailed in wi -3-95. Bumped plug to 3500 p 2.50 PM 5-3-95. In ECEMAR unit.	joints of $5-1/2"$ 17# & 15.5# casing as 79'); 138 joints of $5-1/2"$ 15.5# J-55 T&C (721.43') (Total 8325.56') of casing lar set at 8274'. DV tool set at 6020'. sacks Super "C", .4% CF-2, .3% CF-14A, eight 13.0). PD 5:00 AM 5-3-95. Bumped acks. Circulate through DV tool for 4 ack salt, 5#/sack gilsonite and 1/4#/sack ith 100 sacks Class C (yield 1.32, weight osi for 5 minutes. Circulate 42 sacks.
give subsurface locations and measured TD 8322'. Reached TD follows: 31 joints of LT&C (6204.34') and 16 set at 8322'. Float s Cemented in two stages 3.42#/sack salt and 8# plug to 1500 psi for 5 hours. Stage 2: 700 celloseal (yield 2.01, 14.8). PD 10:00 AM 5- WOC. Released rig at	at 9:00 PM 5-1-95. Ran 185 5-1/2" 17# J-55 LT&C (1399. 5 joints of 5-1/2" 17# J-55 I shoe set at 8322'. Float col s as follows: Stage 1: 500 $\frac{1}{3}$ /sack hiseal (yield 1.72, we be minutes. Circulated 114 sa sacks Pacesetter Lite, 5#/sa , weight 12.5). Tailed in we -3-95. Bumped plug to 3500 p 2.50 PM 5-3-95.	joints of $5-1/2"$ 17# & 15.5# casing as 79'); 138 joints of $5-1/2"$ 15.5# J-55 T&C (721.43') (Total 8325.56') of casing lar set at 8274'. DV tool set at 6020'. sacks Super "C", .4% CF-2, .3% CF-14A, eight 13.0). PD 5:00 AM 5-3-95. Bumped acks. Circulate through DV tool for 4 ack salt, 5#/sack gilsonite and 1/4#/sack ith 100 sacks Class C (yield 1.32, weight osi for 5 minutes. Circulate 42 sacks.
give subsurface locations and measured TD 8322'. Reached TD follows: 31 joints of LT&C (6204.34') and 16 set at 8322'. Float s Cemented in two stages 3.42#/sack salt and 8# plug to 1500 psi for 5 hours. Stage 2: 700 celloseal (yield 2.01, 14.8). PD 10:00 AM 5- WOC. Released rig at	and the vertical deputs for an markets and roles period at 9:00 PM 5-1-95. Ran 185 5-1/2" 17# J-55 LT&C (1399. b joints of 5-1/2" 17# J-55 I shoe set at 8322'. Float col s as follows: Stage 1: 500 $\frac{1}{3}$ /sack hiseal (yield 1.72, we b minutes. Circulated 114 sa sacks Pacesetter Lite, 5#/sa weight 12.5). Tailed in wi -3-95. Bumped plug to 3500 p 2.50 PM 5-3-95. DECEMMENT unit.	joints of $5-1/2"$ 17# & 15.5# casing as 79'); 138 joints of $5-1/2"$ 15.5# J-55 T&C (721.43') (Total 8325.56') of casing lar set at 8274'. DV tool set at 6020'. sacks Super "C", .4% CF-2, .3% CF-14A, eight 13.0). PD 5:00 AM 5-3-95. Bumped acks. Circulate through DV tool for 4 ack salt, 5#/sack gilsonite and 1/4#/sack ith 100 sacks Class C (yield 1.32, weight osi for 5 minutes. Circulate 42 sacks.
give subsurface locations and measured TD 8322'. Reached TD follows: 31 joints of LT&C (6204.34') and 16 set at 8322'. Float s Cemented in two stages 3.42#/sack salt and 8# plug to 1500 psi for 5 hours. Stage 2: 700 celloseal (yield 2.01 14.8). PD 10:00 AM 5- WOC. Released rig at Waiting on completion	and the vertical deputs for an markets and vote perturbation of $5-1-95$. Ran 185 5-1/2" 17# J-55 LT&C (1399. 5 joints of $5-1/2"$ 17# J-55 I shoe set at 8322'. Float col- s as follows: Stage 1: 500 //sack hiseal (yield 1.72, we 5 minutes. Circulated 114 sa sacks Pacesetter Lite, 5#/sa , weight 12.5). Tailed in wi -3-95. Bumped plug to 3500 p 2.30 PM 5-3-95. IN 5125 ONL COMPACT OF SACE	joints of 5-1/2" 17# & 15.5# casing as 79'); 138 joints of 5-1/2" 15.5# J-55 T&C (721.43') (Total 8325.56') of casing lar set at 8274'. DV tool set at 6020'. sacks Super "C", .4% CF-2, .3% CF-14A, eight 13.0). PD 5:00 AM 5-3-95. Bumped acks. Circulate through DV tool for 4 ack salt, 5#/sack gilsonite and 1/4#/sack ith 100 sacks Class C (yield 1.32, weight osi for 5 minutes. Circulate 42 sacks.
give subsurface locations and measured TD 8322'. Reached TD follows: 31 joints of LT&C (6204.34') and 16 set at 8322'. Float s Cemented in two stages 3.42#/sack salt and 8# plug to 1500 psi for 5 hours. Stage 2: 700 celloseal (yield 2.01) 14.8). PD 10:00 AM 5- WOC. Released rig at	and the vertical depuis for an markets and roles period at 9:00 PM 5-1-95. Ran 185 5-1/2" 17# J-55 LT&C (1399. b joints of 5-1/2" 17# J-55 I shoe set at 8322'. Float col s as follows: Stage 1: 500 #/sack hiseal (yield 1.72, we b minutes. Circulated 114 sa sacks Pacesetter Lite, 5#/sa weight 12.5). Tailed in we -3-95. Bumped plug to 3500 p 2.30 PM 5-3-95. DECENTER unit.	joints of $5-1/2"$ 17# & 15.5# casing as 79'); 138 joints of $5-1/2"$ 15.5# J-55 T&C (721.43') (Total 8325.56') of casing lar set at 8274'. DV tool set at 6020'. sacks Super "C", .4% CF-2, .3% CF-14A, eight 13.0). PD 5:00 AM 5-3-95. Bumped acks. Circulate through DV tool for 4 ack salt, 5#/sack gilsonite and 1/4#/sack ith 100 sacks Class C (yield 1.32, weight osi for 5 minutes. Circulate 42 sacks.
give subsurface locations and measured TD 8322'. Reached TD follows: 31 joints of LT&C (6204.34') and 16 set at 8322'. Float s Cemented in two stages 3.42#/sack salt and 8# plug to 1500 psi for 5 hours. Stage 2: 700 celloseal (yield 2.01, 14.8). PD 10:00 AM 5- WOC. Released rig at Waiting on completion 14. I hereby certify that the foregoing is true and Signed Mathematical State office use Approved by	and the vertical depuis for an markets and roles period at 9:00 PM 5-1-95. Ran 185 5-1/2" 17# J-55 LT&C (1399. b joints of 5-1/2" 17# J-55 I shoe set at 8322'. Float col s as follows: Stage 1: 500 #/sack hiseal (yield 1.72, we b minutes. Circulated 114 sa sacks Pacesetter Lite, 5#/sa weight 12.5). Tailed in we -3-95. Bumped plug to 3500 p 2.30 PM 5-3-95. DECENTER unit.	joints of $5-1/2"$ 17# & 15.5# casing as 79'); 138 joints of $5-1/2"$ 15.5# J-55 T&C (721.43') (Total 8325.56') of casing lar set at 8274'. DV tool set at 6020'. sacks Super "C", .4% CF-2, .3% CF-14A, eight 13.0). PD 5:00 AM 5-3-95. Bumped acks. Circulate through DV tool for 4 ack salt, 5#/sack gilsonite and 1/4#/sack ith 100 sacks Class C (yield 1.32, weight osi for 5 minutes. Circulate 42 sacks.
give subsurface locations and measured TD 8322'. Reached TD follows: 31 joints of LT&C (6204.34') and 16 set at 8322'. Float s Cemented in two stages 3.42#/sack salt and 8# plug to 1500 psi for 5 hours. Stage 2: 700 celloseal (yield 2.01; 14.8). PD 10:00 AM 5- WOC. Released rig at Waiting on completion	and the vertical deputs for an markets and roles period at 9:00 PM 5-1-95. Ran 185 5-1/2" 17# J-55 LT&C (1399. b joints of 5-1/2" 17# J-55 I shoe set at 8322'. Float col s as follows: Stage 1: 500 J/sack hiseal (yield 1.72, we b minutes. Circulated 114 sa sacks Pacesetter Lite, 5#/sa weight 12.5). Tailed in we -3-95. Bumped plug to 3500 p 2.50 PM 5-3-95. DECEMARY unit.	joints of 5-1/2" 17# & 15.5# casing as 79'); 138 joints of 5-1/2" 15.5# J-55 T&C (721.43') (Total 8325.56') of casing lar set at 8274'. DV tool set at 6020'. sacks Super "C", .4% CF-2, .3% CF-14A, eight 13.0). PD 5:00 AM 5-3-95. Bumped acks. Circulate through DV tool for 4 ack salt, 5#/sack gilsonite and $1/4#/sack$ ith 100 sacks Class C (yield 1.32, weight osi for 5 minutes. Circulate 42 sacks.

*See	Instruction	on	Reverse	Side
------	-------------	----	---------	------