

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well <input checked="" type="checkbox"/> Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other	5. Lease Designation and Serial No. NM-77022
2. Name of Operator YATES PETROLEUM CORPORATION (505) 748-1471	6. Indian, Allottee or Tribe Name
3. Address and Telephone No. 105 South 4th St., Artesia, NM 88210	7. If Unit or CA, Agreement Designation
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 990' FSL & 2310' FWL of Section 26-T25S-R29E	8. Well Name and No. Corral Federal Unit #2
	9. API Well No. 30-015-27554
	10. Field and Pool, or Exploratory Area North Brushy Draw Delaware
	11. County or Parish, State Eddy County, New Mexico

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION
<input checked="" type="checkbox"/> Notice of Intent	<input checked="" type="checkbox"/> Abandonment
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Plugging Back
	<input type="checkbox"/> Casing Repair
	<input type="checkbox"/> Altering Casing
	<input type="checkbox"/> Other
	<input type="checkbox"/> Change of Plans
	<input type="checkbox"/> New Construction
	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Water Shut-Off
	<input type="checkbox"/> Conversion to Injection
	<input type="checkbox"/> Dispose Water



(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Propose to plug and abandon well as follows:

1. Set CIBP at 5250'± and cap with 35' of cement.
2. Set a 100' plug across 8-5/8" casing shoe at 3053'. WOC. Tag plug.
3. Cut and pull 5-1/2" casing. Top of cement is at approximately 1200'.
4. Set a 100' plug across 5-1/2" casing stub.
5. Set a 100' plug across 13-3/8" casing shoe at 466'.
6. Set a 50' surface plug.
7. Install regulation abandonment marker.

NOTIFY BLM (505-887-6544) 24 HOURS PRIOR TO COMMENCING OPERATIONS.

14. I hereby certify that the foregoing is true and correct		
Signed 	Title Production Clerk	Date Jan. 13, 1995
(This space for Federal or State office use)		
Approved by 	Title ENGINEER	Date 1/26/95
Conditions of approval, if any:		

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

*See Instruction on Reverse Side