

Page 2

5/23/94 Swab well until noon, TOH w/pkr, RU Schlumberger & perf 4819.5'-4823' & 4829'-4833' w/20 perfs, TIH w/RBP & set @ 4850', TOH, TIH w/pkr, SION.

5/24/94 Ran pkr to 4833', circ hole, spot 2 bbls acid over perfs, pull pkr to 4739' & set, formation broke @ 2915 psi, acidize w/1000 gals 7½ HCl + 40 ballsealers, AIR-3.5 BPM @ 900 psi, max-3571, ISIP-285, trip pkr thru perfs, pull pkr to 4739' & set, frac w/16300 gals YF130, 1000# 100 mesh, 65000# 16/30, AIR-5.3 BPM @ 750 psi, max-948, FPIP-861, ISIP-560, @ 5"- 499, @ 10"-490, @ 15"-481, SION.

5/25/94 Began flowback & swabbing.

5/26/94 Swabbed well.

5/27/94 TOH w/pkr, TIH w/tbg & SN to 4789' & set, hung well on pump & turn to battery.