

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

C/SF  
Oper.

DISTRICT I  
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30 015 27767
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. V2845
7. Lease Name or Unit Agreement Name CATCLAW STATE
8. Well No. 1
9. Pool name or Wildcat NORTH BRUSHY DRAW DELAWARE

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator SOUTHWEST ROYALTIES, INC.	
3. Address of Operator P.O. BOX 11390; MIDLAND, TX 79702	
4. Well Location Unit Letter <u>A</u> : <u>710</u> Feet From The <u>North</u> Line and <u>500</u> Feet From The <u>East</u> Line Section <u>2</u> Township <u>26S</u> Range <u>29E</u> NMPM <u>Eddy</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

11-14-96 - PLUG #1 - SET 5-1/2" CIBP @ 5200' & CAP W/ 35' CMT ON TOP.  
11-15-96 - PLUG #2 - SPOT 50 SXS CMT FORM 4450'-4310'; WOC & TAG.  
11-15-96 - PLUG #3 - SPOT 60 SXS CMT FROM 3257'-3060'; WOC & TAG.  
11-18-96 - PLUG #4 - SPOT 40 SXS CMT FROM 670'-520'; WOC & TAG.  
11-18-96 - PLUG #5 - SPOT 20 SXS CMT FORM 50'-SURFACE.

INSTALL DRY HOLE MARKER; P&A COMPLETE 11-18-96.

5-1/2" CSG CUT & PULLED FROM 4400'.  
HOLE DISPLACED W/ MLF BETWEEN PLUGS 9.5 PPG BRINE W/ 25 PPB SALT GEL.

DEC 18 '96

D.  
OFFICE

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TYPE OR PRINT NAME JIMMY BAGLEY

Beverly Hatfield

TITLE P&A SUPERVISOR -Sierra WS

Regulatory Coordinator - Southwest Royalties, Inc.

TELEPHONE NO. (915)563-0430

12-16-96

DATE 12/16/96

(This space for State Use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

Field Rep. I

DATE

1-16-97