

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 3001528002
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. VA-0808
7. Lease Name or Unit Agreement Name Hoss State #1
8. Well No.
9. Pool name or Wildcat San Lorenzo B.S.
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 2958 K.B. 2946 G.L.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator
Ronadero Co.

3. Address of Operator

4. Well Location

Unit Letter I : 1980 Feet From The FSL Line and 660 Feet From The FEL Line

Section 2 Township 25N Range 28E NMPM Eddy County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Set CIBP @4580' + 35' cmt. on top.
Cut & Pull 2100' 5 1/2 Casing
1. Spot 25 sxs @ 2668-2416 across 8 5/8 shoe @ 2561 (tag)
2. Spot 35sxs @ 2150 - 2050 across 5 1/2 shoe @ 2100
3. Spot 35 sxs @ 552-452 across 13 3/8 shoe @ 502'
4. 10sxs at surface
5. Install marker, clean Location

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE William R. Hansen TITLE Agent DATE 3/16/98

TYPE OR PRINT NAME William R. Hansen TELEPHONE NO 622-4772

(This space for State Use)

APPROVED BY messteele TITLE Field Rep. II DATE 3-18-98