Submit 3 Copies to Appropriate District Office

State of New Mexico inerals and Natural Resources Department Energ

Form	C	·103
Revis	ed	1-1

DISTRICT I P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION P.O. Box 2088

WELL API NO. 30-015-28270

DISTRICT II P.O. Drawer DD, Artesia, NM 88210	Santa Fe, New Mexico 87504-2088		5. Indicate Type of Lease STATE FEE X
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Gas Lease No.
(DO NOT USE THIS FORM FOR PROPO	ES AND REPORTS ON WELL DISALS TO DRILL OR TO DEEPEN O DIR. USE "APPLICATION FOR PER 1) FOR SUCH PROPOSALS.)	JA FEUGI BROIL 1971	7. Lease Name or Unit Agreement Name
1. Type of Weil:			Contrac AIR
OIL X WEIL WEIL	OTHER		Squires ALR
2. Name of Operator YATES PETROLEUM CORPORAT	TION		8. Well No. 1 9. Pool name or Wildcat
3 Address of Operator			Sand Dunes Delaware, South
105 South 4th St., Artes			
4. Well Location Unit Letter B : 330	Feet From The North	Line and175	O Feet From The East Line
	212	0.17	NMPM Eddy County
Section 7	Township 24S Ra 10. Elevation (Show whether	DF, RKB, RT, GR, etc.)	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\
	/////\ 347	1' GR	<u> </u>
Charle A	ppropriate Box to Indicate 1	Nature of Notice, R	eport, or Other Data
11. Check A	PHICH TO:	SUB	SEQUENT REPORT OF
NOTICE OF INTE			ALTERING CASING
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	
PULL OR ALTER CASING	_	CASING TEST AND C	ion casing & cement X
OTHER:		1	Ton cabing a comme
Day of Completed Operation	ions (Clearly state all pertinent details, a	nd give pertinent dates, incli	uding estimated date of starting any proposed
work) SEE RULE 1103. TD 8136'. Reached TD follows: 28 joints of LT&C (6345.10') and 13 casing set at 8136'. set at 6110'. Cemente .3% CF-14A, 3.42#/sack 75 sacks Class C, 10% 5-31-95. Bumped plug DV tool for 4 hours. and 1/4#/sack celloses	at 3:00 PM 5-29-95., 5-1/2" 17# J-55 LT&C joints of 5-1/2" 17# Float shoe set at 813 ed in two stages as for salt and 8#/sack his thixad and 8#/sack his to 1700 psi for 5 min Stage 2: 800 sacks his al (yield 2.01, weight	Ran 182 joints (1213.77'); 14 J-55 LT&C (584 66'. Float coll clows: Stage 1 seal (yield 1.72 iseal (yield 1.72 acesetter Lite t 12.5). Taile	of 5-1/2" 17# & 15.5# casing as al joints of 5-1/2" 15.5# J-55 4.94') (Total 8143.81') of lar set at 8088.14'. DV tool 1: 400 sacks Super CF-4, 2, weight 13.0): Talled in with 55, weight 14.6). PD 3:30 PM ted 75 sacks Circulate thru , 5#/sack salt, 5#/sack gilsonite d in with 100 sacks Super C, .4% ght 100 PD 3:0 PM sacks. Release rig at 1:00 PM
Waiting on completion	unit.		
I hereby certify that the information above is tru	and complete to the best of my knowledge a	Droduction	Clerk 5-6-95
SIGNATURE Tusty	flin 1	mre Production	Clerk 5-6-95 TELEPHONE NO. 505/748-1471
TYPE OR PRINT NAME Rusty Klein	n		ELEFFRACIO, 3037
	ED BY THM W. GUM	TT 8	JUN 7 1995
APPROVED BY UIS I MILL II SUI		TITLE	