

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-015-28270
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	Squires ALR
8. Well No.	1
9. Pool name or Wildcat	Sand Dunes Delaware, South

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	RECEIVED MAY 13 1997
2. Name of Operator YATES PETROLEUM CORPORATION	
3. Address of Operator 105 South 4th St., Artesia, NM 88210	
4. Well Location Unit Letter B : 330 Feet From The North Line and 1750 Feet From The East Line Section 7 Township 24S Range 31E NMPM Eddy County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3471' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: Acidize & frac ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4-26-97 - Swabbed. Unset packer. Dropped down and unset RBP. Pulled up and straddled perforations 7078-7088'. Acidized perforations 7078-7088' with 1000 gallons 7-1/2% iron control HCL acid. Pulled up and straddled perforations 6996-7010'. Acidized perforations 6996-7010' with 1000 gallons 7-1/2% iron control HCL acid. Moved tools and straddled perforations 6996-7088'. Swabbed. Shut well in.
4-27-97 - Opened well and bled well down. Swabbed. Shut well in for weekend.
4-29-97 - Opened well and bled well down. Swabbed. Unset packer. TOOH with tubing and packer. TIH with packer and 2-7/8" tubing. Rset packer at 6906'. Swabbed. Shut well in.
4-30-97 - Swabbed. Frac'd perforations 6996-7088' with 17000 gallons 20# crosslink gel, 45000# 20-40 Ottawa sand and 12000# 16-30 Super LC sand. Shut well in overnight.
5-1-97 - Bled well down to pit. Unset packer. TOOH with tubing and packer. TIH with retrieving tool and tubing. Reversed 120' of sand off of RBP at 7215'. Unset RBP. TOOH with tubing and RBP. TIH with RBP, packer and tubing. Straddled perforations 6613-6630' (Cherry Canyon).

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

CONTINUED ON NEXT PAGE:

SIGNATURE Rusty Klein TITLE Operations Technician DATE May 8, 1997
TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505/748-1471

(This space for State Use)

ORIGINAL SIGNED BY TIM W. GULL
DISTRICT II SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

MAY 14 1997