		-	<u> </u>	
Form 3160-5	UNITED STATES	NM Oil (Cons. Divisi	
(June 1990)	DEPARTMENT OF THE INT			
	BUREAU OF LAND MANAGE			BLM - CRA February 08, 1996
		Artesia, wi	5. Lease D	signation and Serial No.
SUN	IDRY NOTICES AND REPORT		NMNM 050	•
Do not use this form for proposals to drill or to deeper or feerifry to a different reservoir			6. If Indian.	Allotee or Tribe Name
	ICATION FOR PERMIT			
	SUBMIT IN TRIPLICATE		7 16 1 1= 14 ==	
	Seemin in the second S	FP 1 6 1995		CA, Agreement Designation
1. Type of Well	Gas Weil Other		Poker Lake	Unit
2. Name of Operator		CON. DW-	8. Well Nan	and No
Bass Enterprises Produc	ction Company	SCT 9	Poker Lake	
3. Address and Telephone No.		Ultra . C	9. API Well	
P. O. Box 2760			30-015-285	
Midland, Texas 79702-2760 (915) 683-2277 4. Location of Well (Footage, Sec., T., R., M., or Survey Description)				d Pool, or Exploratory Area
4. Location of Well (Footage, Sec., 1.,	R., M., or Survey Description)			(Delaware) South
1980' FSL & 1980' FWL,	Linit Letter K		11. County	or Parish, State
Section 22, T24S-R31E			Eddy, New	Mexico
12. CHECK APPROPF	ATE BOX(S) TO INDICATE NA			
TYPE OF SUBMISSION		N .		
X Notice of Intent	Abandonment			
	Recompletion		Change of F	
Subsequent Report	Plugging Back		Non-Routine	
	Casing Repair		Water Shut	-
_				
Final Abandonment Notic	e Altering Casing			to Injection
Final Abandonment Notic	e Altering Casing	rfs & Frac	Conversion Dispose Wa	ter
3. Describe Proposed or Completed Operations	e Altering Casing	dates, including estimated date of sta	Conversion Dispose Wa (Note: Report in Completion or I	ter suits of multiple completion on Well Recompletion Report and Log form.)
 Describe Proposed or Completed Operations give subsurface locations and measured and Set CIBP @ 6800' and di RIH with 4" casing gun lo 5927-66' (Acidize perfs with 2100 g 	e Altering Casing X Other Add Pe (Clearly state all pertinent details, and give pertinent true vertical depths for all markers and zones pertine	dates, including estimated date of sta ent to this work)* with GOEX 34 gram charges	Conversion Dispose Wa (Note: Report in Completion or I rting any proposed work.	ter sults of multiple completion on Well Recompletion Report and Log form.) If well is directionally drilled,
 13. Describe Proposed or Completed Operations give subsurface locations and measured and Set CIBP @ 6800' and di RIH with 4" casing gun lo 5927-66' (Acidize perfs with 2100 g Frac 13,989 gals of guar-Place well on production. 14. I hereby certify that the foregoing is signed <u>Jammy K. U</u> This space for Federal or State office us 	e Altering Casing X Other Add Pe (Clearly state all pertinent details, and give pertinent true vertical depths for all markers and zones pertinent ump bail 10' sand on top. aded with 2 JSPF @ 180 degree phasing 12' - 24 shots) als 2% KCI with additives. based 20# gel with borate and 45,000 lbs true and correct Multiple Tami L, Wilber ie)	dates, including estimated date of sta ent to this work)* with GOEX 34 gram charges	Conversion Dispose Wa (Note: Report in Completion or I rting any proposed work:	e 9/3/96
 13. Describe Proposed or Completed Operations give subsurface locations and measured and Set CIBP @ 6800' and di RIH with 4" casing gun lo 5927-66' (Acidize perfs with 2100 g Frac 13,989 gals of guar-Place well on production. 14. I hereby certify that the foregoing is a Signed	e Altering Casing X Other Add Pe (Clearly state all pertinent details, and give pertinent true vertical depths for all markers and zones pertinent ump bail 10' sand on top. aded with 2 JSPF @ 180 degree phasing 12' - 24 shots) als 2% KCI with additives. based 20# gel with borate and 45,000 lbs true and correct Multiple Tami L, Wilber ie)	dates, including estimated date of sta ent to this work)* with GOEX 34 gram charges 20/40 sand.	Conversion Dispose Wa (Note: Report in Completion or I rting any proposed work:	Ater It wills of multiple completion on Well Recompletion Report and Log form.) If well is directionally drilled, wing interval: If UP LAND If UP
