

37. SUMMARY OF POROUS ZONES: (Show all important zones of porosity and contents thereof; cored intervals; and all drill-stem, tests, including depth interval tested, cushion used, time tool open, flowing and shut-in pressures, and recoveries):

FORMATION	TOP	BOTTOM	DESCRIPTION, CONTENTS, ETC.	NAME	TOP	
					MEAS. DEPTH	TRUE VERT. DEPTH
Delaware Wtn. Group	4532	8348	Sand, Shale, Lime	Rutler Anhydrite	820	820
				SALT	1165	1165
				Base SALT	4298	4298
				Delaware Wtn. Group	4532	4532
				Bone Spring Lime	8394	8394

38. GEOLOGIC MARKERS