

37. SUMMARY OF POROUS ZONES: (Show all important zones of porosity and contents thereof; cored intervals; and all drill-stem, tests, including depth interval tested, cushion used, time tool open, flowing and shut-in pressures, and recoveries):

GEOLOGIC MARKERS

38.

FORMATION	TOP	BOTTOM	DESCRIPTION, CONTENTS, ETC.	NAME	TOP	
					MEAS. DEPTH	TRUE VERT. DEPTH
Delaware Mountain Group	4320'	8163'	Sand, Lime and Shale	Rustler Anhydrite	500'	500
				Salt	840'	840
				Base Salt	4094'	4094
				Delaware Mountain Group	4320'	4320
				Bone Spring Lime	8188'	8188'