CRA BLM FORMAT

APPLICATION FOR SURFACE COMMINGLING, OFF LEASE STORAGE AND MEASUREMENT APPROVAL

This Format Should Be Attached To A Sundry Notice

То:	P. O. Box 17	nd Managemen 78 w Mexico 8822					
and o	ff-lease storage	and measureme	ent of hydro	carbon producti	ion from the	or surface comming formation to the following formation to the contract of the following formation to	on(s)
	Well No.	Location	Section	Twp.	Rng.	<u>Formation</u>	
	2	SE/4 NE/4	11	248	<u>31E</u>	Delaware	
with hydrocarbon production from the following formation(s) and well(s) on Federal Lease Number NM 67106; Lease Name: Sotol "A" Federal. Well No. Location Section Twp. Rng. Formation							
	3	NE/4 NW/4	12	248	31E	Delaware	
	The Sotol "A	" Federal lease	only has o	ne producing w	ell.		
Prod	uction from the	well(s) involve	ed is as foll	ows:			
	Well Name an	<u>BOPD</u>	Oil Gravity	<u>MCFPD</u>			
		Federal No. 2 Ieral No. 3		40 Est. 40	90 Est. 45		•
* Lo	tos "11-F" Fede	eral No. 2 is a n	ew well wl	nich is currently	being drille	ed.	

The proposed operation is described in detail on the attached diagrams.

continued ...