## Completion

MIRU pulling unit. Install BOP. Drill out DV tool and cement. PBTD 8574'. Test 5-1/2" casing to 1500 psi from 6:30 - 7:00 p.m. 4/29/95.

Perforated the Delaware (Basal Brushy Canyon) from 8160-80' (2 JSPF, 40 holes). Acidize with 1000 gals 7-1/2% NEFE acid. VSand frac with 72,500 gals 30# XL gel and 200,000 lbs 16/30 Ottawa sand. Swabbed.

Set RBP at 6205'. Perforated the Cherry Canyon from 5995-6002' (2 JSPF, 14 holes). Acidized with 400 gals 7-1/2% NEFE. Swabbed.

Perforated the Cherry Canyon from 5964-78 (2 JSPF, 28 holes). Acidized perfs 5964-6002 with 1150 gals 7-1/2% NEFE. Swabbed. TOH with RBP.

Run 2-7/8" prod tbg, rods, and pump. Place well on production on 5/18/96.

OPT ending 5/28/96 - Pump 192 BOPD, 220 BWPD, 171 MCPFD. Delaware Perfs 5964-8180'.

KGC 6/03/96
c:\files\regulat.ory\sotol6.wpd