ATTACHMENT TO 99-GH-277

CRA BLM FORMAT

11-11

APPLICATION FOR SURFACE COMMINGLING, OFF LEASE STORAGE AND MEASUREMENT APPROVAL

This Format Should Be Attached To A Sundry Notice

- To: Bureau of Land Management P. O. Box 1778 Carlsbad, New Mexico 88221-1778
- St Mary Land & Exploration Cd Operator's Name) is requesting approval for surface commingling and off-lease storage and measurement of hydrocarbon production from the following formation(s) and well(s) on Federal Lease No. <u>NM88128</u>; Lease Name: <u>Hopi Federal</u> #1

<u>Well</u> <u>No.</u>	Loc.	Sec.	Twp.	<u>Rng.</u>	Formation
	F		<u>285</u>	28E	<u>Willowlake Del</u> aware
					

with hydrocarbon production from the following formation(s) and well(s) on Federal lease No. <u>NM16104</u>; Lease Name: <u>Seminole Fed #1</u>

NO.	Loc.	Sec.	Twp.	<u>Rng.</u>	Formation
$\frac{1}{1}$	B G J	$\frac{1}{1}$	2 55 255 255	28E 28E 28E	<u>Willowlak</u> e Delaware <u>Willowlak</u> e Delaware Willowlake Delaware

Production from the wells involved is as follows:

Well Name and No.	BOPD	<u>Oil Gravity</u>	MCFPD
Hopi Federal #1 Seminole Fed #1 Seminole Fed #2 Seminole Fed #3		<u>38.4</u> <u>37.5</u> <u>37.5</u> <u>37.5</u>	20 6 16 7
	the second se		_

Continued ...