Submit 3 Copies To Appropriate District Office	State of New I		13.7	Form C-103
<u>District I</u> 1625 N. French Dr., Hobbs, NM 87240				Revised March 25, 1999
District II 811 South First, Artesia, NM 87210 OIL CONSERVATION DIVISION			WELL API NO.	9-015- <b>30958</b>
District III		5. Indicate Type	of Lease	
District IV Santa Fe NM 87505		STATE [	FEE 🔀	
2040 South Pacheco, Santa Fe, NM 87505			6. State Oil & C	Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name:	
1. Type of Well:			Oxy Esperanza	
Oil Well Gas Well Other  2. Name of Operator				
OXY USA Ir	nc.	16696	8. Well No.	
3. Address of Operator			9. Pool name or Wildcat	
P.O. BOX 50250 MIDLAND, TX 79710-0250  4. Well Location			Under White City Penn.	
Unit Letter F	feet from the Now+	line and \	50 feet from	n the West line
Section 9	Township 255			
10	Elevation (Show whether	DR RKB RT GR etc.	NMPM EI	DDY County
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF INTE	opriate Box to Indicate 1			
	NTION TO: .UG AND ABANDON [_]	SUBS	SEQUENT REI	PORT OF: ALTERING CASING
TEMPORARILY ABANDON		LING OPNS. 🔀	PLUG AND	
	JLTIPLE  DMPLETION	CASING TEST AND CEMENT JOB  ABANDONMENT  ABANDONMENT		
OTHER:	F1			
12. Describe proposed or completed or of starting any proposed work). SF	perations. (Clearly state all n	OTHER:		
of starting any proposed work). SE or recompilation.	E RULE 1103. For Multiple	Completions: Attach	wellbore diagram o	of proposed completion
	See other side			<b>*</b> *
I hereby certify that the information above	e is true and complete to the	hest of my knowledge	and ball of	
SIGNATURE SIGNATURE				
SIGNATURE Jun Sty	TITLE	REGULATORY AT	NALYST	DATE 3/7/00
ype or print name DAVID STEWART		Telephone No. 915-685-5717		
(This space for State use)	BO TITLE	history 5	29 A 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	000-0117
APPPROVED BY	Service of Burney	1950 <b>和 #</b> 1947 年 1月 1月 1月 1月 1月 1月 1月 1日	The transfer of the second of	

ATTACHMENT C-103 OXY USA INC. OXY ESPERANZA #1 SEC 9 T25S R26E EDDY COUNTY, NM

NOTIFIED NMOCD 2/26/00, MIRU FWA-PETERSON #308, SPUD WELL @ 1200hrs MST 2/26/00. DRILL 17-1/2" HOLE DRILL TO TD @ 400', 2/27/00. RIH W/ 13-3/8" 48# H40 CSG & SET @ 400'. M&P 180sx 35:65 PCZ/C W/ 6% BENTONITE + 2% CaCl2 + 5#/sx GILSONITE + .25#/sx CELLOFLAKE FCLLOWED BY 200sx CL C W/ 2% CaCl2, DISP W/ FW, PLUG DOWN 2/27/00, CIRCULATE 75sx CMT TO PIT, WOC-6hrs. NMOCD NOTIFIED, BUT DID NOT WITNESS. CUT OFF CASING, WELD ON STARTING HEAD, TEST TO 500#, OK. NU BOP & TEST BLIND RAMS & CASING TO 500#, OK. TEST PIPE RAMS & HYDRIL TO 500#, OK. TOTAL WOC-18hrs. RIH & TAG, DRILL OUT & DRILL AHEAD 2/28/00.

DRILL 12-1/4" HOLE TO TD @ 1820', 3/2/C0, CHC. RIH W/ 9-5/8" 36# J55 CSG & SET @ 1820'. M&P 904sx 35/65 POZ/C W/ 6% BENTONITE + 5#/sx GILSONITE + .25#/sx CELLOFLAKE FOLLOWED BY 200sx Cl C CMT W/ 2% CaCl<sub>2</sub>, DISP W/ FW, PLUG DOWN 3/2/00, CIRCULATED 168sx TO PIT, WOC-8hrs. CUT OFF CSG & WELD ON WELLHEAD, TEST TO 1500#, OK. NU BOP & MANIFOLD, RU SAFETY TEST & TEST TO 5000#, OK. TEST CSG TO 2500#, OK. RIH & TAG, DO CMT & SHOE, DRILL NEW FORMATION 3/3/99, TEST CSG, OK. NMOCD NCTIFIED OF CSG/CMT JOB BUT DII NOT WITNESS. DRILL AHEAD.