

**DRILLING PROGRAM**

**EOG RESOURCES, INC.  
PHANTOM DRAW FEDERAL UNIT NO. 4  
1,980' FNL & 760' FEL  
SEC. 30, T26S, R31E  
EDDY COUNTY, NM**

**6. PLANS FOR RESTORATION OF THE SURFACE:**

After completion of drilling and/or completion operations, all equipment and other material not needed for operations will be removed. Location will be cleaned of all trash and junk to leave the well in an aesthetically pleasing condition as possible.

Any unguarded pits containing fluid will be fenced until they are dry and back filled.

After abandonment of the well, surface restoration will be in accordance with current federal laws and regulations. Location will be cleaned, and The wellpad removed to promote vegetation and disposal of human waste will be complied with. Trash, waste paper, garbage and junk will be hauled to an approved disposal site in an enclosed trash trailer.

All trash and debris will be removed from the well site within 30 days after finishing drilling and/or completion operations.

**ANCILLARY FACILITIES:**

No airstrip, campsite, or other facilities will be built.

**WELL SITE LAYOUT:**

Exhibit #5 shows the relative location and dimensions of the well pad.