				-	• •	.M. ^{L.} V-Dist W. Land A	t. 2 Venue	C151
Form 3160-5 (August 1999)	011120 011120					Expires November	2101	
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or re enter an an abandoned well. Use Form 3160-3 (APD) for such proposals.						5. Lease Serial No.	~	
						NM-82904		
						6. If Indian, Allottee or Tribe Name		-
SUBMIT IN TRIPLICATE - Other instructions on reverse side						7 If Unit or CA/Agreement, Name and/or No.		- ło.
1 Type of Well XOil well Other						8. Well Name and No.	-	
2 Name of Operator Yates Petroleum Corporation						Adeline ALN 9. API Well No.	w	
a. Address 3b. Phone No.(include area			area code)	code) 30-015-3188				
105 South Fourth Street,		505-748-1471			10. Field and Pool, or I	-		
4 Location of Well				Wildcat Delawa				
					State			
1650' FSL and 2310' FWL, Sec. 6-T24S-R3						Eddy, NM		
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, RI								
	······································							~
TYPE OF SUBMIS	2000,000,000,000,000,000,000,000,000,00	TYPE OF ACTION				~		
Notice of Intent	Acidize	Deepen	Production		esume)	Water Shut-Off		
	Alter Casing	Fracture Treat	Reclamatio	n		Well Integrity		
Subsequent Report	Casing Repair	New Construction	Recomplete	e		X Other Perforate,	acidize and frac	-
	Change Plans	Plug and Abandon			n	and the closer of the second		
Final Abandonment Notice	Convert to Injection	Plug Back	Water Disp	osai				~
13 Describe Proposed of Complete If the proposal is to deepen dire Attach the Bond under which the following completion of the invol testing has been completed. If determined that the site is ready 8-31-01 Rigged up Bu	ectionally ro recomplete horizont a work will be performed or pro- ved operations. If the operation Final Abandonment Notices sha for final inspection.)	ally, give subsurface location: vide the Bond no, on file w results in a muliple completic all be filed only after all rec	s and measured and ith BLM/BIA. Requion or recompletion ir quirements, includin	true vertio ired subse a new ir g reclama	cal depths equent rep nterval, a ation, have	of all perinent markers and a lorts shall be filed within Form 3160-4 shall be filed completed, and the opera	zones. 30 days. d once ator has	ON 1002
<u> </u>	•	, ,					AU BAD	~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~
8-31-01 Rigged up Bull Rogers and ran 192 joints casing, set at 8160'. 33 joints 5 1/2" 17# J-55 SB (1396.65'). 2 joints 5-1/2" 17# marker joint (48.49'). 155 joints 5-1/2" 15.5# J-55 varn (6616.98') 2 joints 5-1/2" 17 # J-55 varn (77.38'). Float shoe set at 8158.9'. Float collar set at 8114.72'. Cemented with 325 sacks Super "H" + 5# Halad-344 + .4% CFR-3 +3# jilonite + 3# salt (yld 1.66, wt 13). Tailed in with 50 sacks Premium (yld 1.66, wt 13) Tailed in with 50 sacks Premium (yld 14, wt 14.4). PD to 5:00 pm. Stage 2 cemented with 350 sacks Interfill "C" Neat (yld 2.4, wt 11.9). Tailed in with 50								
with 325 sacks Super	· /						10 1-	- 17
in with 50 sacks Prem			-			•	0 00	mc VIII
to 5:00 pm. Stage 2 ce	emented with 350 sa	icks Interfill "C" N	leat (yld 2.4,	wt 11.	.9). Tai	led in with 50	北京 ト	
sacks Premium Plus +	· 2% CaCl (yld 1.2, y	wt 15.6) PD at 6:00) pm. Circula	ated 40	0 sacks	, float and	AND LICHT. LD OFFICE	
circulate held OK. Ri	.	om 8/30/01.					01.1 0	1
continue on next page								***
14 I hereby certify that the foregoing is true and correct Name (Printed/Typed)			Title	Title				
*				Drilling Techician				62725.200
				Date				
		R FEDERAL OR STA		107000000			18	
Approved by			Title			Date	10	- RECEIVED
Conditions of approval, if any, are a certify that the applicant holds legal	or equitable title to those rights		Office	ΔΟ	°EDT			OCD ARTESH
Which would entitle the applicant to conduct operations thereon. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person kr			owingly and willbully					9000 1000
States any false, fictitious or fraudu								· · · ·
 American State of the state of					2			

ALEXIS C. SWOBODA PETROLEUM ENGINEER Adeline ALN Federal #11 30-015-31885 Sec. 6-T24S-R31E

9-1-4-01- Waiting on completion unit. 9-5-01-moved in and rigged up pulling unit. Rack and tally 2 7/8" J-55 tubing. TIH with bit, collars and tubing to 2000'. TIH with tubing and tag DV tool at 4054'. Will pickle tubing and roll hole with 3% KCL in AM. 9-7-01-Pickle tubing with 1000 gals 15% DI HCL. Reverse out and load hole with 3% KCL water. TOH with tubing laid down bit and collars. Moved in and rigged up JSI wireline. Ran GR/CBL/CCL from PBTD to 5800'-good cement. 9-9-01-Perforated Canyon 7743-7934', 37 total holes, 1 SPF. TIH with 5 1/2" RBP/BC and 5 1/2" packer. TIH with RBP/BC and packer. Set RBP at 8000'. Pull packer above all perfs. Acidize casings perfs in 3 stages. 1st - 7928-7939' 650 gals 15% IC-HCL and balls. 2nd - 7826-7939' 750 gals 15% IC-HCL and balls. Break at 3713#. 3rd-7742-7790'. Total to recover 192 bbls. Release packer and RBP. Frac casing perfs 7742-7931' with 86,250 gals Delta 20 frac and 158,000# 20/40 Super LC. Wash out to PBTD 8114'. Turn well to production to ran production tubing and rods 9-15-01.