

CRA BLM FORMA

**APPLICATION FOR SURFACE COMMINGLING, OFF LEASE
MEASUREMENT AND ALTERNATE METHOD OF MEASUREMENT**

This Format Should Be Attached To A Sundry Notice

To: Bureau of Land Management
2909 W. 2nd
Roswell, NM 88201-2019

BP America Production Company is requesting approval for surface commingling and off-lease measurement and storage and an alternate method of measurement of gas production from the following formation(s) and well(s) on Federal Lease

No. NMNM101108 ; Lease Name: West Brushy 5 Federal

Well

<u>No.</u>	<u>API #</u>	<u>Loc.</u>	<u>Sec.</u>	<u>Twp.</u>	<u>Rng.</u>	<u>Formation</u>
<u>5</u>	<u>30-015-31869</u>	<u>SESE</u>	<u>5</u>	<u>26S</u>	<u>29E</u>	<u>Brushy Draw (Delaware)</u>

No. NMNM 101108; Lease Name: West Brushy 8 Federal

Well

<u>No.</u>	<u>API #</u>	<u>Loc.</u>	<u>Sec.</u>	<u>Twp.</u>	<u>Rng.</u>	<u>Formation</u>
<u>1</u>	<u>30-015-31675</u>	<u>NENE</u>	<u>8</u>	<u>26S</u>	<u>29E</u>	<u>Brushy Draw (Delaware)</u>
<u>2</u>	<u>30-015-31866</u>	<u>SENE</u>	<u>8</u>	<u>26S</u>	<u>29E</u>	<u>Brushy Draw (Delaware)</u>

No. NMNM 89815 ; Lease Name: West Brushy 4 Federal

Well

<u>No.</u>	<u>API #</u>	<u>Loc.</u>	<u>Sec.</u>	<u>Twp.</u>	<u>Rng.</u>	<u>Formation</u>
<u>3</u>	<u>30-015-32196</u>	<u>NENW</u>	<u>4</u>	<u>26S</u>	<u>29E</u>	<u>Brushy Draw (Delaware)</u>