


COPY

Form 9-331a
(Feb. 1951)

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Budget Bureau No. 42-R358.4.
Approval expires 12-31-60.Land Office Las CrucesLease No. 063875Unit Receivable

OCT 24 1960

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

April 22, 1959, 19

Well No. #4 is located 1980 ft. from ~~XXXX~~ line and 660 ft. from ~~XXXX~~ line of sec. 21NE 1/4 Sec. 21 (1/4 Sec. and Sec. No.) 25S (Twp.) 30E (Range) N.M.P.M. (Meridian)Wildcat (Field) Eddy (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Placed 10 sack cement plug at bottom of 5 1/2" casing 3855'. Shot off and pulled 5 1/2" casing and set 10 sack plug at top of casing 3500 feet. Set 10 sack plug at 800 feet. Set 10 sack plug at surface and set marker.

Location cleaned and pit filled. Ready for your inspection.

RECEIVED
APR 28 1959
U. S. G. S.
ARTESIA, NEW MEX.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company H. N. SweeneyAddress Hinkle BuildingRoswell, New MexicoBy /s/ H. N. SweeneyTitle Operator