M. M. C. C. C. COPY

SUBMIT IN 1 LICATE. Form approved. JITED STATES

(May 1963)	DEPARTI	MENT OF THE	INTERI	OR (Other instructions on verse aide)	76 5. LEASE I	DESIGNATION AND S		
		GEOLOGICAL SURVEY				LC-070341		
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug track to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals."						6. IF INDIAN, ALLOTTEE OR TRIBE NAME		
1.		•		1,	7. UNIT AG	REEMENT NAME		
WELL GAS WE				APR 1 C 107			<u> </u>	
2. NAME OF OPERATOR						R LEASE NAME	نم بار م	
Western 3. ADDRESS OF OPER		ducing Comp	any		9. WELL N	er Lake U	nit MP	
900 Building of the Southwest Midland For the Ras 29701								
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*						AND POOL, OR WILE	CAT	
See also space 17 At surface	below.)	Corra	Corral (Canyon) Dela-					
9 6 0' FEL	& 330' FN	11. SEC., 1	11. SEC., T., E. M.; OR BLE. AND WAYS					
		10 5 5 3 -	Sec. 197 T-25-S,					
14. PERMIT NO. 15. ELEVATIONS (Show whether DF, BT, CR, etc.)						12. COUNTY OR PARISH 43. STATE		
14. FERMIL NO.		3209		,,,	2	ly g g line		
					5		M LIEVIC	
16.	Check A	ppropriate Box !o l	ndicate N	lature of Notice, Report, o	# # # # #	3 H > 2 x		
•	NOTICE OF INTEL	NTION TO:		SUB	SEQUENT EBPORT		r	
TEST WATER SH	UT-OFF	PULL OR ALTER CASING		WATER SHUT-OFF	icumon bresch of fine	REPAIRING WALL		
FRACTURE TREAT	·	MULTIPLE COMPLETE		FRACTURE TREATMENT	010.0 01.0 01.0 01.1	ALTERING CASING		
SHOOT OR ACIDI		ABANDON*	X	SHOOTING OR ACIDIZING	و والسا	ABANDONMENT		
REPAIR WELL (Other)		CHANGE PLANS		(Other)	ults of multiple	completion on We	ell	
17	ED OR COMPLETED OP	ERATIONS (Clearly state	all pertinen	t details and give pertinent de	tes, including e	stimated date of s	tarting any	
proposed work nent to this wo	rk.)*	onally drilled, give sub-	suriace loca	tions and measured and true ve	Citcur debras 10	a : u	-14	
						650 100 100 100 100 100 100 100 100 100 1	80. 0.	
1. Pull a	nd warehou	ise rods and	pump	•			9 4	
2. Unseat	tubing a	nchor and sn	ot 20	sack cement plu	g from	그 역 왕칙교도	₹.	
3345'.	_	ichor and sp	00 20	Such coment pro		1		
, 33.3						50 5 E		
3. Freepo	int casing	g and cut of	fat	approximately 25	500 '			
				-ce:		14 10 10 10 10 10 10 10 10 10 10 10 10 10		
4. Spot 2	0 sack cer	ment plug at	cut	orr point.		ot s out I out I out I		
5. Spot 2	20 sack cer	7 cas	ing.					
J. bpoc z	o back ce.		THE WAY	•				
6. Spot 5 sack plug at surface.								
_		·			RECE	IVFD		
7. Remove	head and	weld on pla	ite.		3 5 E 8	The Part of the Pa		
0 0-5 3-	bala ma	rker and cle	.an 10	astion	APR 14	1972 2 3 3 3		
8. Set dr	ту поте ша.	tker and cre	an IO	U.	S. George	A SUMP		
				A	RISIA NE	WEXING 3		
		•			5 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			
						albo Joseph Raffin		
18. I hereby certify	that the foregoing	is true and correct			<u> </u>			
61	les I	10 moth	TITLE	Operations Manag	rero de la como	TE April	11. 19	
SIGNED 1			TTLE	operacions manag	1JA - معمو			
(This space of	Faderal or State of	fice use)						
APPROVED BY			TITLE		DĀ	TB		
CONDITION	F APPROVAL, IF	ANY:				40		
B. K. Il.	1					10 10 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0		
A DESCRIPTION	المستعدر المحاصين				⇒ 24 = 24	್ ಪ್ರಚಿತ್ರ		

*See Instructions on Reverse Side