		•				
DISTRIBUTION	,	NEW MEXICO OIL CONS	ERVATION COMMISSION	D Form C-11 Revised 1	015-23878 11	
FILE U.S.G.S.					ate Type of Lease	
LAND OFFICE	<b>}</b>				5. State Oil & Gus Lease No.	
OPERATOR	·	O. C. D.			E-742	
			ARTESIA, OFFI	Ci		
APPLICATIC	DN FOR PERM	IT TO DRILL, DEEPEN	, OR PLUG BACK			
	-			7. Unit A	greement Name	
b. Type of Well DRILL X	]	DEEPEN	PLUG		pr Lease Name	
OIL GAS MULTIPLE SINGLE MULTIPLE ZONE ZONE						
2. Name of Operator	J OTHER		ZONE []	ZONE J STATE 9. Well N	KL 17 Com	
Tenneco Oil Company 3. Address of Operator	y 🧭				] and Pool, or Wildcat	
6800 Park Ten Bl.	San Antonio	. TX 78213			. Empire Morrow	
		LOCATED 1980	West			
	· · ·		FEET FROM THE			
AND 660 FEET FROM	THE South	LINE OF SEC. 17	TWP. 175 RGE. 2	29E NMPM		
ΛΙΙΙΙΙΙΙΙΙΙΙΙ	HHHHH,	THHHHHHH		12. Coun	a VIIIIIIA	
ΔΗΗΗΗΗΗΗ	HHHHH			<u>Eddy</u>		
ΛΙΙΙΙΙΙΙΙΙΙΙΙΙ	HHHHH			//////////////////////////////////////	MM////////////////////////////////////	
<u> </u>	<i>44111111</i>	<i>\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\</i>	19. Proposed Depth	9A. Formation	20. Rotary or C.T.	
AIIIIIIIIIIIIIIIA				Morrow		
21. Elevations (Show whether DF	, RT, etc.) 21	A. Kind & Status Plug. Bond	21B. Drilling Contractor		Rotary rox. Date Work will start	
3612.4 GL	B1	anket - #248-074	Parker #34		st 21, 1981	
23.	<u>-</u>	PROPOSED CASING AN				
SIZE OF HOLE	SIZE OF CA	SING WEIGHT PER FOO	T SETTING DEPTH	SACKS OF CEMEN		
17-5"		ew 54.5# K-55 ST(		385	T EST. TOP Circ to surface	
<u>12-¼"</u> 8-½"		ew 36# K-55 STC	2600'	826	Circ to surface	
8- <sup>1</sup> <sub>2</sub> "	5-1/2" N	ew 17# N-80 LTC	10810'	650	Top @ 8300'.	
1 +	1 11 1 <i>1</i>		1	ł		
1. Set + 40' of 20'	' conductor	w/Rathole machine.	a' <u>-                                   </u>			
2. MIRU rotary rig.		gos is ded	indu		بر ا	
2. millio rocary rig.		0			A State of the	
3. Drill 17½" hole	to ± 350'.			•.	1 31-51	
4. Run & cement 13-	-3/8" 54.5#	K-55 ST&C csg. (N	lotify proper age	ncy before run	ning csg	
Cir. Cement to s	surface. R	un cement baskets i	if necessary.	sincy before run	ining cog./	
		· · · · · · · · · · · · · · · · · · ·	· · · · · · · · · · · · · · · · · · ·			
5. Cut off conducto weld to 50% of c	or & 13-3/8 sg. collap:	" Csg. weld on 13- se (Approx. 575 psi	-3/8" SOW 3000# t i)	ype "S" csg. h	d. Test	
6. NU 13-5/8" 5M BC	)Ps. Test	BOPs to 1000 psi w/	'rig pump and fre	sh water. (RU	Mud Logger	
before Ø out)		•	· •	APPROVAL VALID F	OR / DAYS	
7. Drill 123" hole IN ABOVE SPACE DESCRIBE PR FIVE ZONE. GIVE BLOWOUT PREVENT	to 2600'.	Set 9-5/8" csg. ce	ement to surface.	PERMIT EXPIRES	NGAWNDERWAYEW PRODUCT	
hereby certify Mat the information	on above is true a	nd complete to the best of my i	inpwiedge and belief.		<del></del>	
Signed Laite L	tray_	Tule_Productio	on_Analyst	Date]	<u>1 1 y 21, 1981</u>	
(This space for :	State Use)					
APPROVED BY MICH	' Ares	SUPER SUPER	VISOR, DISTRICE H		<b>JUL</b> 2 8 1981	
CONDITIONS OF APPROVAL IF	ANY:			DATE		
must be Commu	nitized	nolify 2	his office Im	mediately	. ej	
Prior to Produc	ing	Water +	this office Im	countered	_ <b>/</b>	

- 8. ND BOPs. NU 13-5/8" 3000# X 11" -5000# WKM type "SF" csg. head spool. Test spool to 1250 psi.
- 9. NU 10" 5M BOP or 13-5/8" 5M BOP (Note: 13-5/8" will require a DSA in order to NU) Test Hydril to 2500 psi. Test Rams & Manifold to 5000 psi. Test csg. to 1500 psi before Ø out.

.

- 10. Drill 8<sup>1</sup><sub>2</sub>" hole to 10810'.
- 11. Log as directed by Geologist.

--

12. If productive, Run 5<sup>1</sup>/<sub>2</sub>" csg.

Gas is dedicated.