



- ◁ Wind Direction Indicators (wind sock or streamers)
- △ H2S Monitors (alarms at bell nipple and shale shaker)
- ◇ Briefing Areas
- Remote BOP Closing Unit
- Sign and Condition Flags

EXHIBIT "D"
RIG LAY OUT PLAT

W.A. & E.R. HUDSON, INC.
PUCKETT "B" # 12-1
UNIT "D" SECTION 12
T17S-R31E EDDY CO. NM