

- Wind Direction Indicators (wind sock or streamers)
- H2S Monitors (alarms at bell nipple and shale shaker)
- Briefing Areas

÷

- Remote BOP Closing Unit
- □ Sign and Condition Flags

EXHIBIT "D" RIG LAYOUT PLAT

CONCHO RESOURCES, INC. BLACK JACK "1" FEDERAL #2 UNIT "P" SECTION 1 T24S-R30E EDDY CO. NM

N