

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

WELL API NO. 30-045-09936
5. Indicate Type of Lease STATE FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other
2. Name of Operator BP America Production Company Attn: Mary Corley
3. Address of Operator P.O. Box 3092 Houston, TX 77253

7. Lease Name or Unit Agreement Name: Blanco Com 1
Well No. 1
Pool name or Wildcat Blanco Mesaverde

4. Well Location Unit Letter <u>G</u> <u>1490</u> feet from the <u>North</u> line and <u>1715</u> feet from the <u>East</u> line Section <u>02</u> Township <u>30N</u> Range <u>11W</u> NMPM <u>San Juan</u> County

10. Elevation (Show whether DR, RKB, RT, GR, etc.) 5869' GR
--

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPLETION <input type="checkbox"/>	SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER: <input type="checkbox"/> Add Pay

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

12/14/2002 MIRU workover rig. NDWH. NU BOPs. TOH w/2-3/8" production tubing. TIH w/ bit & scraper for 5 1/2" CSG to liner top @ 4352' & scraper for 5" CSG to 4656'. TIH w/CIBP & set @ 4656'. Load hole with 2% KCL. Pressure test CSG to 2300 psi. Run GR log over Menefee & Lewis Shale from 4656' - 4000'. RU & Perforate w/2 JSPF, .400 inch diameter: 15 Shots / 30 Holes - 4579', 4552', 4534', 4514', 4505', 4470', 4457', 4440', 4434', 4411', 4405', 4388', 4361', 4351', 4340'. RU & frac w/500 gal 15% HCL, then 81,076# 16/30 Brady Sand, 70% Quality Foam & N2. RU & Flowback frac thru 1/4" choke for 4 hrs. Upsized choke to 1/2" & continued flow back. Upsized choke to 3/4" after 18 hrs & flowed back for 1 hrs. ND Flowback tree. TIH & tag fill @ 4560'. Unload hole. C/O to CIBP set @ 4656'. DO CIBP. C/O to 4867'. TIH & tag 12' of fill. C/O to PBSD. Blow well dry at PBSD. TOH. TIH w/2 3/8" production tubing & land @ 4760'. ND BOP's. NU WH. Test well for air.

12/30/2002 RDMO workover rig. Return well to production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNATURE <u>Mary Corley</u>	TITLE <u>Sr. Regulatory Analyst</u>	DATE <u>01/02/2003</u>
Type or print name <u>Mary Corley</u>	Telephone No. <u>281-366-4491</u>	
(This space for State use)		
APPROVED BY <u>[Signature]</u>	TITLE <u>DEPUTY OIL & GAS INSPECTOR, DIST. 43</u>	DATE <u>JAN - 6 2003</u>
Conditions of approval, if any:		