Submit 3 Copies To Appropriate District	State of New Me	xico		Form C-103
Office • •	Energy, Minerals and Natural Resources		/	Revised March 25, 1999
District I 1625 N. French Dr., Hobbs, NM 88240	Energy, minerals and material resources		WELL API NO.	
District II	OIL CONSERVATION DIVISION			045-10150
811 South First, Artesia, NM 88210 District III	1220 South St. Francis Dr.		5. Indicate Type o	
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505		STATE 6. State Oil & Ga	FEE X
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM	build 1 c, 1 live o root		o. State Off & Ga	is Lease No.
87505				
	FICES AND REPORTS ON WELLS	IC PACK-TO A	7. Lease Name or	Unit Agreement Name:
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG-BACK-TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH (/ / / / / / / / / / / / / / / / / /		Walla	ce Gas Com	
PROPOSALS.)	19 N 19 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		Walla	,c das dom
1. Type of Well:			١	
Oil Well Gas Well	M Other	EB 2000) 3	8. Well No.	
2. Name of Operator BP America Production Company	Attn: Mary Corley	www.	of well no.	1
3. Address of Operator	tel O	3 1	9. Pool name or W	/ildcat
P.O. Box 3092 Houston, TX 7725	3	Die.	Blanco Mesaver	
4. Well Location	Se de la companya della companya del	2 277		
		28212022 Standard		
Unit Letter H	1640_feet from theNorth line	and 790 feet fi	rom the East	_line
Section 35	Township 31N Range	11 W NM	IPM San Juan	County
Section 35 Township 31N Range 11W NMPM San Juan County 10. Elevation (Show whether DR, RKB, RT, GR, etc.)				
1640' GR				
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
	NTENTION TO:		SÉQUENT REF	
PERFORM REMEDIAL WORK	☐ PLUG AND ABANDON ☐	REMEDIAL WORK	<	ALTERING CASING
TEARDODADU V ADANDON -	☐ CHANGE PLANS ☐	COMMENCE DRIL	LINC ODNE	PLUG AND
TEMPORARILY ABANDON [_ CHANGE PLANS	COMMENCE DRIL	LING OPINS.	ABANDONMENT
PULL OR ALTER CASING [☐ MULTIPLE ☐	CASING TEST AN	ID 🗆	
	COMPLETION	CEMENT JOB		
OTHER:		OTHER: Add Perf	s in Mesaverde	X
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date				
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion				
or recompilation.				
AND THE RESIDENCE OF THE PROPERTY OF THE PROPE				
01/03/2003 MIRU workover rig. Blow down well. NDWH. NU BOPs. TIH & tag fill @ 4925'. TOH w/2-3/8" production TBG. RU & TIH w/4-1/2" CIBP & set @ 4640'. Load hole w/ 2% KCL & pressure tested CSG to 1500 psi. RU & perf (2 SPF 120 deg phasing, .400				
inch diameter) Menefee & Lewis shale: 4342', 4346', 4388', 4412', 4422', 4431', 4446', 4488', 4494', 4536', 4554', 4604', 4614'.				
RU & Frac w/57,071# 16/30 Brady Sand & 70 Quality N2 Foam. RU & flowback frac fluid thru ½" choke for 16 hrs. TIH & tag fill @				
	clean. PU above perfs & SI well for 15			
Unable to go past 4925'. New PBTD @ 4925'. Circ hole clean. TIH & tag 0 fill. TOH. TIH w/ 2-3/8" production TBG & land @t 4755'.				
ND BOP's. NU WH. Test well	for air.			
PDMO workover rig. Pig rele	ased @ 10:30 hrs on 01/10/03.			
NDWO WORKOVELING. HIS TELE	ased @ 10.30 ms on 01/10/03.			
Return well to production.				
I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
Type or print name Mary Corley Telephone No. 281-366-4491 (This space for State use)				
DEPUTY ON & GAS INTERECTOR, MIST. 43 FEB 10 2003				
APPPROVED BY Chash The TITLE DATE 2003				
Conditions of approval, if any:				