

(August 1999)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED

OMB No. 1004-0135

Expires: November 30, 2000

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

RECEIVED
2003 FEB 14 PM 1:11

5. Lease Serial No.

NOO-C-14-20-5389

6. If Indian, Allottee, or Tribe Name

NAVAJO - NAPI

7. If Unit or CA Agreement Designation

FARMINGTON, NM

8. Well Name and No.

Ricky #2

9. API Well No.

30-045-25977

10. Field and Pool, or Exploratory Area

Basin Fruitland Coal

11. County or Parish, State


San Juan

NM

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
☒ Notice of Intent	☐ Acidize	☐ Deepen	☐ Production (Start/Resume)	☐ Water Shut-off
☐ Subsequent Report	☐ Altering Casing	☐ Fracture Treat	☐ Reclamation	☐ Well Integrity
☐ Final Abandonment Notice	☐ Casing Repair	☐ New Construction	☐ Recomplete	☐ Other
	☐ Change Plans	☒ Plug and abandon	☐ Temporarily Abandon	
	☐ Convert to Injection	☐ Plug back	☐ Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths or pertinent markers and sands. Attach the Bond under which the work will be performed or provide the Bond No. on file with the BLM/ BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notice shall be filed only after all requirements, including reclamantion, have been completed, and the operator has determined that the site is ready for final inspection.)



**Coleman Oil & Gas, Inc., Proposes To Plug and Abandon this well as follows.
See attached procedure.**

14. I hereby certify that the foregoing is true and correct.

Name (Printed/ Typed)

MICHAEL T. HANSON

Title

ENGINEER

Signature

Date

February 12, 2003

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Original Signed: Stephen Mason

Title

Date

2/21/03

Conditions of approval, if any are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 AND Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on reverse)

NMOCD

330 2903

Wednesday, February 12, 2003

Well: Ricky #2

Field: Basin Fruitland Coal
1150-1154
1182-1186

PLUG AND ABANDON PROCEDURE.

1. MOL with cementers, hold safety meeting, blow well down and kill with water if necessary.
2. Connect cement truck to 2 7/8" casing and fill 40 sacks (47 Cu. Ft.) Class B cement, add 1/2# per sack of celloflake to first 5 sacks of cement. Pump cement until casing stands full of cement. Volumes based on 18% excess.
3. Install dry hole marker.
4. Location will not be reclaimed. Well pad will be used for Ricky Com #2R.