Form	21	40 S	
CILLI	JI	00-5	
(Aum	101	1999)	
(Augi	191	1777	

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

. .

FORM APPROVED
OMB NO. 1004-0135
Evniros: November 20, 200

	/ Expires: Nove
i.	Lease Serial No.
	NIKASEO78115

Б	UKEAU OF LAND MANA	AUEMEN I				
SUNDRY NOTICES AND REPORTS ON WELLS			5. Lease Serial No. NMSF078115  6. If Indian, Allottee or Tribe Name			
Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.						
SUBMIT IN TRI	PLICATE - Other instru	ctions on reverse side	).	7. If Unit or CA/Agre	ement, Name and/or No.	
Type of Well     Oil Well				8. Well Name and No GRENIER 11F	8. Well Name and No. GRENIER 11F	
2. Name of Operator	Contact:			9. API Well No.		
BURLINGTON RESOURCES O&G CO LP E-Mail: pcol				30-045-30466-00-S1		
3a. Address 3401 EAST 30TH FARMINGTON, NM 87499	3b. Phone No. (include area code) Ph: 505.326.9727 Fx: 505.326.9781		10. Field and Pool, or Exploratory BASIN DAKOTA			
4. Location of Well (Footage, Sec., 7	n)		11. County or Parish,	and State		
Sec 13 T31N R12W NWNW 965FNL 500FWL			SAN JUAN COUNTY, NM			
12. CHECK APPI	ROPRIATE BOX(ES) T	O INDICATE NATUR	E OF NOTICE, F	L REPORT, OR OTHE	R DATA	
TYPE OF SUBMISSION	TYPE OF ACTION					
□ Notice of Intent	☐ Acidize	☐ Deepen	☐ Produc	ction (Start/Resume)	☐ Water Shut-Off	
_	☐ Alter Casing	☐ Fracture Treat	□ Reclar	nation	■ Well Integrity	
Subsequent Report	□ Casing Repair	■ New Construct	tion 🔲 Recom	plete	Other	
☐ Final Abandonment Notice	☐ Change Plans	Plug and Aban	don 🗖 Tempo	orarily Abandon	Workover Operations	
	☐ Convert to Injection	☐ Plug Back	Plug Back Water Disposal			
If the proposal is to deepen directions Attach the Bond under which the wo following completion of the involved testing has been completed. Final Ald determined that the site is ready for f (11/1/02) MIRU. SDON. (11/4/02) ND WH. NU BOP. T PT 4-1/2" csg & WH w/braden (11/5/02) TIH w/RBP, set @ 7 psi/30 mins, no leak off on csg (11/6/02) TIH w/retrieving tool TOOH w/RBP. TIH w/CIBP, set (11/7/02) Establish rate throug OK. PT tbg to 2000 psi, OK. P SDON. (11/8/02) TIH w/bit, tag cmt @ open to 500 psi/30 mins, OK.	rk will be performed or provide operations. If the operation repandonment Notices shall be final inspection.)  I'll w/2-3/8" tbg, tag up @ thead open to 500 psi, not 149'. Set pkr @ 7119'. Pg. Rls pkr & TOOH. SDO to RBP @ 7149'. Unload et @ 7157'. PT CIBP to 19 h sqz hole. TIH w/cmt repump 946 sxs Type III cm @ 3822'. Drill out cmt to 38 SDON.	e the Bond No. on file with Besults in a multiple completion led only after all requirement 7391'. TOOH w/tbg. To leak off. TOOH w/pkr. T RBP to 1000 psi, OK. N. d. hole w/air. Latch onto 1000 psi, OK. Perf 1 sqzetainer, set @ 3854'. PT at w/2% calcium chloride	LM/BIA. Required son or recompletion in a son including reclamation of the control of the contro	ubsequent reports shall be new interval, a Form 316 on, have been completed,  et @ 30'.	filed within 30 days 50-4 shall be filed once and the operator has	
14. I hereby certify that the foregoing is  Con  Name (Printed/Typed) PEGGY C	: Electronic Submission For BURLINGTON R nmitted to AFMSS for prod		sent to the Farmi	ngton 03MXH0334SE)		
Signature (Electronic S	Submission)	Date 1	2/03/2002	·		
		OR FEDERAL OR ST		JSE		
Approved By ACCEPT	ED		THEW HALBER' ROLEUM ENGIN		Date 01/09/2003	
Conditions of approval, if any, are attached certify that the applicant holds legal or equivalent would entitle the applicant to conduct the conduction of t	uitable title to those rights in the	e subject lease	armington		1 0 1/00/2000	
Title 18 U.S.C. Section 1001 and Title 43	U.S.C. Section 1212, make it a			nake to any department or	agency of the United	

States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

## Additional data for EC transaction #16549 that would not fit on the form

## 32. Additional remarks, continued

(11/9/02) Ran CBL @ 4688' to surface, 0-350' good bond, 350-1175' no bond, 1175-3750' spotty, 3750-4688' good bond. SDON.
(11/11/02) (Verbal approval from Jim Lovato, BLM and Charlie Perrin, OCD, to squeeze). Perf 2-0.32" diameter sqz holes @ 1070'. TlH w/4-1/2" pkr, on 2-3/8" tbg, set @ 761'. PT backside w/wtr to 500 psi, OK. SDON.
(11/12/02) Rls pkr & TOOH. TlH w/RBP, set @ 1175'. TlH w/pkr, set @ 1137'. PT RBP to 2500 psi, OK. Rls pkr & PUH reset @ 761'. Pump 296 sxs Type III cmt (420 cu. ft.). WOC. SDON.
(11/13/02) Rls pkr & TOOH. TlH w/bit, tag cmt @ 1003'. Circ hole clean. WOC. SDON.
(11/14/02) Drill hard cmt @ 1015' to sqz holes @ 1070'. Drill cmt stringers @ 1070' to 1085'. Circ hole clean. PT sqz holes @ 1070' to 500 psi, no leak off. TOOH w/bit. TlH, latch onto RBP & release RBP. TOOH w/RBP. PT sqz holes to 500 psi, no leak off. Ran CBL @ 3990' to surface. TOC @ 996'. SDON.
(11/15/02) TlH w/mill to CIBP @ 7157'. Mill CIBP @ 7157'. Circ hole clean. CO to 7380'. SDON.
(11/18/02) TIH w/mill to CIBP @ 7155' bg, set @ 7333'. SN @ 7331'. ND BOP. NU WH. RD. Rig released.

CTP0219728202