

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO.

30-045-25272

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

L-2986

7. Lease Name or Unit Agreement Name
State of New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS)

1. Type of Well:

OIL
WELL ☒

GAS
WELL ☐

OTHER

2. Name of Operator

Elm Ridge Resources, Inc.

8. Well No.

36-13

3. Address of Operator

PO Box 189 Farmington, NM 87499

9. Pool name or Wildcat

Lybrook Gallup

4. Well Location

Unit Letter L : 1650 Feet From The South Line and 990 Feet From The West Line

Section 36 Township 24N Range 8W NMPM Rio Arriba County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
6871' GR

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

11. **NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent date, including estimated date of starting any proposed work) SEE RULE 1103.

PCD - 334-6178 EXT 16
Elm Ridges Resources, Inc intends to plug and abandon this well in accordance with regulations. Production equipment will be removed. Plugs will be placed inside and outside casing unless evidence of cement behind pipe is indicated. Proposed procedure as follows: Notify BLM office @ 505-599-8907 24-hrs prior to commencement of plugging operations. Pull all retrievable downhole equipment. Set a CIBP @ 5180'. Spot a 200' cement plug on top of CIBP to 4980'. Set a 200' cement plug from 4980' to 4780' across Mesa Verde inside and outside 4-1/2" casing. Set a 200' cement plug from 4780' to 4580' across Pictured Cliffs inside and outside 4-1/2" casing. Set a 100' cement plug from 4580' to 4380' across Fruitland inside and outside casing. Set 250' cement plug from 1400' to 1250' across Ojo Alamo inside and outside casing. Set a 250' cement plug from 250' to surface between 4-1/2" and 8-5/8" casing. Cut off wellhead. Install dryhole markers. Clear and remediate. 300' inside & outside casing
Certified Return Receipt # 7001 1940 0002 1375 7313

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Trudy Grubelnik

TITLE

Production Assistant

DATE

03/17/03

TYPE OR PRINT NAME

Trudy Grubelnik

TELEPHONE NO.

505-632-3476

(This space for State Use)

APPROVED BY

Charles

TITLE

DEPUTY OIL & GAS INSPECTOR, DIST. #3

DATE

MAR 18 2003

CONDITIONS OF APPROVAL, IF ANY:

X