	۳.		
Submit 2 Control To Assessment District	•		/
Submit 3 Copies To Appropriate District Office	State of New Me	exico	// Form C-103
District I	Energy, Minerals and Natu	ral Resources	// Revised March 25, 1999
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.
<u>District II</u> 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION	DIVISION	30-045-30942
District III	1220 South St. Fran		5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87		STATE X FEE
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM	Santa Pe, INIVI 67	7303	6. State Oil & Gas Lease No.
87505			
SUNDRY NOTICE	ES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name:
(DO NOT USE THIS FORM FOR PROPOSAL	LS TO DRILL OR TO DEEPEN OR PLI	UG BACK TO A	Ropco 16
DIFFERENT RESERVOIR. USE "APPLICA" PROPOSALS.)	TION FOR PERMIT" (FORM C-101) FO	OR SUCH	•
1. Type of Well:		N 30 311 1 5 1	
Oil Well Gas Well X Ot	her (1)	A J	
2. Name of Operator		(V)	7. Well No.
Richardson Operating Company	A Comment of the Comm	MAR 2003 이	\1
3. Address of Operator	50		9. Pool name or Wildcat
3100 La Plata Highway Farmington,	NM 87401		Basin Fruitland Coal & Twin Mounds PC
4. Well Location		* 10 2 J	
The William Do			
Unit Letter B : 9	997feet from theNorth	/, line and1563_	feet from theEastline
Section 16 Township 29N Range 14W NMPM County San Juan			
	10. Elevation (Show whether DI	R. RKB. RT GR. etc.	MPM County San Juan
5210' GR			
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTE	ENTION TO:	SUBS	EQUENT REPORT OF:
	PLUG AND ABANDON	REMEDIAL WORK	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRIL	
PULL OR ALTER CASING	MULTIPLE	CASING TEST AND	ABANDONMENT
(COMPLETION	CEMENT JOB	
OTHER:		OTHER:	
12. Describe proposed or completed or	perations. (Clearly state all perti		e pertinent dates, including estimated date of
starting any proposed work). SEE	RULE 1103. For Multiple Com	nent details, and give	bore diagram of proposed completion or
recompliation.			
03/27/03 Spud 8 3/4" surface hole. Drill to 125'. Ran 3 joints 7" 20# casing to 122' (127' KB). Flush with 5 Bbl water. Pump 50 sx (59			
cu.ft.) Class 'B' w/ 2% CaCl, 1/4#/sk celloflake. Circ 4 Bbl cement to surface. SDFN; WOC.			
03/28/03 NU BOP; test to 600 psi, test good. Test surface casing to 600 psi for 30 min.; test good. Drill 6 1/4" hole to 650'. SDFN.			
03/28/03 NU BOP; test to 600 psi, test a	good. Test surface casing to 600	psi for 30 min.; test	good. Drill 6 1/4" hole to 650'. SDFN.
03/29/03 Drill to 700' TOH Pan 18 its 4 1/" PR 10 5# assistant at 2703 (7777 177)			
03/29/03 Drill to 790'. TOH. Ran 18 jts 4 ½" 8R 10.5# casing; set at 772' (777' KB). Float collar at 736' (741' KB). Pump 85 sx (100 cu.ft.) Class 'B' cement w/ ¼#/sk celloflake, 15.6 ppg slurry; circ 4 Bbl cement to surface. Bumped plug to 1000 psi, plug held.			
comone w /4m/sk conor	lake, 15.0 ppg siurry, effe 4 Bor	cement to surface. B	sumped plug to 1000 psi, plug held.
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNATURE	TITLE O	perations Manager	DATE_03-31-03
Trans on maintain		·	
Type or print name Drew Carnes			Telephone No. 505-564-3100
(This space for State use)	.//	and the second of the second o	
APPPROVED BY Charles 7		y oil & gas inspect	**** 6) # //#/ *
Conditions of approval, if any	Cerry TITLE_		DATE