submitted in lieu of Form 3160-5

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

PEOEN/ED

201 477 -2 AM 11: 30

Sundry Notices and Reports on Wells Lease Number Mington, NM 5. 14-20-603-2034 1. Type of Well 6. If Indian, Ali, or **Tribe Name** WIW 7. **Unit Agreement Name** 2. Name of Operator Hart Oil & Gas, Inc. 8. Well Name & Number 3. Address & Phone No. of Operator Navajo T1 "F" #140 9. PO Box 307, Farmington, NM 87499 (505) 326-1163 API Well No. 30-045-10902 Location of Well, Footage, Sec., T, R, M 10. Field and Pool Horseshoe Gallup 990' FSL and 850' FEL, Section 9, T-31-N, R-17-W, 11. **County & State** San Juan County, NM 12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA Type of Submission Type of Action Notice of Intent X Abandonment Change of Plans Recompletion **New Construction** Non-Routine Fracturing X Subsequent Report Plugging Back Casing Repair Water Shut off **Final Abandonment Altering Casing** Conversion to Injection Other -13. Describe Proposed or Completed Operations Hart Oil & Gas plugged and abandoned this well on February 27, 2004. 14 2-26-04 MOL & RU. Work packer free. NU BOP. TOH and LD 24 joints 2-3/8" tubing, no packer. PU 25 joints 1-1/4" workstring and push packer down to 791'. W. Ashley, NN, approved depth to plug well at 791'. Shut in well. 2-27-04 Establish circulation out the 4.5" casing with 15 bbls water. Plug #1 with 48 sxs cement with 2% CaCl2 inside the casing from 791' to 230' to isolate the Gallup perforations. LD tubing. Shut in well and WOC. Attempt to pressure test casing, leak. TIH and set packer at 30'. Pressure test casing below packer, well still circulating out bradenhead. Set packer at 61' and pressure test casing below to 500#, OK. TOH and LD tubing and packer. RIH with wireline and tag cement at 296'. Perforate 2 holes at 86'. TIH and set packer at 61'. Pump 15 bbls water down tubing 1-1/2 bpm at 350#, no circulation. Procedure change approved B. Freeman, NEPA. Plug #2 with 21 sxs cement pumped down 4.5" casing from 86' to surface, circulate good cement out bradenhead. Shut in well. Cut off wellhead and found cement at surface. Mix 17 sxs cement and install P&A marker. RD and MOL. V. Euentillie, W. Ashley, Navajo Nation Minerals and B. Freeman Navajo EPA were on location. 14. I hereby certify that the foregoing is true and correct. Signed Title Vice President Date 3/15/04 Gina Salied (This space for Federal or State Office use) APPROVED BY Title Daten DECO CONDITION OF APPROVAL, if any: PR 0 5 2004

SR U 5 2004