

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENTFORM APPROVED
OMB No. 1004-0137
Expires: March 31, 2007**SUNDRY NOTICES AND REPORTS ON WELLS**

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE- Other instructions on reverse side.1. Type of Well
☐ Oil Well ☒ Gas Well ☐ Other2. Name of Operator **Richardson Operating Company**3a. Address
3100 La Plata Highway, Farmington, NM, 874013b. Phone No. (include area code)
505-564-31004. Location of Well (Footage, Sec., T., R., M., or Survey Description)
2010 FSL, 1785 FEL, Sec. 14, T28N, R8W5. Lease Serial No.
NMSF-0783906. If Indian, Allottee or Tribe Name
NA7. If Unit or CA/Agreement, Name and/or No.
NA8. Well Name and No.
Federal 14-14 #29. API Well No.
30-045-3195010. Field and Pool, or Exploratory Area
Basin Fruitland Coal11. County or Parish, State
San Juan County, New Mexico**12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA**

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input checked="" type="checkbox"/> Other Spud & Surface csg
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompletable horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletable in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

6/1/2004 MIRU. Secure rig, SDFN.**6/2/2004 Spud well at 9:30am. Drill 310' new 8 3/4" hole to 310'. Mix mud w/ 100 sx gel, 2 sx lime, 10 sx starch, and 1/2 sk Drispac.****Circulate mud. Secure rig, SDFN.****6/3/2004 TOH with DP/DC and bit. Set 303' 7" K-55 surface csg at 304' -1 GL. Cement surface csg with 120 sx Class B cement, with 2% CaCl2, 1/4#/sk celloflake, 15.60 ppg, 1.18 yield. Circulate 12 bbl to surface. Secure rig, SDFN. WOC.**

14. I hereby certify that the foregoing is true and correct
Name (Printed/Typed)

Title

Signature

Date

06/28/2004**THIS SPACE FOR FEDERAL OR STATE OFFICE USE****ACCEPTED FOR RECORD**

Approved by

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

JUL 07 2004**FARMINGTON FIELD OFFICE**
BY **ste**

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

NMOCD