submitted in lieu of Form 3160-5

UNITED STATES

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

		5.	Lease Number
_		c	NMSF-078423
Type of Well GAS		6.	If Indian, All. or Tribe Name
GAS			IIIDE Name
		7.	Unit Agreement Name
Name of Operator			
BURLINGTON			
RESOURCES OIL & GAS	COMPANY LP	8.	San Juan 29-7 Unit Well Name & Number
Address & Phone No. of Opera	tor	0.	San Juan 29-7 U #51
PO Box 4289, Farmington, NM		9.	
			30-039-25268
Location of Well, Footage, S		10.	Field and Pool Basin Fruitland Coa
790'FNL, 1535'FEL, Sec.8, T-	-23-N, K-/ -W, NMPM		Blanco Pictured Cli
		11.	County and State
			Rio Arriba Co, NM
CHECK APPROPRIATE BOX TO IN	INTERME NAMIDE OF NOMICE DI	PDODU OURD	рата
Type of Submission	Type of Action		DAIR
X Notice of Intent		Change of Pl	ans
<u> </u>		New Construc	
Subsequent Report		Non-Routine Water Shut o	
Final Abandonment	Altering Casing		
	Other -		,
Describe Proposed or Comp	oleted Operations		
		according t	o the attached
	nd abandon the subject well	according t	o the attached
It is intended to plug ar	nd abandon the subject well	according t	o the attached
It is intended to plug ar	nd abandon the subject well	according t	o the attached
It is intended to plug ar	nd abandon the subject well	according t	210
It is intended to plug ar	nd abandon the subject well	according t	230
It is intended to plug ar	nd abandon the subject well	according t	2004 A
It is intended to plug ar	nd abandon the subject well lbore diagram.	according t	2004 ANG 1 PR 070 F/
It is intended to plug ar	nd abandon the subject well lbore diagram.	according t	2014 RUG
It is intended to plug ar	nd abandon the subject well lbore diagram.	according t	2004 RUS 1.7 RE 070 F.A.7
It is intended to plug ar	nd abandon the subject well lbore diagram.	according t	2004 RUG 11 REC GTO FAAA
It is intended to plug ar	nd abandon the subject well	according t	2001 RUG 11 PCO RECEIVED 070 FARMINGIA
It is intended to plug ar	nd abandon the subject well lbore diagram.	according t	2001 AUG 11 PO 1 RECEIVED 670 FASKURDI DO
It is intended to plug ar	nd abandon the subject well lbore diagram.	according t	2001 AUG 11 PO 1 RECEIVED 670 FASKINGS DE
It is intended to plug ar	nd abandon the subject well lbore diagram.	according t	2001 RUG 11 PCO RECEIVED 070 FARMINGIA
It is intended to plug ar	nd abandon the subject well lbore diagram.	according t	2001 AUG 11 PO 1 RECEIVED 670 FASKURDI DO
It is intended to plug ar procedure and wel	AUG 2004		2001 AUG 11 PO 1 RECEIVED 670 FASKINGS DE
It is intended to plug ar procedure and wel	nd abandon the subject well lbore diagram.		2004 AUG 11 P7 1 RECEIVED 670 FASANGIDE
It is intended to plug ar procedure and wel	Aug 2004 a foregoing is true and cor	rect.	2004 RUG 11 PR 1 10 RECEIVED 670 FALKHIROTOU EW
It is intended to plug ar procedure and well well and well and well are the med Manay Ultmann	AUG 2004 a foregoing is true and cor Title Senior Staff Spe	rect.	2004 AUG 11 P7 1 RECEIVED 670 FASANGIDE
It is intended to plug ar procedure and wel	AUG 2004 a foregoing is true and cor Title Senior Staff Spe	rect.	2004 RUG 11 PO 1 100 RECEIVED 670 FAARHOLDE EN

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

San Juan 29-7 Unit #519 – PC/FtC PLUG AND ABANDONMENT PROCEDURE

790' FNL & 1535' FEL NE, Section 8, T029N, R00W Latitude: N36°44.73', Longitude: W107° 35.436' AIN: 3744700 8/2/2004

All cement volumes use 100% excess outside pipe and 50' excess inside pipe. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures. All cement will be ASTM Type III, mixed at 14.8 ppg with a 1.32 cf/sx yield.

- 1. Install and test location rig anchors. Prepare blow pit. Comply with all NMOCD, BLM, and Burlington safety regulations. MOL and RU daylight pulling unit. Conduct safety meeting for all personnel on location. NU relief line and blow down well; kill with water as necessary. ND wellhead and NU BOP. Test BOP.
- 2. PU and release pump. TOH and LD rods with pump. TOH and tally 99 joints 2-3/8" tubing. Inspect tubing, if necessary, LD and PU workstring.
- 3. Plug #1 (Pictured Cliffs and Fruitland perforations, 3136' - 2650'): TIH with 4-1/2" cement retainer and set at 2780'. Pressure test tubing to 1000#. Load casing with water and circulate well clean. Pressure test casing to 1000#. Mix and pump 62 sxs Type III cement, squeeze 49 sxs below the CR to fill the PC and Fruitland perforations then leave 13 sxs above the CR to cover the Fruitland top. PUH with tubing to 2247'.
- Plug #2 (Kirtland and Ojo Alamo tops, 2247' 19\$57): Mix 23 sxs Type III cement and spot a 4. balanced plug inside casing to cover the Kirtland and Ojo Alamo tops. PUH to 470'.
- 6. Plug #3 (Nacimiento top and 8-5/8" casing shoe, 470' - Surface): Pressure test bradenhead annulus to 300#. If it tests, then mix 38 sxs Type III cement and spot a balanced plug inside casing from 470 to surface, circulate good cement out casing valve. TOH and LD tubing. If the bradenhead annulus does not test, then perforate at the appropriate depth and set plug(s) at the appropriate depths to cover from 470° to 370' inside the casing and the surface casing shoe. 734

7. ND BOP and cut off casing below surface. Install P&A marker with cement to comply with regulations. RD, move off location, cut off anchors and restore location.

Recommended:

Engineer

Office - (599-4043) Cell - (320-0321)

Sundry Required: Many Oltmanns

Approved:

San Juan 29-7 Unit #519

CurrentAIN #3744700

Basin Fruitland Coal / Blanco Pictured Cliffs

790' FNL & 1535' FEL, Section 8, T-29-N, R-7-W, Rio Arriba County, NM Lat: N 36^ 44.73 / Long: 107^ 35.436 / API #30-039-25268

Today's Date: 7/19/04

Spud: 6/9/93 Completed: 8/5/93 Elevation: 3199' GL

12-1/2" hole

Nacimiento @ 420'


Ojo Alamo @ 2015'

Kirtland @ 2197'

Fruitland @ 2700'

Pictured Cliffs @ 3005'

7-7/8" Hole



Circulated Cement to Surface

8-5/8" 24# K-55 Casing set @ 246' Cement with 277 cf (Circulated to Surface)

WELL HISTORY

Nov '99: Pull tubing. TIH with 3-7/8" bit and watermellon mill; CO to 3154'. TIH with 99 joints 2-3/8" tubing and land at 3136'. Ran pump and rods.

2-3/8" Tubing @ 3136' (99 joints, EUE with rods)

DV Tool @ 2755'
Cement with 624 sxs (1036 cf)
Circulated 25 bbls cement to surface.

Fruitland Coal Perforations: 2830' – 2980'

Pictured Cliffs Perforations: 3003' – 3136'

4-1/2" 10.5# K-55 Casing set @ 3194'
Cement with 138 sxs (182 cf)
Circulated cement to surface before second stage.

San Juan 29-7 Unit #519

Proposed P&A

AIN #3744700

Basin Fruitland Coal / Blanco Pictured Cliffs

790' FNL & 1535' FEL, Section 8, T-29-N, R-7-W, Rio Arriba County, NM Lat: N 36^ 44.73 / Long: 107^ 35.436 / API #30-039-25268

Today's Date: 7/19/04

Spud: 6/9/93 Completed: 8/5/93 Elevation: 3199' GL

12-1/2" hole

Nacimiento @ 420'


Ojo Alamo @ 2015'

Kirtland @ 2197'

Fruitland @ 2700'

Pictured Cliffs @ 3005'

7-7/8" Hole



TD 3194'

Circulated Cement to Surface

8-5/8" 24# K-55 Casing set @ 246' Cement with 277 cf (Circulated to Surface)

> Plug #3: 470' - Surface Type III cement, 35 sxs

Plug #2: 2247' - 1965' Type III cement, 23 sxs

Plug #1: 3136' - 2730' Type III cement, 62 sxs with 49 sxs below CR and 13 sxs above CR.

Set Cement Ret @ 2780'

DV Tool @ 2755'
Cement with 624 sxs (1036 cf)
Circulated 25 bbls cement to surface.

Fruitland Coal Perforations: 2830' – 2980'

Pictured Cliffs Perforations: 3003' - 3136'

4-1/2" 10.5# K-55 Casing set @ 3194'
Cement with 138 sxs (182 cf)
Circulated cement to surface before second stage.