Submit 3 Copies To Appropriate District Office	State of New Me	exico		Form C-103
District I	Energy, Minerals and Natu	ıral Resources		March 4, 2004
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.	020 24777
<u>District II</u> 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION	[5. Indicate Type	0-039-24777
District III	1220 South St. Fra	(u, to = = = u, r, r, s	STATE	X FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM &	WAR - 27H	6. State Oil & G	
1220 S. St. Francis Dr., Santa Fe, NM 87505	(so	AUG 2004		E-347-28
	CES AND REPORTS ON WELLS	1004 g	2. Lease N	ame or Unit Agreement
(DO NOT USE THIS FORM FOR PROPOS	ALC TO DRILL OR TO DEEDEN TO DE	HG BACK TO A	Name	
DIFFERENT RESERVOIR. USE "APPLIC PROPOSALS.)	ATION FOR PERMIT" (FORM (\$\frac{10}{2})) F	okżńch. TW	3	*
1. Type of Well:	V.	1.3		OSA UNIT
Oil Well Gas Well X	Other	50,000	8. Well Number	#334
		TO LOUGHT PARTY		π534
2. Name of Operator			9. OGRID Numb	
	RODUCTION COMPANY LLC		10 D 1	120782
3. Address of Operator	2, MS 37-2, TULSA, OK 74101		10. Pool name or	RUITLAND COAL
4. Well Location	2, NIS 37-2, TOLSA, OK 74101		DASIN III	KOTILAND COAL
4. Well Location			•	
Unit LetterA_:10	25feet from theNORTH_	line and790_fee	et from theE	AST_line
Section 32 Township			RRIBA County	T I 1005 H B X 10 H H M THE HELLER TY CENTRE OF THE TOWN OF THE ARCHIVE THE SAME THE TOWN OF THE ARCHIVE THE ARCHI
	11. Elevation (Show whether DR 6581)			
Pit or Below-grade Tank Application (For)	
Pit Location: ULSectTwp	Rng Pit type D	epth to Groundwater_	Distance from n	earest fresh water well
Distance from nearest surface water				i de la companya de
feet from theline and	·		,	
<u> </u>				
10. 61. 1. 4				
	ppropriate Box to Indicate N			
NOTICE OF IN	TENTION TO:	SUBS	SEQUENT RE	PORT OF:
	TENTION TO:	SUBS	SEQUENT RE	
NOTICE OF IN	TENTION TO:	SUBS	SEQUENT RE	PORT OF: ALTERING CASING PLUG AND
NOTICE OF IN PERFORM REMEDIAL WORK	TENTION TO: PLUG AND ABANDON CHANGE PLANS	SUBS REMEDIAL WORK COMMENCE DRIL	SEQUENT RE	PORT OF:
NOTICE OF IN	TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE	SUBS REMEDIAL WORK COMMENCE DRIL CASING TEST AN	SEQUENT RE	PORT OF: ALTERING CASING PLUG AND
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING	TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION	SUBS REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB	BEQUENT RE	PORT OF: ALTERING CASING PLUG AND
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER:	TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION	SUBS REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: Install do	BEQUENT RE LING OPNS. D D D D D D D D D D D D D	PORT OF: ALTERING CASING PLUG AND ABANDONMENT
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complete.	TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION eted operations. (Clearly state all	SUBS REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: Install depertment details, and	LING OPNS. D D D D D D D D D D D D D	PORT OF: ALTERING CASING PLUG AND ABANDONMENT es, including estimated date
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comples of starting any proposed work.	TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION	SUBS REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: Install depertment details, and	LING OPNS. D D D D D D D D D D D D D	PORT OF: ALTERING CASING PLUG AND ABANDONMENT es, including estimated date
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion.	TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION cted operations. (Clearly state all state) (Clearly SEE RULE 1103. For Multip	SUBS REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: Install do pertinent details, and le Completions: Atta	LING OPNS. D ownhole pump give pertinent dat ach wellbore diagr	PORT OF: ALTERING CASING PLUG AND ABANDONMENT es, including estimated date
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. 07-25-2004 MIRU, NDWH, NU BOP	TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION eted operations. (Clearly state all rk). SEE RULE 1103. For Multip, blow well down, unseat tbg hanger, hange	SUBS REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: Install do pertinent details, and le Completions: Atta	LING OPNS. D D D D D D D D D D D D D	PLUG AND ABANDONMENT es, including estimated date am of proposed completion
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or completion of starting any proposed work or recompletion. 07-25-2004 MIRU, NDWH, NU BOP	TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION eted operations. (Clearly state all rk). SEE RULE 1103. For Multip, blow well down, unseat tbg hanger, hange el and start air package. Blow air around u	SUBS REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: Install do pertinent details, and le Completions: Atta	LING OPNS. D ownhole pump give pertinent dat ach wellbore diagr //, SDFN.	PLUG AND ABANDONMENT es, including estimated date am of proposed completion
NOTICE OF IN' PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comple of starting any proposed work or recompletion. 07-25-2004 MIRU, NDWH, NU BOP 07-26-2004 Blow down well, RU swive running soap/wtr sweeps to get well cleen.	TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION eted operations. (Clearly state all rk). SEE RULE 1103. For Multip, blow well down, unseat tbg hanger, hange	SUBS REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: Install do pertinent details, and le Completions: Atta	D Downhole pump give pertinent dat ach wellbore diagray, SDFN. tagged up on the inserpu BHA, TIH w/ tbg, I	PLUG AND ABANDONMENT PLUG AND ABANDONMENT es, including estimated date am of proposed completion at 31' from the 1st, land tbg @ 3340.) ND
NOTICE OF IN' PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comple of starting any proposed worder or recompletion. 07-25-2004 MIRU, NDWH, NU BOP 07-26-2004 Blow down well, RU swive running soap/wtr sweeps to get well cleed BOP, NU new WH to accommodate roce.	TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION eted operations. (Clearly state all rk). SEE RULE 1103. For Multip blow well down, unseat tbg hanger, hange el and start air package. Blow air around u an, run air to get well dry. TOOH w/ tbg, t is. RIH w/ rods & downhole pump. Hook	SUBS REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: Install do pertinent details, and le Completions: Atta er is bad. TIH, tag fill, SW entil bottoms up. CO 1st jt, ally coming out of hole. I polish rod and well head	D. LING OPNS. D.	PLUG AND ABANDONMENT es, including estimated date am of proposed completion at 31' from the 1st jt, land tbg @ 3340' ND down hole pump.
NOTICE OF IN' PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comple of starting any proposed worder or recompletion. 07-25-2004 MIRU, NDWH, NU BOP 07-26-2004 Blow down well, RU swive running soap/wtr sweeps to get well cleed BOP, NU new WH to accommodate root. I hereby certify that the information a	TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION eted operations. (Clearly state all rk). SEE RULE 1103. For Multip blow well down, unseat tbg hanger, hange el and start air package. Blow air around u an, run air to get well dry. TOOH w/ tbg, t is. RIH w/ rods & downhole pump. Hook	SUBS REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: Install do pertinent details, and le Completions: Atta er is bad. TIH, tag fill, SW ntil bottoms up. CO 1st jt, ally coming out of hole. I polish rod and well head eest of my knowledge	D. LING OPNS. D.	PLUG AND ABANDONMENT PLUG AND ABANDONMENT es, including estimated date am of proposed completion at 31' from the 1st jt, land tbg @ 3340' ND down hole pump.
NOTICE OF IN' PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comple of starting any proposed worder or recompletion. 07-25-2004 MIRU, NDWH, NU BOP 07-26-2004 Blow down well, RU swive running soap/wtr sweeps to get well cleed BOP, NU new WH to accommodate roce.	TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION eted operations. (Clearly state all rk). SEE RULE 1103. For Multip blow well down, unseat tbg hanger, hange el and start air package. Blow air around u an, run air to get well dry. TOOH w/ tbg, the last RIH w/ rods & downhole pump. Hook blove is true and complete to the belosed according to NMOCD guidelines	SUBS REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: Install do pertinent details, and le Completions: Atta er is bad. TIH, tag fill, SW ntil bottoms up. CO 1st jt, ally coming out of hole. It polish rod and well head of est of my knowledge dest of my knowledge lageneral permit of	D. LING OPNS. D.	PLUG AND ABANDONMENT PLUG AND ABANDONMENT es, including estimated date am of proposed completion at 31' from the 1st jt, land tbg @ 3340' ND down hole pump.
NOTICE OF IN' PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comple of starting any proposed worder or recompletion. 07-25-2004 MIRU, NDWH, NU BOP 07-26-2004 Blow down well, RU swive running soap/wtr sweeps to get well cleed BOP, NU new WH to accommodate root. I hereby certify that the information a	TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION eted operations. (Clearly state all rk). SEE RULE 1103. For Multip blow well down, unseat tbg hanger, hange el and start air package. Blow air around u an, run air to get well dry. TOOH w/ tbg, the last RIH w/ rods & downhole pump. Hook blove is true and complete to the belosed according to NMOCD guidelines	SUBS REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: Install do pertinent details, and le Completions: Atta er is bad. TIH, tag fill, SW ntil bottoms up. CO 1st jt, ally coming out of hole. I polish rod and well head eest of my knowledge	D. LING OPNS. D.	PLUG AND ABANDONMENT PLUG AND ABANDONMENT es, including estimated date am of proposed completion at 31' from the 1st jt, land tbg @ 3340' ND down hole pump.
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or completion of starting any proposed work or recompletion. 07-25-2004 MIRU, NDWH, NU BOP 07-26-2004 Blow down well, RU swive running soap/wir sweeps to get well clear BOP, NU new WH to accommodate road grade tank has been/will be constructed or estimated to the supplementary of the supplementa	TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION eted operations. (Clearly state all rek). SEE RULE 1103. For Multiple, blow well down, unseat tbg hanger, hange el and start air package. Blow air around u an, run air to get well dry. TOOH w/ tbg, this. RIH w/ rods & downhole pump. Hook above is true and complete to the belosed according to NMOCD guidelines. TITLE	SUBS REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: Install do pertinent details, and le Completions: Atta er is bad. TIH, tag fill, SW ntil bottoms up. CO 1st jt, ally coming out of hole. It polish rod and well head of est of my knowledge at a general permit of Sr. Production Analy	D. LING OPNS. D. D. Downhole pump give pertinent dat ach wellbore diagram, SDFN. Dequipment up. Set the and belief. I further an (attached) alternation of the set of	PLUG AND ABANDONMENT PLUG AND ABANDONMENT es, including estimated date ram of proposed completion at 31' from the 1st, land tbg @ 3340'.) ND down hole pump. er certify that any pit or belownative OCD-approved plan 1
NOTICE OF IN' PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comple of starting any proposed worder or recompletion. 07-25-2004 MIRU, NDWH, NU BOP 07-26-2004 Blow down well, RU swive running soap/wtr sweeps to get well cleed BOP, NU new WH to accommodate root. I hereby certify that the information a	TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION eted operations. (Clearly state all rek). SEE RULE 1103. For Multiple, blow well down, unseat tbg hanger, hange el and start air package. Blow air around u an, run air to get well dry. TOOH w/ tbg, this. RIH w/ rods & downhole pump. Hook above is true and complete to the belosed according to NMOCD guidelines. TITLE	SUBS REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: Install do pertinent details, and le Completions: Atta er is bad. TIH, tag fill, SW ntil bottoms up. CO 1st jt, ally coming out of hole. It polish rod and well head of est of my knowledge dest of my knowledge lageneral permit of	D. LING OPNS. D. D. Downhole pump give pertinent dat ach wellbore diagram, SDFN. Dequipment up. Set the and belief. I further an (attached) alternation of the set of	PLUG AND ABANDONMENT PLUG AND ABANDONMENT es, including estimated date am of proposed completion at 31' from the 1st, t, land tbg @ 3340', ND down hole pump. er certify that any pit or belownative OCD-approved plan
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON TEMPORARILY	TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION eted operations. (Clearly state all rek). SEE RULE 1103. For Multiple, blow well down, unseat tbg hanger, hange el and start air package. Blow air around u an, run air to get well dry. TOOH w/ tbg, this. RIH w/ rods & downhole pump. Hook above is true and complete to the belosed according to NMOCD guidelines. TITLE	SUBS REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: Install do pertinent details, and le Completions: Atta er is bad. TIH, tag fill, SW ntil bottoms up. CO 1st jt, ally coming out of hole. It polish rod and well head of est of my knowledge at a general permit of Sr. Production Analy	D. LING OPNS. D. D. Downhole pump give pertinent dat ach wellbore diagram, SDFN. Dequipment up. Set the and belief. I further an (attached) alternation of the set of	PLUG AND ABANDONMENT PLUG AND ABANDONMENT es, including estimated date ram of proposed completion at 31' from the 1st, land tbg @ 3340'.) ND down hole pump. er certify that any pit or belownative OCD-approved plan 1
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or completion of starting any proposed work or recompletion. 07-25-2004 MIRU, NDWH, NU BOP 07-26-2004 Blow down well, RU swive running soap/wir sweeps to get well clear BOP, NU new WH to accommodate road grade tank has been/will be constructed or estimated to the supplementary of the supplementa	TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION eted operations. (Clearly state all rek). SEE RULE 1103. For Multiple, blow well down, unseat tbg hanger, hange el and start air package. Blow air around u an, run air to get well dry. TOOH w/ tbg, this. RIH w/ rods & downhole pump. Hook above is true and complete to the belosed according to NMOCD guidelines. TITLE	SUBS REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: Install do pertinent details, and le Completions: Atta er is bad. TIH, tag fill, SW ntil bottoms up. CO 1st jt, ally coming out of hole. It polish rod and well head of est of my knowledge at a general permit of Sr. Production Analy	D. LING OPNS. D. D. Downhole pump give pertinent dat ach wellbore diagram, SDFN. Dequipment up. Set the and belief. I further an (attached) alternation of the set of	PLUG AND ABANDONMENT PLUG AND ABANDONMENT es, including estimated date ram of proposed completion at 31' from the 1st, land tbg @ 3340'.) ND down hole pump. er certify that any pit or belownative OCD-approved plan 1
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON TEMPORARILY	TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION eted operations. (Clearly state all rek). SEE RULE 1103. For Multiple, blow well down, unseat tbg hanger, hange el and start air package. Blow air around u an, run air to get well dry. TOOH w/ tbg, this. RIH w/ rods & downhole pump. Hook above is true and complete to the belosed according to NMOCD guidelines. TITLE	SUBS REMEDIAL WORK COMMENCE DRIL CASING TEST AN CEMENT JOB OTHER: Install do pertinent details, and le Completions: Atta er is bad. TIH, tag fill, SW ntil bottoms up. CO 1st jt, ally coming out of hole. It polish rod and well head of est of my knowledge at a general permit of Sr. Production Analy	D. LING OPNS. D. D. Downhole pump give pertinent date ach wellbore diagram, SDFN. tagged up on the inserved BHA, TIH w/ tbg, I equipment up. Set the and belief. I further an (attached) alternation of the set	PLUG AND ABANDONMENT PLUG AND ABANDONMENT es, including estimated date ram of proposed completion at 31' from the 1st, land tbg @ 3340'.) ND down hole pump. er certify that any pit or belownative OCD-approved plan 1