	PN
Submit 3 Copies To Appropriate District Office District I 1025 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 87210 State of New Me. Energy, Minerals and Natur CONSERVATION	Revised March 25, 1999 WELL API NO. DIVISION 30-031-07028
District III 1000 Rio Brazos Rd., Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505	ncis Dr. State Person
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLU DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FO PROPOSALS.) 1. Type of Well:	R SUCH
Oil Well Gas Well (Other) WIW	HOSPAH SAND UNIT
3. Address of Operator P. U. Box 1680, Hot.	9. Pool name or Wildcat
4. Well Location Unit Letter <u>L</u> : 999 feet from the <u>3007</u>	14 line and 999 feet from the East line
Section 36 Township / 3N Range 9W NMPM MCC, County 10. Elevation (Show whether DR, RKB, RT, GR, etc.)	
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON	REMEDIAL WORK ALTERING CASING
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND
COMPLETION OTHER:	CEMENT JOB OTHER:
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.	
PLEASE SEE ATTO	ch mest
1-27-43	
I hereby certify that the information above is true and complete to the SIGNATURE TITLE	best of my knowledge and belief. Blesident DATE 8/11/63
Type or print name	Telephone No.
// W - V(/#	TUTY OIL & GAS INSPECTOR, DIST. #8 AUG 3 1 2004
APPPROVED BY /f. Williams TITLE Conditions of approval, if any:	DATEDATE

HOSPAH SAND UNIT WELL 62

30-031-07028 SEC.36,T18N,R9W KCKINLEY, NEW MEXICO

8/27/02	MIRU WORK OVER RIG AND PLUGGING EQUIPMENT, CONDUCT SAFETY MEETING, POOH AND LAY DOWN TBG AND PKR., PU AND TIH W/ 2 7/8" TBG, SECURE WELL, SDFN
8/28/02	CREW TO LOCATION CONDUCT SAFETY MEETING, BEGIN WASHING OUT FILL TO 1690', (PERFS@ 1666'-1685'), SECURE WELL, SDFN
8/29/02	CREW TO LOCATION, CONDUCT SAFETY MEETING, BREAK CIRCULATION, CIRCULATE HOLE CLEAN, MIX AND PUMP 53 SXS CLASS "B" CMT @ 15.8 PPG, SPOT BALANCED PLUG @ 1000' TO 1685', POOH W/ TBG, WASH EQUIPMENT, SECURE WELL, SDFN (MR. BRUCE MARTIN)
8/30/02	CREW TO LOCATION, CONDUCT SAFETY MEETING, MIRU WIRE LINE TRUCK, TIH W/ WIRELINE TAG TOC @ 1116', ATTEMPT TO FREE POINT PIPE HAD TROUBLE DETERMING FREE POINT, PERF 2 SPF @ 500', SET RETAINER @ 473', PERF 2 SPF @ 141, POOH RIG DN AND RLS WIRELINE TRUCK. (MR. BRUCE MARTIN)
9/4/02	CRE W TO LOCATION, CONDUCT SAFETY MEETING, TIH W/ 2 7/8" TBG AND STING INTO RETAINER @ 473', MIX AND PUMP 41 SXS BELOW RETAINER AND 15.5 SXS ON TOP OF RETAINER @ 15.7 PPG, POOH W/TBG, MIX AND PUMP 154 SXS CLASS "B" @ 15.7 PPG DOWN CASING INTO PERFS @ 141' NO CIRCULATION OUT BRADEN HEAD, CLEARED PERFS @ 141' W/WATER, SECURE WELL, SDFN (MR. BRUCE MARTIN)
9/5/02	CREW TO LOCATION, CONDUCT SAFETY MEETING, MIX AND PUMP LCM TO AID IN CIRCULATION, MIX AND PUMP 160 SXS CLASS "B" CMT @ 15.7 PPG, NO CIRCULATION, SECURE WELL, SDFN (MR. BRUCE MARTIN)
9/6/02	CREW TO LOCATION, CONDUCT SAFETY MEETING, MIX AND PUMP LCM TO AID IN CIRCULATION, MIX AND PUMP 160 SXS CLASS "B" CMT @ 15.7 PPG, NO CIRCULATION, SECURE WELL, RIG DN EQUIPMENT (MR. BRUCE MARTIN)
	NO ACTIVITY PENDING EVALUATION OF WELL
1/21/03	MIRU PLUGGING EQUIPMENT, CONDUCT SAFETY MEETING, MIX AND PUMPED 100 SXS CLASS "B" CMT @ 15.7 PPG, @ 400 PSI WITH PRESSURE INCREASING TO 1200 PSI, CHECK FLOW BACK (NONE) WELL DID NOT CIRCLE ATE, ELUSIED TO 002, SECURE WELL SOFT!

CIRCULATE, FLUSHED TO 90', SECURE WELL SDFN (MR. HENRY VILLANUEA)

1/22/03

CREW TO LOCATION, TAG TOC @ 93', W/ WIRE LINE TRUCK, PERF @ 56', RIG DN WIRELINE TRUCK, ATTEMPT TO PUMP INTO PERFS @ 56' @ 1100 PSI COULD NOT, TIH W/ THREE JTS TBG TO 93', MIX AND PUMP 56 SXS CLASS "B" CMT @ 15.7 PPG, WITH GOOD SLURRY TO PIT, POOH W/ TBG, TOP OFF CASING, HOLE STABLE, WELL NOW PLUGGED, RIG DN AND MOVE ALL EQUIPMENT.

(MR. HENRY VILLANUEVA)

CLEAN LOCATION INSTALL P&A MARKER