

PN

to Appropriate
District Office

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.

30-031-20610

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☐

GAS
WELL ☐

OTHER ☒ WEW

2. Name of Operator

CEED OPERATING, INC.

3. Address of Operator

P.O. Box 1680, Hobbs, NM 88241

4. Well Location

Unit Letter K : 2460 Feet From The WEST Line and 1790 Feet From The SOUTH Line

Section

36

Township

18N

Range

9W

NMPM

McKinley

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

7077' GL

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Please SEE Attachment



6-30-03

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Donnie Hill

TITLE

President

DATE

7/1/03

TYPE OR PRINT NAME

Donnie Hill

505-397-3972

TELEPHONE NO.

(This space for State Use)

APPROVED BY

H. Villanueva

TITLE

DEPUTY OIL & GAS INSPECTOR, DIST. 3

DATE

AUG 31 2004

CONDITIONS OF APPROVAL, IF ANY:

8-31-04

HOSPAH SAND UNIT 91
30-031-20610
SEC.36,T18N,R9W
MCKINLEY,NM

6/23/03

MIRU PLUGGING EQUIPMENT, CONDUCT SAFETY MEETING, RLS PKR, POOH W/TBG AND PKR, PU AND TIH W/ 2 7/8" TBG TO 1729' (PERFS @ 1709'-1724') SECURE WELL, SDFN

6/24/03

CREW TO LOCATION, CONDUCT SAFETY MEETING, RIG UP PUMP, CIRCULATE HOLE CLEAN, MIX AND PUMP 60 SXS. CLASS "B" CMT @ 16.0 # PPG, (70.8 CUBIC FEET) SPOT BALANCED PLUG @ 1342' TO 1729', POOH W/ TBG, SECURE WELL, SD, WOC (BRUCE MARTIN)

6/25/03

CREW TO LOCATION, CONDUCT SAFETY MEETING, MIRU WIRELINE TRUCK TAG TOC @ 1273', POOH, PU AND TIH, CUT CASING @ 557', RIG DOWN AND RLS WIRELINE, POOH AND LAY DOWN 5 1/2" CSG, SECURE WELL SDFN (BRUCE MARTIN)

6/26/03

CREW TO LOCATION, CONDUCT SAFETY MEETING, PU AND TIH W/ 2 7/8" TBG. TO TIH W/ 2 7/8" TBG TO 607', (50' INSIDE CSG STUB) PREPARE TO CIRCULATE HOLE CLEAN, SDFN

6/27/03

CREW TO LOCATION, CONDUCT SAFETY MEETING, BREAK CIRCULATION, CIRCULATE HOLE CLEAN, MIX AND PUMP 65 SXS CLASS "B" CEMENT (76.70 CUBIC FEET) @ 15.8 PPG, SPOT BALANCED PLUG @ 607' TO 353', POOH W/TBG, SECURE WELL, SDFN

6/30/03

CREW TO LOCATION, CONDUCT SAFETY MEETING, TIH W/ TBG, TAG TOC @ 305', POOH TO 92', CIRCULATE HOLE CLEAN, MIX AND PUMP 50 SXS CLASS "B" CEMENT (59 CUBIC FEET) @ 16.3# PPG, GOOD SLURRY TO PIT, POOH W/ TBG, TOP OFF CSG, CLEAN LOCATION, RIG DOWN PLUGGING EQUIPMENT, INSTALL P&A MARKER, WELL PLUGGED