w			PN
to Appropriate District Office	MINEJ, IIII in the more a real		Accordance a a sugar
DISTRICT I P.O. Box 1980, Hobbs, NM 88240			WELL API NO.
DISTRICT II P.O. Drawer DD, Artesia, NM 88210  DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410			3 0 - 031 - d 0/6/2  5. Indicate Type of Lease
			6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lesse Name or Unit Agreement Name
1. Type of Well: OIL GAS WELL WELL	OTHER	WZW	HOSPAH Sand Unit
2. Name of Operator  BCED	sperating, Z		8. Well No.
3. Address of Operator  P. G. Bay	1680 Habbs	nm 88241	9. Pool same or Wildcat    JosPAA UPPER Sand
4. Well Locution Unit Letter 7:23	90 Feet From The 5007	H Line and 14	9. Pool name or Wildcat    Jospan UPPER Sand  75   Feet From The East   Line
Section 36		<b>~</b> .	NMPM M CKINGED County
	10. Elevation (Show t	whether DF, RKB, RT, GR, etc.)	
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
NOTICE OF IN	TENTION TO:	SUE	SSEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	G OPNS. DPLUG AND ABANDONMENT 🗗
PULL OR ALTER CASING		CASING TEST AND C	EMENT JOB
OTHER:		OTHER:	D
12. Describe Proposed or Completed Oper work) SEE RULE 1103.	ntions (Clearly state all pertinent de	tails, and give pertinent dates, inclu	ding estimated date of starting any proposed
PLease SE	E ATTACHM		
	- ////4///	(6)	5789m
		E.	JUL 2003 🖹
		OIL	CONS. DIV.
			DIST. 3
6-30-03			20 Calendary
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNATURE MORNIE		_ me Parsident	
TYPE OR PRINT NAME OGON	E HILL		575-397-3972 TELEPHONE NO.
(This space for State Use)		OFFUTY OIL & GAS INCOM	CTOR, EUST. 🔊 AUG 3 1 2804
ADDROGNED BY H. Villan	ma a	TIRE	
CONDITIONS OF APPROVAL IF ANY	31-04		

## HOSPAH SAND UNIT 90 30-031-20612 SEC.36,T18N,R9W MCKINLEY,NM

6/23/03

MIRU PLUGGING EQUIPMENT, CONDUCT SAFETY MEETING, RLS PKR, POOH W/TBG,SDFN

6/24/03

CREW TO LOCATION, CONDUCT SAFETY MEETING, TIH W/ 2 7/8" TBG TO 1790.42' (PERFS @ 1780'-1795') RIG UP PUMP CIRCULATE HOLE CLEAN, MIX AND PUMP 60 SXS. CLASS "B" CMT @ 16.1 # PPG, (70.8 CUBIC FEET) SPOT BALANCED PLUG @ 1424' TO 1790', POOH W/ TBG SECURE WELL, SDFN, WOC (BRUCE MARTIN)

6/25/03

CREW TO LOCATION, CONDUCT SAFETY MEETING, MIRU WIRELINE TRUCK TAG TOC @ 1250', POOH, PU AND TIH, CUT CASING @ 598', SDFN (BRUCE MARTIN)

6/26/03

CREW TO LOCATION, CONDUCT SAFETY MEETING, POOH W/ 5 ½" CSG, TIH W/ 2 7/8" TBG TO 650', (52' INSIDE CSG STUB) PREPARE TO CIRCULATE HOLE CLEAN, SDFN

6/27/03

CREW TO LOCATION, CONDUCT SAFETY MEETING, BREAK CIRCULATION, CIRCULATE HOLE CLEAN, MIX AND PUMP 95 SXS CLASS "B" CEMENT (112.10 CUBIC FEET) @ 16.0 PPG, SPOT BALANCED PLUG @ 650' TO 343', POOH W/TBG, SECURE WELL, SDFN (BRUCE MARTIN)

6/30/03

CREW TO LOCATION, CONDUCT SAFETY MEETING, TIH W/ TBG, TAG TOC @ 248', POOH TO 92', CIRCULATE HOLE CLEAN, MIX AND PUMP 50 SXS CLASS "B" CEMENT (59 CUBIC FEET) @ 16.2# PPG, GOOD SLURRY TO PIT, POOH W/ TBG, TOP OFF CSG, CLEAN LOCATION, RIG DOWN PLUGGING EQUIPMENT, INSTALL P&A MARKER, WELL PLUGGED (BRUCE MARTIN)