Form 3160-5 (April 2004)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
OM B No. 1004-0137
Expires: March 31, 2007

5 Lease Serial No.

OUNDBY	NOTIOES AND DE	2022		_	J. Lease 5	-603-2199	
SUNDRY NOTICES AND REPORTS ON WELLS  Do not use this form for proposals to drill or to re-enter an					6. If Indian, Allottee or Tribe Name		
abandoned we	ell. Use Form 3160-3 (a	APD) for su	o re-ent ch propo	er an osais.		jo Nation	
SUBMIT IN TRIPLICATE- Other instructions of				reverse side.		7. If Unit or CA/Agreement, Name and/or No.  NW Cha Cha Unit	
1. Type of Well Oil Well ✓ Gas Well Other						Name and No.	
Name of Operator Richardson C	Operating Company				NW	Cha Cha Unit #32	
		21. M XI	C -1 1	2 \	9. API V	weii No. <b>45-29121</b>	
3a. Address 3100 La Plata Highway, Farmington, NM, 87401 505-564-			1 1			10. Field and Pool, or Exploratory Area Cha Cha Gallup  11. County or Parish, State	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 849' FSL, 682' FWL, Sec. 22, T29N, R14W					Cha		
					11. Coun		
			., .,, .	· · · · · · · · · · · · · · · · · · ·		Juan County, New Mexico	
12. CHECK AF	PPROPRIATE BOX(ES) TO	INDICATE 1	NATURE	OF NOTICE,	REPORT, (	OR OTHER DATA	
TYPE OF SUBMISSION			ТҮРЕ	OF ACTION	·		
7	Acidize	Deepen		Production	(Start/Resume)	Water Shut-Off	
Notice of Intent	Alter Casing	Fracture Tre		Reclamatio		Well Integrity	
Subsequent Report	Casing Repair	New Const	-	Recomplete		Other	
Final Abandonment Notice	Change Plans	Plug and Al	eandon L r		y Abandon		
	Convert to Injection	Plug Back	L	Water Disp	osai		
Attach the Bond under which the following completion of the investing has been completed. Fit determined that the site is ready	ectionally or recomplete horizontall he work will be performed or provi volved operations. If the operation nal Abandonment Notices shall be y for final inspection.)	ly, give subsurfac ide the Bond No. results in a multi filed only after a	e locations a on file with ple completi I requiremen	and measured and BLM/BIA. Resion or recomple- ints, including re-	nd true vertical de equired subsequen- tion in a new inte- clamation, have b	work and approximate untactor accepts the original pertinent markers and zones. at reports shall be filed within 30 days rval, a Form 3160-4 shall be filed once been completed, and the operator has	
If the proposal is to deepen dire Attach the Bond under which the following completion of the invitesting has been completed. Fit determined that the site is ready The subject well was test at  1. Pulled and laid down re 2. TIH with csg scraper to 3. TIH with pkr, set pkr as 4. TIH with pkr and 2-3/8	ectionally or recomplete horizontall he work will be performed or provivolved operations. If the operation hal Abandonment Notices shall be of final inspection.)  according to the following propods and pump.  5 5070', POOH.  at 5066' and test to 500psi, held the state of the st	ly, give subsurfactide the Bond No. I results in a multifiled only after a second results and is second results and is do OK. TOH work of the control of the	e locations a on file with ple completi il requirement being conv lth pkr. aeld OK.	and measured and BLM/BIA. Reform or recompletents, including referred to a Wi	nd true vertical de equired subsequen- tion in a new inte- clamation, have b	pths of all pertinent markers and zones. at reports shall be filed within 30 days rval, a Form 3160-4 shall be filed once	
If the proposal is to deepen dire Attach the Bond under which the following completion of the invitesting has been completed. Fit determined that the site is ready The subject well was test at  1. Pulled and laid down re 2. TIH with esg scraper to 3. TIH with pkr, set pkr at 4. TIH with pkr, set pkr at 5. MIT conducted on 8/11 Application to convert to very	ectionally or recomplete horizontall he work will be performed or provivolved operations. If the operation hal Abandonment Notices shall be of for final inspection.)  according to the following proposed and pump.  5 5070', POOH.  at 5066' and test to 500psi, held be of the following proposed and test to 500psi, held by the following proposed and test to 500psi,	ly, give subsurfactide the Bond No. I results in a multifiled only after a second results and is second results and is do OK. TOH work of the control of the	e locations a on file with ple completi I requirement being conv ith pkr. actin of the	and measured at a BLM/BIA. Reform or recompletes, including reverted to a William or NMOCD.	nd true vertical de equired subsequen- tion in a new inte- clamation, have b	pths of all pertinent markers and zones. In reports shall be filed within 30 days rval, a Form 3160-4 shall be filed once been completed, and the operator has	
If the proposal is to deepen dire Attach the Bond under which the following completion of the invitesting has been completed. Fit determined that the site is ready The subject well was test at  1. Pulled and laid down re 2. TIH with esg scraper to 3. TIH with pkr, set pkr at 4. TIH with pkr, set pkr at 5. MIT conducted on 8/11 Application to convert to well as the set of	ectionally or recomplete horizontall he work will be performed or provivolved operations. If the operation hal Abandonment Notices shall be a for final inspection.)  according to the following provided and pump.  10 5070', POOH.  11 5066' and test to 500psi, held to 500psi, held to 500psi, held to 500psi.  WIW is in process.  WIW is in process.	ly, give subsurfactide the Bond No. I results in a multifiled only after a ceedure and is ceedure and is do OK. TOH w. csg to 500psi, ly Mr. Bruce M	e locations a on file with ple completi I requirement being converted by the converted being converted by the converted by th	and measured at BLM/BIA. Recommendation or recomplete. Its, including recently to a William of the NMOCD.	rations Manage	pths of all pertinent markers and zones. In reports shall be filed within 30 days rval, a Form 3160-4 shall be filed once been completed, and the operator has	
If the proposal is to deepen dire Attach the Bond under which the following completion of the investing has been completed. Fit determined that the site is ready The subject well was test at 1. Pulled and laid down re 2. TIH with esg scraper to 3. TIH with pkr, set pkr at 4. TIH with pkr, set pkr at 4. TIH with pkr and 2-3/8 5. MIT conducted on 8/11 Application to convert to 5  I hereby certify that the fore Name (Printed/Typed) Charles H. William	ectionally or recomplete horizontall he work will be performed or provivolved operations. If the operation hal Abandonment Notices shall be a for final inspection.)  according to the following provides and pump.  10 5070', POOH.  11 5066' and test to 500psi, held to 500psi, held to 500psi.  12 they will be a seen at 5077'. Test 1/04, test passed. Witnessed by WIW is in process.	ly, give subsurfactide the Bond No. I results in a multifiled only after a ceedure and is ceedure and is do OK. TOH w. csg to 500psi, ly Mr. Bruce M	e locations a on file with ple completi I requirement being converted by the converted being converted by the converted by th	and measured at BLM/BIA. Recommendation or recomplete. Its, including recently to a William of the NMOCD.	rations Manage	pths of all pertinent markers and zones. In reports shall be filed within 30 days rval, a Form 3160-4 shall be filed once been completed, and the operator has	
If the proposal is to deepen dire Attach the Bond under which the following completion of the invitesting has been completed. Fit determined that the site is ready The subject well was test at  1. Pulled and laid down re 2. Till with egg scraper to 3. Till with pkr, set pkr at 4. Till with pkr and 2-3/8 5. MIT conducted on 8/11 Application to convert to value of the pkr and 2-3/8 I hereby certify that the fore Name (Printed/Typed) Charles H. Williams	ectionally or recomplete horizontall he work will be performed or provivolved operations. If the operation hal Abandonment Notices shall be a for final inspection.)  according to the following provided and pump.  10 5070', POOH.  11 5066' and test to 500psi, held to 500psi, held to 500psi, held to 500psi.  WIW is in process.  WIW is in process.	ly, give subsurfactide the Bond No. I results in a multifiled only after a ceedure and is ceedure and is do OK. TOH w. csg to 500psi, ly Mr. Bruce M	e locations a on file with ple completi I requirement being converted by the converted being converted by the converted by th	and measured at BLM/BIA. Reform or recomplements, including reverted to a William Process of the NMOCD.	rations Manage	pths of all pertinent markers and zones. In reports shall be filed within 30 days rval, a Form 3160-4 shall be filed once been completed, and the operator has	

OCT 0 5 2004

