

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE\*  
(Other instructions on reverse side)

Form approved.  
Budget Bureau No. 42-R1424

5. LEASE DESIGNATION AND SERIAL NO.

Contract #103

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

Jicarilla Apache

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Jicarilla "H"

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

Tapacito Pictured Cliffs

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 17, T-26-N, R-4-W

N.M.P.M.

12. COUNTY OR PARISH

Rio Arriba

13. STATE

New Mexico

1.

OIL WELL  GAS WELL  OTHER

2. NAME OF OPERATOR

Southern Union Production Company

3. ADDRESS OF OPERATOR

P.O. Box 808, Farmington, New Mexico 87401

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\* See also space 17 below.)  
At surface

1650 Feet from the North line and 1650 feet from the East line

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

6771 DF

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

1. Moved in and rigged up L & M Ventures pulling unit.
2. Ran 2-3/8" tbg. to T.D. 3489 feet, spotted 15 sacks cement 3489' to 3350'.
3. Pulled 2-3/8" tubing.
4. Rigged up & pulled 125,000# on 4-1/2" casing.
5. Ran csg. shot & shot 4-1/2" csg. off @ 1894 ft., pulled 25 jts. 4-1/2" casing.
6. Ran 2-3/8" tubing to 1944 ft., spot 21 sks. cement 1944 ft. to 1844 ft.
7. Pulled tbg. to 225 ft., spot 20 sks cement 225 ft. to 175 ft.
8. Pulled tbg. to 24 ft., spot 10 sks. cement plug to surface.
9. Set dry hole marker, restored location.
10. Will reseed location in spring of 1977.



18. I hereby certify that the above is true and correct

SIGNED James N. Bonaventura  
James N. Bonaventura

TITLE Production Superintendent

DATE 12/1/76

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

TITLE \_\_\_\_\_

DATE \_\_\_\_\_

\*See Instructions on Reverse Side

St