Form & 160-5 (August 1999)

UNITED STATES DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS

FORM APPROVED
OMB NO. 1004-0135
Expires: November 30, 2000

5.	Lease	Serial	No.

5.	Lease	Serial	No
	FFF		

COMBILLIA	OTIOLO AND INLI ONTO ON WILLES	
Do not use this	form for proposals to drill or to re-enter an	
	Use form 3160-3 (APD) for such proposals.	

6.	If Indian,	Allottee	OT	Tribe	Name	

SUBMIT IN TRIF	PLICATE - Other in:	structions on reverse side.	7. If Unit of CA/Agreement, Name and/or No. NMNM89400
1. Type of Well			8. Well Name and No.
☐ Oil Well ☐ Gas Well ☐ Othe	er		KUTZ 29-9-19 # 1
2. Name of Operator	Cont		9. API Well No.
ENERGÉN RESOURCES COI	RPORATION	E-Mail: VDONAGHE@ENERGEN.COM	30-045-28845-00-S1
3a. Address 2198 BLOOMFIELD HIGHWA	·	3b. Phone No. (include area code) Ph: 505-325-6800	10. Field and Pool, or Exploratory BASIN FRUITLAND COAL
FARMINGTON, NM 87401	'	F11. 303-323-0000	BASIN FROITLAND COAL
4. Location of Well (Footage, Sec., T.	, R., M., or Survey Desc	ription)	11. County or Parish, and State
Sec 19 T29N R9W SWNE 250	0FNL 1505FEL		SAN JUAN COUNTY, NM
36.71135 N Lat, 107.81505 W			5, 11, 55, 11, 555, 11, 11, 11, 11, 11,
12. CHECK APPR	OPRIATE BOX(ES	S) TO INDICATE NATURE OF NOTICE,	REPORT, OR OTHER DATA
		· · · · · · · · · · · · · · · · · · ·	
TABLE OF GUIDAUGGIONI I		TUDE OF ACTION	

TYPE OF SUBMISSION	TYPE OF ACTION			
Notice of Intent ☐ Subsequent Report ☐ Final Abandonment Notice	☐ Acidize ☐ Alter Casing ☐ Casing Repair ☐ Change Plans ☐ Convert to Injection	☐ Deepen ☐ Fracture Treat ☐ New Construction ☐ Plug and Abandon ☐ Plug Back	Production (Start/Resume) Reclamation Recomplete Temporarily Abandon Water Disposal	□ Water Shut-Off □ Well Integrity □ Other

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

We suspect that this well has a casing leak. We plan to isolate and repair the leak as follows:

- 1. MIRU. ND Wellhead. NU BOP.
- 2. TOH with 2-3/8" tubing.
 3. Pick up and TIH with 5 ?? RBP and set @ 1800?. Test plug to 500 psi. Dump sand on top of plug.
- 4. TIH w/5 ?? packer to isolate casing leak. Cement will be determined after injection rate.
- 5. Squeeze casing leak.
- 6. Drill out cement and test casing to 500 psi. CONDITIONS OF APPROVAL

Adhere to previously issued stipulations.

For ENERGEN RESOURCES CORF	by the BLM Well Information System ORATION, sent to the Farmington HEW HALBERT on 01/05/2005 (05MXH0278SE)
Name (Printed/Typed) CHARLIE DONAHUE	Title DISTRICT ENGINEER
Signature (Electronic Submission)	Date 12/20/2004
THIS SPACE FOR FEDERA	AL OR STATE OFFICE ASCEPTED FOR RECORD
Approved By	Title JAN 1 1 2005 Date
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	Office FARMINGTON FIELD OFFICE

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Additional data for EC transaction #52083 that would not fit on the form

- 32. Additional remarks, continued
- 7. TOH with RBP.

- 8. TIH with 2-3/8? production string and clean out to PBTD. Land tubing.
- 9. ND BOP. NU wellhead. Return to production.