Form 3160-5 (August 1999)

UNITED STATES DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT

NMNM03549

OMB NO. 1004-0135 Expires: November 30, 2
Lease Serial No.

SUNDKIN	OTICES AND KEPOKTS ON MELLS	
Do not use this	form for proposals to drill or to re-enter a	n
abandoned well.	Use form 3160-3 (APD) for such proposa	ls.

6. If Indian, Allottee or Tribe Name
7. If Unit or CA/Agreement, Name and/or No.
8. Well Name and No. FLORANCE C LS 5
9. API Well No. 30-045-07167-00-D1

FORM APPROVED

2000

SUBMIT IN TRIPLICATE - Other instructions on reverse side. Type of Well Oil Well Gas Well Other Name of Operator MARY CORLEY Contact: BP AMERICA PRODUCTION CO E-Mail: corleyml@bp.com 3a. Address 3b. Phone No. (include area code) Ph: 281.366.4491 Field and Pool, or Exploratory P. O. BOX 3092 BLANCO MESAVERDE BLANCO PICTURED CLIFFS Fx: 281.366.0700 HOUSTON, TX 77253 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 11. County or Parish, and State Sec 30 T28N R8W SENE 1735FNL 0890FEL SAN JUAN COUNTY, NM 36.63480 N Lat, 107.71568 W Lon 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION □ Acidize Deepen ☐ Production (Start/Resume) ☐ Water Shut-Off Notice of Intent ☐ Alter Casing ☐ Fracture Treat ☐ Reclamation ☐ Well Integrity ☐ Subsequent Report Other
Subsurface Commingl Casing Repair □ New Construction Recomplete Final Abandonment Notice ☐ Change Plans ☐ Plug and Abandon ☐ Temporarily Abandon Convert to Injection □ Plug Back ■ Water Disposal 13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) determined that the site is ready for final inspection.) BP America Production Company request permission to convert the subject well from a dual string completion to a single string completion, add pay in the Mesaverde and commingle production downhole from the Blanco Pictured Cliffs & Blanco Mesaverde Pools as per the attached procedure. The Blanco Pictured Cliffs (72359)& the Blanco Mesaverde (72319) Pools are Pre-Approved Pools for Downhole Commingling per NMOCD order R-11363. The working, overriding, and royalty interest owners in the proposed commingled pools are identical, therefore, no notification of this application need be submitted via certified mail. Production is proposed to be allocated based on actual production from both the Pictured Cliffs and Mesaverde Pools as reflected on the attached procedure. 14. I hereby certify that the foregoing is true and correct Electronic Submission #20884 verified by the BLM Well Information System
For BP AMERICA PRODUCTION CO, sent to the Farmington
Committed to AFMSS for processing by Matthew Halbert on 04/28/2003 (03MXH0740SE) Name (Printed/Typed) MARY CORLEY **AUTHORIZED REPRESENTATIVE** CONDITIONS OF APPROVAL re to previously is their stipulations. 04/22/2003 THIS SPACE FOR FEDERAL OR STATE OFFICE USE /s/ Jim Lovato Approved By APR 30 2003 Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Florance C LS 005 PC/MV

Sec 30, T28N, R8W API# 3004507167


- 1. Check anchors. MIRU workover rig.
- 2. Blow down well. Kill with 2% KCL water ONLY if necessary. ND WH and NU BOP's.
- 3. Tag for fill and TOH with 1-1/4" short string set at 2309'. LD production tbg.
- 4. TOH with 2-3/8" long string set at 4639'.
- 5. Mill 5 1/2" production packer set at 2351'.
- 6. Clean out to PBTD.
- 7. RIH and set CIBP at 4400'. Test casing to 2500 psi.
- 8. RIH w/ GR log.
- 9. RIH with 3-1/8" casing guns 1 SPF 120 deg phasing with Schlumberger's Prospector, select-fire charge. Perforate Menefee (correlate to GR log).
- 10. RU frac equipment. Use 2% KCL-N2 foam in fracture stimulation.
- 11. Frac Menefee according to pump schedule.
- 12. Flowback frac fluid immediately.
- 13. POH with frac string.
- 14. RIH with work string and bit. Drill out CIBP set at 4400'. Continue clean out hole to PBTD at 4744'. Blow well dry with air package at PBTD. POH with work string.
- 15. Rabbit tubing and RIH with 2-3/8" production tubing (with X-nipple and plug on bottom). Replace any joints that fail the pressure test.
- 16. Land 2-3/8" production tubing at 4670'.
- 17. Swab water from tubing with the sandline.
- 18. RU slickline unit. Run gauge ring for 2-3/8" tubing. Pull plug. RD slickline unit.
- 19. ND BOP's. NU WH. Test well for air. Return well to production.

Allocation Based	on Year 20	02 Production		
Pool	Oil	%	Gas	%
Pictured Cliffs	0	0%	2486	49% 8/
Mesaverde	94	100%	28387	94% 3

MARY CORLEY, BT AMERICA FRONT, AGREED WITH ME
THE GAS A/OCATION RATE SHOULD BE 8% & 92%.
4-28-03

Florance C LS 005 PC/MV

API# 3004507167 Sec 30, T28N, R8W



updated: 01/07/03 az