

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division

Sundry Notices and Reports on Wells

1. Type of Well
GAS

2. Name of Operator

**BURLINGTON
RESOURCES**

OIL & GAS COMPANY

3. Address & Phone No. of Operator

PO Box 4289, Farmington, NM 87499 (505) 326-9700

4. Location of Well, Footage, Sec., T, R, M

1200' FNL, 2390' FEL, Sec. 22, T-30-N, R-11-W, NMPM, San Juan County

API # (assigned by OCD)

30-045-29936

5. Lease Number

Fee

6. State Oil&Gas Lease #

7. Lease Name/Unit Name

Vasaly Com

8. Well No.

#2

9. Pool Name or Wildcat

WC:30N11W22B Morrison

10. Elevation:

Type of Submission

☐ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment

Type of Action

☐ Abandonment

☒ Recompletion

☐ Plugging Back

☐ Casing Repair

☐ Altering Casing

☐ Other -

☐ Change of Plans

☐ New Construction

☐ Non-Routine Fracturing

☐ Water Shut off

☐ Conversion to Injection

13. Describe Proposed or Completed Operations

8-10-01 MIRU. SDON.

8-13-01 ND WH. NU BOP. TIH w/6000' 2-3/8" tbg. SDON.

8-14-01 TIH w/2-3/8" tbg to 10,000'. Circ hole w/2% KCL wtr. TOOH w/2-3/8" tbg. Notified state of intent to sqz. Pump cmt from sqz holes @ 7150' up to Sqz holes @ 6684'. Placing cmt between 9-5/8" & 7" csg. Perf 2 sqz holes @ 7150'. Shoot sqz holes @ 6684'. Set 7" CICR @ 7100'. SDON.

8-15-01 Pump 26 bbls 50/50 Class H poz cmt. Displace w/5 bbls 2% KCL wtr. TOOH. TIH w/bit. SDON.

8-16-01 TIH, tag cmt @ 6110'. Drill out cmt to 6600'. SDON.

8-17-01 Drill out cmt to 6657', fell out of cmt. PT sqz hole @ 6684' to 1000 psi, bleed off. Verbal approval from Charlie Perrin, OCD, to sqz. TOOH. TIH w/7" CICR, set @ 6650'. Pump 120 sx Class H cmt w/2% calcium chloride. Displace to 6400'. Sting out of 7" CICR, dump 1 bbl cmt on top. SDON.

8-18-01 TOOH. TIH w/bit, tag up @ 6608'. Drill out cmt to 6650'. Drill out CICR @ 6650'. Drill out cmt @ 6650-6684'. PT sqz & csg to 1000 psi, OK. Drill out & clean out to PBTD. Circ hole clean. SDON.

8-19-01 TOOH w/bit. RU W/L. Ran CBL @ 7021-4000', TOC @ 6684'. RD W/L. TIH, tag up @ 7070'. Drill out to 7100'. Circ hole clean. SDON.

8-20-01 Spot acid. Blow well dry from 1500' to surface. TOOH w/bit. Perf Morrison @ 7018-28' w/40 holes. Brk dwn Morrison perfs. SDON.

8-21-01 Swab well back to clean up well. Flow back well.

8-22-01 Swab well back. SDON.

8-23-01 TIH w/CIBP, set @ 6985'. Dump 15 sx cmt on CIBP. ND BOP. NU WH. SDON.

8-24-01 RD. Rig released.

Morrison formation was plugged and abandoned on 8-24-01.

SIGNATURE

Peggy Case

Regulatory Administrator September 7, 2001

TLW

(This space for State Use)

Approved by

[Signature]

Title

Date

9-26-01