Form 3160-5 (August 1999)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.

PORM APPROVED OMB NO. 1004-0135 Expires: November 30, 2000

5. Lease Serial No.

K	(49IND8486	

0.	EASTERN NAVAJO	,

SUBMIT IN TRII	7. If Unit or CA/Agree NMNM78391C	ment, Name and/or No.						
1. Type of Well			Killy 10 11	7/3	8. Well Name and No. GALLEGOS CAN	VON 405		
Oil Well Gas Well Oth			D-			TON 195		
2. Name of Operator Contact:   BP AMERICA PRODUCTION CO		MARY CORLEY E-Mail: CORLEYML@BP.COM 2000			99. API Well No. 30-045-11592-00-S1			
3a. Address 200 ENERGY CT FARMINGTON, NM 87402		Ph: 281-36	(include area cod 5-4491 (	le)	310. Field and Pool, or Exploratory BASIN DAKOTA			
4. Location of Well (Footage, Sec., T	K.O.	(6.30)	11. County or Parish, a	and State				
Sec 33 T29N R12W SESW 0 36.67767 N Lat, 108.10486 W	790FSL 2310FWL / Lon		375	21	SAN JUAN COL	JNTY, NM		
12. CHECK APPI	ROPRIATE BOX(ES) TO	INDICATE	NATURE OF	NOTICE, RE	EPORT, OR OTHER	RDATA		
TYPE OF SUBMISSION TYPE OF				OF ACTION	ACTION			
☐ Notice of Intent	□ Acidize	□ Deep	en	□ Producti	ion (Start/Resume)	☐ Water Shut-Off		
<del>-</del> .	Alter Casing	□ Fract	ure Treat	□ Reclama	ation	☐ Well Integrity		
Subsequent Report     ■	☐ Casing Repair	□ New	Construction	Recomp	lete	Other Workover Operations		
☐ Final Abandonment Notice	☐ Change Plans	□ Plug	and Abandon	☐ Tempora	arily Abandon	Workover Operations		
	Convert to Injection	Plug	Back	□ Water D	isposal			
testing has been completed. Final Al determined that the site is ready for f BRADENHEAD REPAIR:  10/22/2004 MIRUSU. Check p w/production TBG. TIH w/CSC well. TIH w/RBP & set @ 578' & test to 1000#. Test ok. Chec 5541' Test down TBG to 1250#. Test down TBG to 1250#. Test down TBG to 1250#. Test Dump 10 MGAL sand on RBF PKR to 5253'. ND floor. ND B 0#. Blow down well. Pull PKR 80#, CSG 150#. Blow down w	oressure: BH 100#, CSG S scraper to PBTD. TOH. 1'. PU & set PKR @ 5761 ck pressure: BH 5#, CSG #. Test ok. Test down CSG to 1'. TOH. TIH & circ hole ck OP. Change out wellhead. Test to 1000#. Test ok. rell. Check pressure: BH	170#. Blow do Check pressu '. Test RBP to 0#. Blow dow G to 1050#. T 050#. Test ole ean. TOH. Ch I. NU BOP. NU	own well. NDV re: BH 100#, 1500#. Test n bradenhead est ok. PU & c. Test wellhe eck pressure: J floor. Check o RBP & TOH	VH. NU BOPs. CSG 170#. Bl ok. Reset PKF J. TIH & set Pk rest PKR to 52 ad to 1500#. L BH 90#, CSG pressure: BH	TOH ow down R @ 5253' KR @ 223'eaked. 0#. Reset 90#, CSG ure: BH			
14. Thereby certify that the foregoing is	strue and correct. Electronic Submission # For BP AMERICA	51065 verified PRODUCTIO	by the BLM W	ell Information	System			
	itted to AFMSS for process	sing by MATT	IEW HALBERT	on 12/13/2004	(05MXH0225SE)	•		
Name (Printed/Typed) MARY CC	DRLEY 		Title AUTH	IORIZED REP	RESENTATIVE			
Signature (Electronic S	Submission)		Date 11/18	/2004				
	THIS SPACE FO	R FEDERA	L OR STATI	E OFFICE US	SE			
Approved By ACCEPT	ED	· · · · · · · · · · · · · · · · · · ·		W HALBERT EUM ENGINE		Date 12/13/2004		
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.			Office Farmin		NMOCD			
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent	U.S.C. Section 1212, make it a	crime for any pe	rson knowingly	and willfully to m	ake to any department or	agency of the United		