Form 3160-5 (August 1999)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB NO. 1004-0135
Expires: November 30, 20

_	_					• •
Г	5	Lease	Serial	Nο		
		~~~	~~		•	
		HOA		A A		^

5. Lease Serial No. JICARILLA APACHE	5.	
JIOANILLA AFAONE		

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an
abandoned well. Use form 3160-3 (APD) for such proposals.

abandoned well. Use form 3160-3 (APD) for such proposals.				6. If Indian, Allottee or Tribe Name				
SUBMIT IN TRI	PLICATE - Other instructions of	on reverse side.	d. If Unit or CA/Agre	ement, Name and/or No.				
1. Type of Well		RECEI	VED 8. Well Name and No.					
Oil Well Gas Well Ot		070 FARMIL		9 				
<ol><li>Name of Operator BURLINGTON RESOURCES</li></ol>		Y JONES TJones3@br-inc.com	9. API Well No. 30-039-22042	•				
3a. Address PO BOX 4289 FARMINGTON, NM 87499-4	Ph: 5	one No. (include area code) 05.599.4068 05.599.4062		Exploratory CO PICTURED CLIFFS				
4. Location of Well (Footage, Sec., 7	., R., M., or Survey Description)	R ON TO	County or Parish,	and State				
Sec 36 T26N R5W NWSW 16	330FSL 880FWL		RIO ARRIBA C	OUNTY, NM				
12. CHECK APPI	ROPRIATE BOX(ES) TO INDIC	CATE NATURE OF 1	OTICE, REPORT, OR OTHE	R DATA				
TYPE OF SUBMISSION		TVEEO	ACTION					
_ >	☐ Acidize [	] Deepen	☐ Production (Start/Resume)	☐ Water Shut-Off				
□ Notice of Intent	☐ Alter Casing [	Fracture Treat	☐ Reclamation	☐ Well Integrity				
Subsequent Report	☐ Casing Repair [	New Construction	Recomplete	☐ Other				
☐ Final Abandonment Notice	☐ Change Plans	Plug and Abandon	☐ Temporarily Abandon	_				
	Convert to Injection	] Plug Back	☐ Water Disposal					
09/02/04 MIRU. SDFN. 09/03/04 ND WH, NU BOP. Run Wireline gauge ring to 3065'. TIH w/2-7/8" CIBP set @ 3065'. PU 1-1/4" work string, tag CIBP. Load casing w/18 bbls water. PT csg to 500 psi, leaking 1.5 bpm @ 500 psi. Plug #1: Spot 24 sx Type III cement (32 cf) inside the casing above the CIBP up to 2091' in two stages to cover the Pictured Cliffs perforations, Fruitland, Kirtland and Ojo Alamo tops. TOOH. with tubing and WOC. 09/07/04 TIH w/tbg, tag plug #1 @ 2040'. Attempt to pressure test casing, leak 1.5 bpm at 500#. TOOH. TIH, Perf 3 SPF @ 1465. TIH w/2-7/8" cmt retainer, set at 1415'. TOOH. Est rate 1.5 bpm @ 500 psi. Plug #2: mix and pump 40 sxs Type III cement (55 cf), squeeze 35 sxs outside the casing from 1465' to 1294' and leave 20 sxs inside casing to cover the Nacimiento top. TOOH. WOC. RIH with wireline and tag cement at 1220'. Perforate 2 sqz holes at 274'. Establish circulation out bradenhead with water. Plug #3: with 68 sxs Type III cement (90 cf) pumped down the 2-7/8" casing								
14. I hereby certify that the foregoing is	true and correct. Electronic Submission #36496 ve For BURLINGTON RESOURC			CEIVI BLM				
Name (Printed/Typed) FRANCES	BOND	Title REGUL	ATORY SPECIALIST	<u> </u>				
Signature (Electronic S	ubmission)	Date 09/27/20	Z	: 50				
	THIS SPACE FOR FED	ERAL OR STATE	OFFICE USE					
Approved By /s/ D	David R. Sitzler	Division Title	of Multi-Resources	JAN 3 2005				
Conditions of approval, if any, are attached certify that the applicant holds legal or equal which would entitle the applicant to conduct	itable title to those rights in the subject le							

** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED **

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

## Additional data for EC transaction #36496 that would not fit on the form

## 32. Additional remarks, continued

from 274' to surface, circulate good cement out bradenhead. Shut in well and WOC. Cut off well head. Found cement at surface in 2-7/8" casing and annulus. Install P& A marker with 15 sxs Type III cement. RD, Rig released.

Brice Hammond with JAT, was on location.

Weil Plugged and Abandoned 9/07/04