| Form 3160-5 (August 1999) DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals. | | | FORM APPROVED OMB No. 1004-0135 Expires November 30, 2000 5. Lease Serial No. SF- O 8 / 2 2 6 6. If Indian, Allottee or Tribe Name | | | |
|---|---|---|---|---|--|--|
| SUBMIT IN TRIPLICATE - Other instructions on reverse side 1. Type of Well | | | | 7. If Unit or CA/Agreement, Name and/or No. Horse shoe Gallup | | |
| 2. Name of Operator Volca | 8. Well Name and No. 257 HGU | | | | | |
| | | | e area code) | 9. API Well No. 3004509816 10. Field and Pool, or Exploratory Area | | |
| 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Sec. 3, T. 30 N., R. 16 W. | | | , | 11. County or Parish, State | | |
| 330/5 -10 | | | | San Juan NM | | |
| 12. CHECK A | 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA | | | | | |
| TYPE OF SUBMISSION | | TY | PE OF ACTION | | | |
| Notice of Intent Subsequent Report Final Abandonment Notice | Alter Casing Casing Repair | Deepen Fracture Treat New Construction Plug and Abandon Plug Back | Production (Start Reclamation Recomplete Temporarily Aba Water Disposal | Well Integrity Other | | |
| 13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizentally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) | | | | | | |
| See att | school plugging p | rocedure: | | · . | | |
| 14. I hereby certify that the foregoin | | ATTACHED FOI MS OF APPRO | R DVAL S | APR 2003 | | |
| Name (Printed/Typed) WMOCO | ontract Plugging | Title | | | | |
| Signature NMOCD | 7,1099,73 | Date | 4/21, | /03 | | |

Signature NM 0 C 0

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by Seed M Man Title Pt Date 4/23/03

Conditions of approval, if any, are attached. Approval of this notice does not warrant or

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office 1

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

WELL NAME 257 HGU SEC, TWN, RNG. 3-30N-16W -

Volume

- 5K - ft³

| Mesavarde | |
|--|---|
| Point Lookout Mancos 228' | 85/8" 24# 124' plus 278 - Surface |
| L P 8 | $278/7.443(1.14) = 31 \text{ sks}$ $154/5.7719(1.14) = 23 \text{ sks}$ $124/5.172 (1.14) = \frac{20}{74} \text{ sks}$ |
| | TOC -1105' TS |
| Gally /239 | |
| | Plug 1505'- 1189' |
| | P+ (+ @ 1504' - 1623' |
| 5.27.00 | 5/2" 15.5# 1667' INTERMEDIATE CAS |
| SURFACE CASING SIZE HOLE" SIZE CASING" | SIZE HOLE SIZE CASING Annulur Volume |
| Annilar Volume ft3/ft. | Cement |
| Volume C.3 | Volume |

API WELL # Well Name Well # Operator Name Type Stat County Surf_Owner UL Sec Twp N/S Rng W/E Feet NS Ft EW

Order_No 30-045-09816 HORSESHOE GALLUP UNIT 257 PLAYA MINERALS & ENERGY INC O A San Juan 1 3 30 N 16 W 330 S 1650 W

30-045-09816 CO 8 5/8 124 200S 5 1/2 1677 100S 2 3/8 1639 1504-1623

Procedure

MIRU, NUBOPE,

POOH Lay Down Rods & Tubing if present,

RIH with Gauge ring,

Pick up work string, Run Scrapper if required,

RIH Set CIBP 1505, cap with 316 cement.

Test casing.

POOH lay down tubing.

RU wire line RIH, perforate @ 278 '+ - 50' under surface casing shoe or Mesa Verde base whichever is lower..

Establish Circulation; circulate cement to surface inside and outside casing

Cut off well head and install P&A marker

Cut off anchors 2' below ground

Clean and level location

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON FIELD OFFICE

1235 LA PLATA HIGHWAY FARMINGTON, NEW MEXICO 87401

Attachment to notice of

Re: Permanent Abandonment

Intention to Abandon:

Well: 257 Horseshoe Gallup Unit

CONDITIONS OF APPROVAL

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."
- 2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 599-8907.
- 3. The following modifications to your plugging program are to be made:

Office Hours: 7:45 a.m. to 4:30 p.m.