Form 3160-5 (August 1999)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

/	FORM APPROVED
,	OMB No. 1004-0135
E	pires November 30, 200

SUNDRY	NOTICES AND	REPORTS	ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

5.	Lease Se	rial No.
	14-20	-603 - 734
6	If Indian	Allottes or Tribe Name

				Na	V4)'0	
SUBMIT IN TRIPLICATE - Other Instructions on reverse side				7. If Unit or CA/Agreement, Name and/or No.		
1. Type of Well				Horseshoe Gallup Unit		
Oil Well Gas Well				8. Well Na	ime and No.	
2. Name of Operator Vulcan	Minerals & Energy				HGU	
3a. Address 1000 Rto Bra Zos Rd. 3b. Phone No. (include area code)				9. API Well No. 30045 60050		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			10. Field and Pool, or Exploratory Area Hors & Shoe Gallup			
Sec. 29 T. 3IN. R 16 W.			11. County or Parish, State Say Juna NM			
660/N = 4					•	
12. CHECK AF	PPROPRIATE BOX(ES)	TO INDICATE NATUR	RE OF NOTICE, RE	PORT, OR	OTHER DATA	
TYPE OF SUBMISSION		TYI	PE OF ACTION	-	***	
Notice of Intent Subsequent Report Final Abandonment Notice	Acidize Alter Casing Casing Repair Change Plans Convert to Injection	Deepen Fracture Treat New Construction Plug and Abandon Plug Back	Production (Start/I Reclamation Recomplete Temporarily Abar	(Water Shut-Off Well Integrity Other	
13. Describe Proposed or Complete	d Operation (clearly state all pe	rtinent details including estim	Water Disposal	proposed wor	rk and approximate duration thereof.	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

See attached plugging Procedure:

CONDITIONS OF APPROVAL Adhere to previously issued stipulations.



14. I hereby certify that the foregoing is true and correct Name (Printed/Typed)	1				
NMOCO CONTract Plugging	Title				
Signature NMOCQ	Date		5/28/03)	
THIS SPACE FOR FED	ERAL OR	STATE	OFFICE USE		
Approved by Sugh m Man		Title	Pi	Date	MMAY 2 8-2003
Conditions of approval, if any, are attached. Approval of this notice does not certify that the applicant holds legal or equitable title to those rights in the su which would entitle the applicant to conduct operations thereon.	warrant or bject lease	Office	FFO		
Title 18 II S C Section 1001 and Title 42 II S C Section 1012					

API WELL # Well Name Well # Operator Name Type Stat County UL Sec Twp N/S Rng W/E Feet NS Ft EW Order_No 30-045-60050 HORSESHOE GALLUP UNIT 033 PLAYA MINERALS & ENERGY INC O A San Juan A 29 31 N 16 W 660 N 417 E

api_number status csg_1 csg_1q csg_1d csg_2 csg_2q csg_2d csg_3 csg_3q csg_3d liner_size liner_quan tubing t_set_dept csg_perf 30-045-60050 CO 8 5/8 100 115S 4 1/2 1365 130S 2 7/8 1325 1304-22

Procedure

MIRU, NUBOPE,

POOH Lay Down Rods & Tubing if present,

RIH with Gauge ring,

Pick up work string, Run Scrapper if required,

RIH Set CIBP 1205, cap with 300 cement.

Test casing.

POOH lay down tubing.

RU wire line RIH, perforate @ ____' + - 50' under surface casing shoe or Mesa Verde base whichever is lower..

Establish Circulation; circulate cement to surface inside and outside casing

Cut off well head and install P&A marker

Cut off anchors 2' below ground

Clean and level location

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON FIELD OFFICE

1235 LA PLATA HIGHWAY FARMINGTON, NEW MEXICO 87401

Attachment to notice of

Re: Permanent Abandonment

Intention to Abandon:

Well: 33 Horseshoe Gallup Unit

CONDITIONS OF APPROVAL

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."
- 2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 599-8907.
- 3. The following modifications to your plugging program are to be made:

Office Hours: 7:45 a.m. to 4:30 p.m.