

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side.

1. Type of Well <input type="checkbox"/> Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other		8. Well Name and No. AXI APACHE N 8
2. Name of Operator CONOCOPHILLIPS COMPANY		9. API Well No. 30-039-08134
3a. Address P.O. BOX 2197 WL3-6081 HOUSTON, TX 77252	3b. Phone No. (include area code) Ph: 832.486.2463	10. Field and Pool, or Exploratory BLANCO PC SOUTH
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Sec 2 T25N R4W SESE 1090FSL 890FEL		11. County or Parish, and State RIO ARRIBA COUNTY, NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION				
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off	
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity	
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other	
	<input type="checkbox"/> Change Plans	<input checked="" type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon		
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal		

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleate horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleation in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

This well was plugged and abandoned effective 1/20/2005. Daily summary is attached.



14. Thereby certify that the foregoing is true and correct. Electronic Submission #53576 verified by the BLM Well Information System For CONOCOPHILLIPS COMPANY, sent to the Rio Puerco Committed to AFMSS for processing by ANGIE MEDINA-JONES on 02/02/2005 ()	
Name (Printed/Typed) CHRIS GUSTARTIS	Title AUTHORIZED REPRESENTATIVE
Signature (Electronic Submission)	Date 01/31/2005

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved By _____	Title Division of Multi-Resources	FEB 4 2005 Date
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.		Office _____

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

**** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED ****

Daily Summary

API/UWI 300390813400	County RIO ARRIBA	State/Province NEW MEXICO	Surface Legal Location NMPM-25N-4W-2-P	N/S Dist. (ft) 1090.0	N/S Ref. S	E/W Dist. (ft) 890.0	E/W Ref. E
Ground Elevation (ft) 7272.00	Spud Date 08/09/1965	Rig Release Date 01/20/2005	Latitude (DMS) 36° 25' 26.652" N	Longitude (DMS) 107° 12' 55.08" W			

Start Date	Ops This Rot
01/17/2005 07:00	JSA ON SAFELY MOVING RIG. ROAD RIG TO LOCATION & SPOT. JSA ON SAFELY RIGGING UP W/ EMPHASIS ON MUDDY & ICY CONDITIONS. RIG UP RIG. CK WELL PRESSURES - TBG 50# - CSG 50# - BRADENHEAD 10#. RU BLOWDOWN LINE & PUMP TRUCK & BLOW WELL DOWN. PUMP 30 BBLs DOWN TBG TO KILL WELL. ND WELL HEAD & NU WEATHERFORD 7 5/8" X 7 1/16" COMPANION FLANGE. NU BOP & TEST. 250# LOW - 2250# HIGH. TEST OK. JSA ON SAFELY PULLING & LAYING DOWN TBG. RU FLOOR. X-OVER TO 1 1/4" TOOLS. PU ON TBG, LD TBG HANGER. LD 118 JTS 1 1/4" IJ TBG & 1 - 15' TAIL JT. JSA ON PU & RUNNING TBG. X-OVER TO 2 3/8" TOOLS. PU 4 1/2" CSG SCRAPER & PU, TALLY & RIH 119 JTS 2 3/8" TBG TO 3765'. JSA ON PULLING TBG. LD 1 JT, STAND BACK 59 STDS, LD CSG SCRAPER. SECURE WELL, DRAIN UP, SDFN.
01/18/2005 07:30	JSA ON THE DAY'S OPERATIONS W/ EMPHASIS ON MUDDY & ICY CONDITIONS. CK PRESSURES - CSG 30#, BH 10#. BLOW WELL DOWN. PU 4 1/2" DHS CMT RETAINER & TIH W/ 59 STDS & 1 JT & SET CR @ 3764'. DEPTH APPROVED BY JAT REP. PRESS TEST 2 3/8" TBG TO 1000#. TEST OK. STING OUT. LOAD & CIRC CSG W/ 60 BBLs. ATTEMPT TO PT. TEST FAILED - PUMPED 2 BBM @ 500#. PUMP PLUG #1 W/ 25 SX, 33.02 CU/FT, TYPE III CMT W/ 1% CACL2, MIXED @ 14.8 PPG. 3764' - 3445'. TOC 3395' W/ REQUIRED EXCESS. LD TBG TO 3410', PU 10' SUB, EOT @ 3420'. CIRC CSG CLEAN W/ 50 BBLs BH STARTED CIRC. STAND BACK 5 STDS. SIW, WOC PER JAT REP. TIH W/ 5 STDS, PU 1 JT & TAG TOC @ 3420'. LD 3 JTS, STAND BACK 53 STDS, LD STINGER. RU WIRELINE & PERFORATE @ 3415' W/ 3-3 1/8" HSC. PU 4 1/2" CMT RETAINER & TIH W/ 53 STDS, 1- 10' & 1- 8' SUB & SET CR @ 3363'. STING OUT & ATTEMPT TO PRESSURE TEST. TEST FAILED, BH STARTED CIRCULATING. STING BACK IN & ATTEMPT TO ESTABLISH RATE. PRESSURED TO 1000#. APPROVED BY JAT REP TO PUMP 20 SX ON TOP OF CMT RETAINER. PUMP PLUG #2 W/ 20 SX, 26.4 CU/FT, TYPE III CMT MIXED @ 14.8 PPG. 3363' - 3163'. TOC W/ REQUIRED EXCESS 3069'. LD TBG TO 1630'. SECURE WELL, DRAIN UP, SDFN.
01/19/2005 07:30	JSA ON THE DAY'S OPERATIONS W/ EMPHASIS ON MUDDY & ICY CONDITIONS. CK PRESSURES. ALL 0. POOH W/ 26 STDS, LD STINGER, PT CSG. TEST FAILED. RU WIRELINE & TAG TOC @ 3040'. PERFORATED @ 1680' W/ 3-3 1/8" HSC. RD WIRELINE. PU 4 1/2" DHS CMT RETAINER & TIH W/ 26 STDS TBG. SET CR @ 1630' & STING OUT. LOAD CSG & ATTEMPT TO PRESSURE TEST. TEST FAILED, CIRC OUT BH. STING IN & ATTEMPT TO ESTABLISH RATE. PRESSURED TO 1000# W/ 1/2 BBL. JAT REP APPROVED TO SET 20 SX PLUG ON TOP OF CR. PUMP PLUG #3 W/ 20 SX, 26.4 CU/FT, TYPE III CMT W/ 1% CACL2, MIXED @ 14.8 PPG. 1630' - 1336'. LD ALL TBG & STINGER, SIW, WOC. ATTEMPT TO PT CSG. TEST FAILED. BH CIRCULATED. RIH W/ WIRELINE & TAG TOC @ 1479'. PERFORATE @ 253 W/ 3-3 1/8" HSC. RD WIRELINE. PUMP PLUG #4, SURFACE PLUG, W/ 97 SX TYPE III CMT MIXED @ 14.8 PPG. 252' - SURFACE. CIRC GOOD CMT TO SURFACE. SI BH & PUMPED 8 - 10 MORE SX. SIW W/ 500#. WASH UP, DRAIN UP, DIG OUT WH, SECURE WELL. SDFN.
01/20/2005 07:30	JSA ON THE DAY'S OPERATIONS W/ EMPHASIS ON MUDDY & ICY CONDITIONS. OPEN WELL - 0#. TOC IN 4 1/2" DOWN 10'. ND BOP, WRITE HOT WORK PERMIT, CUT OFF WELLHEAD. CMT IN 4 1/2" X 8 5/8" DOWN 10'. TOP OFF & INSTALL DRY HOLE MARKER W/ 25 SX TYPE III CMT @ 14.8 PPG. RIG DOWN RIG. CUT OFF ANCHORS. CLEAN LOCATION. MOL. FINAL REPORT. WELL PLUGGED & ABANDONED.