## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Title 18 U S C. Section 1001, makes it a crime for any person knowingly and willfully to make any density the United States any false, fictitious or fraudulent statements or representations as to any matter within



MAY 03 2011

1 1 2011

**BUREAU OF LAND MANAGEMENT** Earnington Field Office Sureau of Land Managemen Sundry Notices and Reports on Wells Lease Number 5. SF-078885 Type of Well 6. If Indian, All. or 4567897077 TT- 155777 **GAS** Tribe Name **Unit Agreement Name** Name of Operator Canyon Largo Unit BURLINGTON RESCURCES OIL & GAS COMPANY LP Well Name & Number Address & Phone No. of Operator Canyon Largo Unit 292E PO Box 4289, Farmington, NM 87499 (505) 326-9700 API Well No. 30-039-30951 Location of Well, Footage, Sec., T, R, M 10. Field and Pool Surface: Unit J (NWSE), 1860' FSL & 1495' FEL, Section 10, T25N, R6W, NMPM Basin DK BHL: Unit I (NESE), 1705' FSL & 490 ' FEL, Section 10, T25N, R6W, NMPM 11. **County and State** Rio Arriba, NM 12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA Type of Submission Type of Action Notice of Intent Abandonment Change of Plans Other -Casing Report Recompletion New Construction Subsequent Report Plugging Non-Routine Fracturing Casing Repair Water Shut off Final Abandonment Altering Casing Conversion to Injection 13. Describe Proposed or Completed Operations 4/17/11 MIRU AWS 673. NU BOPE. PT csg to 600#/30 min. 4/18/11. Test – OK. 4/18/11 TIH w/ 8 3/4" bit. Tag & DO cmt. Drilled ahead to 4757' - Inter TD reached 4/20/11. Circ. Hole. TIH w/ 112 jts. 7", 23#, J-55, LT&C set @ 4749'. 4/22/11 RU cmt. Pre-flush w/ 10 bbls FW, 10 bbls GW, 10 bbls FW. Pumped scavenger 19 sx (57cf-10bbl-3.02 yld) Premium Lite w/ 3% CACL, .25 pps cello-flake, 5 pps LCM-1, 0.4% FL-52, 8% bentonite, and 0.4% sms. Lead w/ 531 sx (1,131 cf-201 bbls-2.13 yld) Premium Lite w/ 3% CACL, .25 pps cello-flake, 5 pps LCM-1, 0.4% FL-52, 8% bentonite, and 4% sms. Tail w/ 110 sx (152 cf-27bbls-1.38 yld) Type III w/ 1% CACL, .25 pps cello-flake, 0.2% FL-52. Dropped plug & displaced w/ 185 bbls FW. Bump plug. Circulated 65 bbls to surface. Plug down @ 19:20 hrs on 4/22/11. RD cmt. WOC. 4/22/11 RIH w/ 6 1/4" bit, tag cmt @ 4681' & DO. PT 7" csg to 1500#/30 min. @ 4:15 hrs on 4/22/11. Test-OK. 4/23/11 Drilled ahead to 7364' (TD) - TD reached 4/24/11. Circ hole & RIH w/ 172 jts. 4 1/2", 11.6#, L-80, LT&C set @ 7407'. RU cmt. Pre-flush w/ 20 bbls FW, 10 bbls GW, 10 bbls FW. Pumped scavenger 9 sx (27 cf-5 bbls-3.02 yld) Premium Lite w/ .25 pps cello-flake, 0.3% CD-32, 6.25 pps LCM-1, 1% FL-52. Tail w/ 178 sx (352 cf-63 bbls-1.98 yld) Premium Lite w/ .25 pps cello-flake, 9.3% CD-32, 6.25 pps LCM-1, 1% Fl-52. Dropped plug and displaced w/ 115 bbls FW, Plug down @ 19:00 hrs. on 4/28/11. RD cmt. ND BOPE. NU WH. RD. RR @ 00:45 hrs on 4/29/11. Revise depths 7364 < 7407 14. I hereby certify that the foregoing is true and correct. Signed Denise Journey Title:Regulatory Technician Date 5/2/2011 (This space for Federal or State Office use) ADDRETED FOR RECORD APPROVED BY CONDITION OF APPROVAL, if any: