RECEIVED

Form 3160-5 (April 2004)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

JUN 13 2011

FORM APPROVED OM B No 1004-0137 Expires March 31, 2007

SUNDRY NUTICES AND REPU	RTS ON WEDLISton Field	d Office, NM-052931	
Do not use this form for proposals to a abandoned well. Use Form 3160-3 (AP)	drill or to reachteram Ma	STAGE TO SHE Indian, Allottee or Tribe Name Navajo	
SUBMIT IN TRIPLICATE- Other instruc	tions on reverse side.	7 If Unit or CA/Agreement, Name and/or No	
Type of Well ☐ ☐ Gas Well ☐ ☐ Other			
		8 Well Name and No. Hanson #29	
Name of Operator BC&D Operating C/O Nacogdoches O&G Inc		9 API Well No	
a Address 38 816 North Street, Nacogdoches TX.	936-560-4747	30-031-20143 204 38 10 Field and Pool, or Exploratory Area	
Location of Well (Footage, Sec., T., R., M., or Survey Description)		Hospah	
1130' FWL & 400' FSL Section 6 T17N R8W		11 County or Parish, State	
		McKinley County, New Mexico	
12. CHECK APPROPRIATE BOX(ES) TO IN	DICATE NATURE OF NOTICE	E, REPORT, OR OTHER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION	TYPE OF ACTION	
☐ Notice of Intent ☐ Alter Casing ☐	Fracture Treat Reclamati		
Subsequent Report Casing Repair Change Plans	New Construction Recomple Plug and Abandon Temporari	te L_JOther	
Final Abandonment Notice Convert to Injection	Plug Back Water Dis		
5-13-2011- RIH with WS, tag bottom plug at 1233.97'. Lay d 6-02-2011-Mix and Pump 40 Sks @ 15.0 ppg down 7 7/8" an surface. Cut off well casing at 5', place P&A marker, clean location.		at 125'. Mix and pump 15 Sks at 15.0 ppg to level	
		STECEIVEL SOLUTIONS DIV.	
I hereby certify that the foregoing is true and correct		SECENTEL ON CONS. DIN. DIST. 3	
I hereby certify that the foregoing is true and correct Name (Printed/Typed) Mike Allen	Title VP Engineering	TEON SOLVET SOLV	
Name (Printed/Typed)	Title VP Engineering Date	06/10/2011	
Name (Printed/Typed) Mike Allen Signature		06/10/2011 ASSETT FOR FECOR	
Mike Allen Signature	Date	06/10/2011 OCESTICONS DIN. DIST. 3 CO. CONS. DIN. DIST. 3	