Form 3160-5

## UNITED STATES

FORM APPROVED	
OM B No. 1004-0137	
OM B No. 1004-0137 Expires: March 31, 20	ľ

(April 2004)	DEPARTMENT OF THE INTERIO BUREAU OF LAND MANAGEMEN	OR JUL 29 2011	OMB No. 1004-0137 Expires: March 31, 2007  5. Lease Scrial No.	
SUNDRY	NOTICES AND REPORTS is form for proposals to drill of ell. Use Form 3160-3 (APD) for	ONIWELLUSField Office Paratanad Manageme	NM-052931	
SUBMIT IN TRIPLICATE- Other instructions on reverse side.			7. If Unit or CA/Agreement, Name and/or No.	
1. Type of Well ✓ OilWell□ □	Gas Well□□ Other	8. Well Name and No.		
2. Name of Operator Nacogdoches	Oil & Gas Inc.		Hanson #15  9. API Well No.	
3a Address 816 North Street, Nacogdoches		No. (include area code) -4747	30-031-20143 10. Field and Pool, or Exploratory Area	
4. Location of Well (Footage, Sec.,	T., R., M., or Stavey Description)		Hospah	
720' FWL & 730' FSL Section 6 17N 8W			11. County or Parish, State  McKinley County, New Mexico	
12. CHECK A	PPROPRIATE BOX(ES) TO INDICATE	E NATURE OF NOTICE, R	EPORT, OR OTHER DATA	
TYPE OF SUBMISSION		TYPE OF ACTION		
Notice of Intent	Acidize Deepen Alter Casing Fracture	Production (Sta	rt/Resume) Water Shut-Off Well Integrity	
✓ Subsequent Report	Promise the second	astruction Recomplete	Other	
Final Abandonment Notice	Convert to Injection Plug Back	Abandon Temporarily Ab k Water Disposal	ападп	
Attach the Bond under which the following completion of the invitesting has been completed. Find determined that the site is ready 7-13-11- RIH with 2 3/8" V 7-14-11- RIH with WS to 1 7-15-11- RIH with WS to 1 WS, Mix and Pump 40 Sk	the work will be performed or provide the Bond Nolved operations. If the operation results in a musual Abandonment Notices shall be filed only after for final inspection.)  WS to 1539'. Mix and Pump 40 Sks, Portla ag bottom plug at 1294.96'. Redo bottom plug at 1294.96'. Redo bottom plug. Pull WS to 648' s @ 14.8 PPG, pump cement to top. SD.	to. on file with BLM/BIA. Require alltiple completion or recompletion in all requirements, including reclams and @ 14.8 PPG cover openhole olug. Mix and Pump 21 Sks @ for inside and outside plug. Mix 8 PPG. Cement to top. Cut off all the country of the country	14.8 PPG, Pull WS.  x and Pump 45 Sks @ 14.6 PPG. Pull 10 Jts,  casing, Place P&A Marker. Clean Locations  RECEIVED  2011	
14. Thereby certify that the foreg	oing is true and correct	1		
Mike Allen		Title VPE&P	Less The state of	
Signature		Date 07	/28/2011	
THIS SPACE FOR FEDERAL OR STATE OFFICE USE				
Approved by		Title	Date JUL 28 2011	
Conditions of approval, if any, are at certify that the applicant holds legal which would entitle the applicant to	tached. Approval of this notice does not warra: or equitable title to those rights in the subject le conduct operations thereon.	nt or ase Office	FARMSTON FIRED OFFICE	

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, first tious or fraudulent statements or representations as to any matter within its jurisdiction.



