

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Form C-141  
Revised October 10, 2003

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

30-645-09378

**OPERATOR**

Initial Report  Final Report

Name of Company	Williams Midstream	Contact	Aaron Dailey
Address	188 County Road 4900	Telephone No.	(505) 632-4708
Facility Name	Riddle 001 Well Site	Facility Type	Pipeline

Surface Owner	BLM	Mineral Owner	BLM	Lease No./ Meter	NMSF 080244
---------------	-----	---------------	-----	------------------	-------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	21	30 N	9 W					San Juan

GPS: N 36\*48' 1.908" W 107\*46' 57.648"

**NATURE OF RELEASE**

Type of Release	Fire-no injury	Volume of Release:	N/A	Volume Recovered:	N/A
Source of Release:	Field Dehydrator and 45 BBL Tank	Date and Hour of Occurrence	5.5.11 @ 06:00 hours (est)	Date and Hour of Discovery	5.5.11 @ 06:00 hours
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Brandon Powell, Aztec District office			
By Whom?	Aaron Dailey	Date and Hour 5.6.11 @ 16:00 hours			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken:

On Thursday 5/5/11 @ 6:00 am, the 45 bbl. Dehydrator pit/tank and dehy caught on fire on the Riddle-1 location. From Initial investigation it appears that flammable liquids in the tank ignited first and the heat and flames from that fire caused the dehy liquid level controller to also catch on fire. Investigation after the fire went out revealed that the 2" burner access plug had been removed and one of the liquid level cat-eyes had blow-out during the fire. The dehy's pump had been shut off and someone had inadvertently or maliciously removed the 2" burner access plug allowing flammable vapors from the liquid pit tank to find open access to the dehy's burners

Incident time log:

- 6:15 am--Smoke spotted west of Horse Canyon CDP by David Corbett.
- 6:19 am Corbett arrived at site of pit-tank fire. Riddle-1 BP well-site.
- 6:22 am Corbett notified 911 emergency operator of need for fire trucks. Also notified Tony DeHerrera and Nicole Reid.
- 6:23 am John Todd shut off BP compressor, wellhead valve and Williams downstream meter-run valve.
- 6:30 am One dehy cat-eye sightglass blew out, feeding natural gas on pit fire.
- 6:40 am Pit fire went out.
- 7:00 Corbett blew down the location piping.
- 7:15 am Center Point Fire Dept arrived-sprayed water on pit-tank to cool it.

Report and photos are attached to this C-141 report.

Describe Area Affected and Cleanup Action Taken:

Fire did not damage any vegetation. No impact to soil or groundwater. Photos attached to this report. In the photos, the area that appears dark in color is water as a result of the Center Point fire departments efforts in applying approximately 3 truck loads of water on the 45 BBL tank as a method of cooling the equipment.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.



Signature: *[Handwritten Signature]*  
Printed Name: Aaron Dailey

**OIL CONSERVATION DIVISION**  
Approved by District Supervisor: *[Handwritten Signature]* 5-12-11

nJK1122355963

Title: Environmental Specialist	Approval Date:	Expiration Date:
E-mail Address: aaron.dailey@williams.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 5.11.2011 Phone: (505) 632-4708		

\* Attach Additional Sheets If Necessary



PS INCIDENT NUMBER

# Property Damage / Loss Report / Near Miss Reporting

**Instructions:** Use this form to report non-vehicular Damage to / or loss of Property / Process / Profit or Near Miss Incidents. This form must be mailed within 24 hours after the incident to Risk Management (47-15). Do not forward Near Misses to risk management. **Notify risk management immediately of serious incidents or injuries: 1-800-324-3995.**

## Subsidiary Information

INSURED SUBSIDIARY	BUSINESS UNIT Midstream	DEPARTMENT GP&T	SITE CODE
ADDRESS 180 road 4980	CITY/STATE Bloomfield, NM	ZIP 87413	TELEPHONE No. (505) 632-4422
LOCAL MANAGER'S NAME Tony DeHerrera	LOCATION/AREA/DISTRICT Mesa View District		

## When and Where

LOCATION OF INCIDENT	ADDRESS Riddle-1- Well-Site	CITY/STATE Blanco, NM	OTHER DIRECTIONS
DATE (M/D/Y)	5/5/11	DAY OF WEEK	Thursday
TIME	6:15	<input checked="" type="checkbox"/> AM <input type="checkbox"/> PM	INVESTIGATED BY CIVIL AUTHORITIES? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
PERSON'S NAME	AGENCY NAME		

## Incident Information

THE INCIDENT: Based upon known, suspected, or hearsay information, describe in detail how you believe this incident occurred. Attach additional sheets and information, if necessary. 1. Check all that apply:  Damage  Loss  Near Miss

2. CHECK BOX FOR CAUSE OF DAMAGE, LOSS OR NEAR MISS REPORTING	<input checked="" type="checkbox"/> Fire	<input type="checkbox"/> Water	<input type="checkbox"/> Windstorm	<input type="checkbox"/> Explosion	<input type="checkbox"/> Collapse	<input type="checkbox"/> Unknown
	<input type="checkbox"/> Upset	<input type="checkbox"/> Lightning	<input checked="" type="checkbox"/> Flashback	<input type="checkbox"/> Chemical <input type="checkbox"/> does include or <input type="checkbox"/> does not include exposure	<input type="checkbox"/> Smoke	<input type="checkbox"/> Theft
	<input type="checkbox"/> Pressure	<input type="checkbox"/> Product Contamination	<input type="checkbox"/> Hail	<input checked="" type="checkbox"/> Vandalism	<input type="checkbox"/> Electrical	<input type="checkbox"/> Collision or Contact with
	<input type="checkbox"/> Power Outage	<input type="checkbox"/> Equip Safety Failure				
	<input type="checkbox"/> Overfill	<input type="checkbox"/> Product Outage				
	<input type="checkbox"/> Other cause as noted below					

DESCRIPTION OF INCIDENT On Thursday 5/5/11 @ 6.00 am, the 45 bbl. Dehydrator pit/tank and dehy caught on fire on the Riddle-1 location. From Initial investigation it appears that flammable liquids in the tank ignited first and the heat and flames from that fire caused the dehy liquid level controller to also catch on fire. Investigation after the fire went out revealed that the 2" burner access plug had been removed and one of the liquid level cat-eyes had blow-out during the fire. The dehy pump had been shut off and someone had inadvertently or maliciously removed the 2" burner access plug allowing flammable vapors from the liquid pit tank to find open access to the dehy burners

Incident time log:

6:15 am--Smoke spotted west of Horse Canyon CDP by David Corbett.  
6:19 am Corbett arrived at site of pit-tank fire. Riddle-1 BP well-site.  
6:22 am Corbett notified 911 emergency operator of need for fire trucks. Also notified Tony DeHerrera and Nicole Reid.  
6:23 am John Todd shut off BP compressor, wellhead valve and Williams downstream meter-run valve.  
6:30 am One dehy cat-eye sightglass blew out, feeding natural gas on pit fire.  
6:40 am Pit fire went out.  
7:00 Corbett blew down the location piping.  
7:15 am Center Point Fire Dept arrived-sprayed water on pit-tank to cool it.

EMPLOYEE INVOLVED	EMPLOYEE ID #	DEPARTMENT
ADDRESS	TELEPHONE NO. ( )	

## Damages and Repairs

Describe the apparent and suspected details concerning the type of damage and cost of repairs.

The 45 bbl open top steel pit was damaged by the heat and fire. The pit tank will cost \$2000.00 to replace. The dehy has minimal damage. The liquid level controller will need replaced. Cost \$600 00

REPAIR/REPLACEMENT COST ESTIMATE	<input checked="" type="checkbox"/> KNOWN AMT. \$2600.00 <input type="checkbox"/> UNDER \$1,000 <input checked="" type="checkbox"/> UNDER \$5,000 <input type="checkbox"/> UNDER \$10,000 <input type="checkbox"/> UNDER \$25,000 <input type="checkbox"/> OVER \$25,000
	IS PROPERTY INVOLVED OWNED OR LEASED? <input checked="" type="checkbox"/> Owned <input type="checkbox"/> Leased
IS DAMAGED ITEM TO BE <input type="checkbox"/> repaired or <input checked="" type="checkbox"/> replaced? IF SO, WHEN?	5/15/11
	IF ITEM IS LEASED, STATE OWNER

## Other Involved Persons, Companies or Products

Name other companies, products, or persons who are or may be responsible or somehow involved in this incident. State names, addresses, and details of involvement. Are there any written agreements or contracts between any of the parties?


## Witnesses


NAME	ADDRESS	TELEPHONE NO.
John Todd-(Devon Energy)		( ) 801-7434







		( )
--	--	-----

**Other Information or Remarks – Attach Additional Pages if Necessary**

REPORT DATE (M/D/YY) 5/5/11	NAME OF PERSON MAKING THIS REPORT David Corbett	TITLE Senior Op/Tech	SIGNATURE David S. Corbett
--------------------------------	--	-------------------------	-------------------------------







From (505) 632-4708  
 Aaron Dailey  
 Williams Environmental  
 188 County Road 4900

Origin ID FMNA




J11151102250225

Bloomfield, NM 87413

Ship Date 11MAY11  
 ActWgt 0.3 LB  
 CAD 100945005/INET3130

Delivery Address Bar Code



SHIP TO: (505) 334-6178

BILL SENDER


**Brandon Powell**  
 EMNRD-Oil Conservation Division  
 1000 RIO BRAZOS RD  
 ENVIRONMENTAL BUREAU  
 AZTEC, NM 87410

Ref #  
 Invoice #  
 PO #  
 Dept #

THU - 12 MAY PM  
 PRIORITY OVERNIGHT

TRK# 7947 4591 8232

0201



**9A FMNA**

**87410**  
 NM-US  
 ABQ



50DG1/1577/7EFB

**After printing this label**

- 1 Use the 'Print' button on this page to print your label to your laser or inkjet printer
- 2 Fold the printed page along the horizontal line
- 3 Place label in shipping pouch and affix it to your shipment so that the barcode portion of the label can be read and scanned

**Warning** Use only the printed original label for shipping. Using a photocopy of this label for shipping purposes is fraudulent and could result in additional billing charges, along with the cancellation of your FedEx account number.

Use of this system constitutes your agreement to the service conditions in the current FedEx Service Guide, available on fedex.com. FedEx will not be responsible for any claim in excess of \$100 per package, whether the result of loss, damage, delay, non-delivery, misdelivery, or misinformation, unless you declare a higher value, pay an additional charge, document your actual loss and file a timely claim. Limitations found in the current FedEx Service Guide apply. Your right to recover from FedEx for any loss, including intrinsic value of the package, loss of sales, income, interest, profit, attorney's fees, costs, and other forms of damage whether direct, incidental, consequential, or special is limited to the greater of \$100 or the authorized declared value. Recovery cannot exceed actual documented loss. Maximum for items of extraordinary value is \$500, e.g. jewelry, precious metals, negotiable instruments and other items listed in our Service Guide. Written claims must be filed within strict time limits, see current FedEx Service Guide.

From (505) 632-4708  
Aaron Dailey  
Williams Environmental  
188 County Road 4900

Origin ID FMNA



J11151102250225

Bloomfield, NM 87413

Ship Date 11MAY11  
Act/Wgt 0.3 LB  
CAD 100945005/INET3130

Delivery Address Bar Code



SHIP TO (505) 599-8900

BILL SENDER

**Mark Kelly** Release Notification  
Bureau of Land Management  
1235 LA PLATA HWY


Ref #  
Invoice #  
PO #  
Dept #

FARMINGTON, NM 87401

THU - 12 MAY AA  
STANDARD OVERNIGHT

TRK# 7970 8484 1599

0201



**9A FMNA**

87401  
NM-US  
ABQ



50DG1/1577/EFB

**After printing this label**

- 1 Use the 'Print' button on this page to print your label to your laser or inkjet printer
- 2 Fold the printed page along the horizontal line
- 3 Place label in shipping pouch and affix it to your shipment so that the barcode portion of the label can be read and scanned

**Warning** Use only the printed original label for shipping. Using a photocopy of this label for shipping purposes is fraudulent and could result in additional billing charges, along with the cancellation of your FedEx account number.

Use of this system constitutes your agreement to the service conditions in the current FedEx Service Guide, available on fedex.com. FedEx will not be responsible for any claim in excess of \$100 per package, whether the result of loss, damage, delay, non-delivery, misdelivery, or misinformation, unless you declare a higher value, pay an additional charge, document your actual loss and file a timely claim. Limitations found in the current FedEx Service Guide apply. Your right to recover from FedEx for any loss, including intrinsic value of the package, loss of sales, income interest, profit, attorney's fees, costs, and other forms of damage whether direct, incidental, consequential, or special is limited to the greater of \$100 or the authorized declared value. Recovery cannot exceed actual documented loss. Maximum for items of extraordinary value is \$500, e.g. jewelry, precious metals, negotiable instruments and other items listed in our Service Guide. Written claims must be filed within strict time limits, see current FedEx Service Guide.