

*District I
1625 N French Dr , Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr , Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company Burlington Resources, a Wholly Owned Subsidiary of ConocoPhillips Company	Contact Kelsi Harrington	
Address 3401 E. 30th St., Farmington, NM 87402	Telephone No. 505-599-3403	
Facility Name Allison Unit 8	Facility Type Gas Well API#3004511433	
Surface Owner Federal	Mineral Owner Federal	Lease No. SF-078459-B

LOCATION OF RELEASE

Unit Letter H	Section 15	Township 32N	Range 07W	Feet from the 1757'	North/South Line North	Feet from the 990'	East/West Line East	County San Juan
-------------------------	----------------------	------------------------	---------------------	-------------------------------	----------------------------------	------------------------------	-------------------------------	---------------------------

Latitude **36.98206° N** Longitude **-107.54872° W**

NATURE OF RELEASE

Type of Release – Natural Gas	Volume of Release – 144 MCF	Volume Recovered –
Source of Release. Wellhead	Date and Hour of Occurrence 6/17/2011 4:00 p.m.	Date and Hour of Discovery 6/20/2011 9:00 a.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour –	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully *

Describe Cause of Problem and Remedial Action Taken. * **The three step stairway to the wellhead lubricator was found out of position and leaning against the wellhead, which caused a fitting to break off of the casing transmitter. There were no signs of vandalism, no signs of vehicle accident, or livestock pushing this stairway over.**

Describe Area Affected and Cleanup Action Taken. * **The natural gas was released to the atmosphere. The fitting was replaced and the stairway was reset into the correct position.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature <i>Kelsi Harrington</i>	OIL CONSERVATION DIVISION	
Printed Name: Kelsi Harrington	Approved by District Supervisor <i>B. J. [Signature]</i>	
Title: Field Environmental Specialist	Approval Date: 7/2/11	Expiration Date:
E-mail Address: kelsi.g.harrington@conocophillips.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 6/30/2011 Phone: 505-599-3403	nJK1122341698	

* Attach Additional Sheets If Necessary

